


# Galvanometers

3

## D'Arsonval Galvanometer



### Deflecting torque

$$T_d = B i N A = G i$$

where,  $B$  = Flux density in air gap;  $\text{Wb/m}^2$

$i$  = Current through moving coil; A

$N$  = Number of turns in coil

$A = l d$  = Area of coil;  $\text{m}^2$

$l, d$  = Length of vertical and horizontal side (width) of coil respectively; m

$G$  = Displacement constant of galvanometer

### Controlling torque

$$T_c = K \theta_f$$

where,  $K$  = Spring constant of suspension;  $\text{Nm/rad}$

$\theta_f$  = Final steady deflection of moving coil; rad

### Final steady deflection

$$\theta_f = \left( \frac{NBA}{K} \right) i = \left( \frac{G}{K} \right) i$$

## Dynamic behaviour of Galvanometers

### Torques in Galvanometers

#### Inertia torque

$$T_i = J \frac{d^2 \theta}{dt^2}$$

where,  $J$  = moment of inertia of moving system about the axis of rotation;  $\text{kg-m}^2$ ,

$\theta$  = deflection at any time  $t$ ; rad.

#### Damping torque

$$T_D = D \frac{d\theta}{dt}$$

where,  $D$  = damping constant

#### Controlling torque

$$T_C = K \theta$$

where,  $K$  = control constant

#### Deflecting Torque

$$T_d = G i$$

#### Equation of motion

$$T_i + T_D + T_C = T_d$$

$$J \frac{d^2 \theta}{dt^2} + \frac{D d\theta}{dt} + K \theta = G i$$

### Note:

- If  $D^2 < 4 KJ$ , galvanometer is underdamped.
- If  $D^2 = 4 KJ$ , galvanometer is critically damped.
- If  $D^2 > 4 KJ$ , galvanometer is overdamped.

#### Total resistance of galvanometer circuit for critical damping

$$R = \frac{G^2}{2\sqrt{KJ}}$$

#### External series resistance required for critical damping

$$R_e = R - R_g = \frac{G^2}{2\sqrt{KJ}} - R_g$$

where,  $R_g$  = Resistance of galvanometer

## Sensitivity

- Current sensitivity

$$S_i = \frac{\theta_f}{i} = \frac{G}{K} \text{ rad/A}$$

$$S_i = \frac{d}{i \times 10^6} \text{ scale divisions}/\mu\text{A}$$

$$S_i = \frac{2000 \text{ G}}{K \times 10^6} \text{ mm}/\mu\text{A}$$

- Voltage sensitivity

$$S_v = \frac{d}{i R_g \times 10^6} \text{ scale division}/\mu\text{V}$$

- Megohm sensitivity

$$S_o = \frac{d}{i \times 10^{-6}} \text{ M}\Omega/\text{scale division}$$

**Remember:** .....

Sensitive galvanometer is one which produces a large deflection for a small current.

.....

