




Limit Gauge :-



limit gauge's are design on Taylor's principle



Plug



Ring



* limit gauge's are use to check whether hole & shaft are coming within the specified Tolerance or not.

* Plug Gauge's are ^{use} for hole and Ring Gauge's are use for shaft.

* These gauge's are design according to Taylor's principle which has two statement

- ① GO Gauge's are design at max. material limit Condⁿ
- ② NO GO Gauge's are design at min. material limit Condⁿ


① When GO plug Gauge's Goes inside Hole It means mean size of ~~GO~~ ~~hole~~ Hole is more then size of GO gauge.

* When No Go gauge doesn't go inside the hole, it means the size of hole is less than the size of No go gauge's.



* When Go Gauge's goes and No Go gauge does not go. it means the hole is in ~~core~~ correct tolerance.

* IF Go gauge's doesn't go inside the hole it means the hole is under size and when No Go gauge enters into the hole it means hole is over size

Snap Gauge's :- Go and No Go gauge's both on the single piece.




*



No. Go

dumple



wear allowance

2nd Statement of Taylor


Go gauges are used to check size as well as shape and has to be in full form and

No Go gauges are used to check one element at a time.

Since go gauge's are covering the entire working length of Hole and Shaft so there will be some wear on gauges so wear allowances are provided over the Go Gauge

$$\text{Gauge tolerance (G.T.)} = \frac{1}{10} (\text{work tolerance})$$

$$\text{wear allowance} = \frac{1}{10} (GT) = \frac{1}{100} (WT)$$



- ① Philosophy of workshop department is that we will not produce anything defective so tolerance on the gauge's will be towards the work tolerance. But it can be seen in the diagram by adopting these type of gauges some of good parts will be treated as bad part.

② Philosophy of inspection ~~dep~~ department is that already a lot of effort taken to produce the component so no good part must be rejected so Tolerance will be away from work Tolerance.

But by adopting these gauges it can be seen that some of the bad parts will be treated as good parts.

Since the inspection gauge are already accurate no wear allowance is provided on Go gauge's.

③ In iso type Gauge Go is taken from the workshop and No Go is taken from the inspection

In exam following point must be remember

① when the work tolerance is less than 0.1 do not provide wear allowance

② when the type of gauge not Given to you design ISO Gauge

③ Answer should be correct ~~should~~ up to 4 decimal place




④ in objective question when the size of gauge is being asked Give that size which include gauge tolerance.

Question25 H₈/f₈


ISO gauge

work tolerance < 0.1

So No wear allowance



Q.27




Plus G_0 $\begin{cases} \text{Max} = 24.9965 \\ \text{min} = 24.9850 \end{cases}$

$$\begin{array}{r} + \\ 24.985 \\ - 0.000 \end{array}$$

(28)

(d)



$$G_0 = 20.014$$

$$NO G_0 = 20.054$$

(29)

b wrong.


Gauge Material

Properties of Material

1. High hardness & high wear resistance.
2. Low coeff. of thermal expansion. ($\propto \downarrow$)
3. When you push No Go gauge it will also go inside the hole. So it is the feel by which operator is trying to check component by Go & No Go inspection. If the gauge's are bulky, this feel will not come.
4. Good machineability
5. Good corrosion resistance

material :- (i) En-24 (High C steel)
 (ii) Inver
 (iii) Elinver
 (iv) Glass

Slip Gauge:



Normal set (M45)

$$1.001 - 1.009 \rightarrow 9$$

$$1.01 - 1.09 \rightarrow 9$$

$$1.1 - 1.9 \rightarrow 9$$


$$1 - 9 \rightarrow 9$$

$$10 - 90 \rightarrow 9$$

45

eg 27.836 mm

$$\begin{array}{r} 27.836 \\ - 1.006 \text{ (1)} \\ \hline 26.83 \\ - 1.03 \text{ (2)} \\ \hline 25.8 \\ - 1.8 \text{ (3)} \\ \hline 24 \\ - 4 \text{ (4)} \\ \hline 20 \text{ (5)} \end{array}$$



Surface plate

5 Gauge's

Special set (M87)

$$1.001 - 1.009 \rightarrow 9$$

$$1.01 - 1.49 \rightarrow 49$$

$$0.5 - 9.5 \rightarrow 19$$

$$10 - 90 \rightarrow 9$$

$$\Rightarrow 1.005 \rightarrow 1$$

87

$$\begin{array}{r} \text{eg } 27.836 \\ - 1.006 \text{ (1)} \\ \hline 26.83 \\ - 1.33 \text{ (2)} \\ \hline 25.5 \\ - 5.5 \text{ (3)} \\ \hline 20 \text{ (4)} \end{array}$$

4 Gauge's

- * Slip gauges also cannot be made accurately so there will be some tolerance. Overall dimension build up is sink i.e. least accurate section, so lesser is the number of slip gauges use accurate will be the dimension.
- * There are webs and ribs one surface plate & plate remain in single plane over the time.