



ELECTRICAL M/C.


Any device capable of continuous Electro mechanical conversion is called electrical m/c.

TRANSFORMER



$$\lambda = N_1 \Phi$$

E_{ab}, V_{ab} means Voltage of 'a' w.r.t 'b'



LENZ LAW :- A/c to Lenz law the direction of induced emf is such that if it is allowed to cause a current (by short cking the coil) then current so produced has an affect that opposes the cause.

This means that the induced emf is given by $e = \pm \frac{d\lambda}{dt}$, where sign depends on Lenz law & which terminal is taken as +ve.

$$e_1 = e_{ab} = N_1 \frac{d\lambda}{dt}$$

$$= N_1 \frac{d}{dt} (\Phi_m \sin \omega t) = N_1 \Phi_m \omega \cos \omega t$$


$$= N_1 \Phi_m \omega \sin(\omega t + 90^\circ)$$

Apply KVL.

$$\sum V = 0 \Rightarrow -V_1 + e_1 = 0 \Rightarrow V_1 = e_1$$

$$\therefore \text{R.M.S } E_1 = \frac{N_1 \Phi_m \omega}{\sqrt{2}} \Rightarrow \boxed{E_1 = \sqrt{2} \pi f \Phi_m N_1}$$

Induced emf eqⁿ of Primary.



DOT CONVENTION:- If the currents enter or leave through the dots simultaneously then the fluxes are additive.

Only the first dot is assigned (self given) the remaining dots follow automatically depending upon sense of winding.

$$e_2 = e_{cd} = + \frac{d\lambda}{dt} = + N_2 \frac{d\phi}{dt} = N_2 \frac{d}{dt} (\Phi_m \sin \omega t)$$

$$\Rightarrow e_2 = N_2 \Phi_m \omega \cos \omega t = N_2 \Phi_m \omega \sin(\omega t + 90^\circ)$$

As applied to transformers therefore if the current entered through dot in primary wdg then it should leave through the dot from secondary wdg because lenz laws to be supported.

In other words the dots in a transformer have the same instantaneous polarity.




Fig:- Phasor diagram of ideal tr on no load.

□ IDEAL TRANSFORMER.

1. NO losses (means no wdg resistance & no core loss).
2. $\mu = \infty$ (means no exciting current & no leakage flux)

$$\phi = \frac{\text{MMF}}{\text{Reluctance}} = \frac{\text{MMF}}{l/\mu A} \Rightarrow \text{MMF} = \phi \times \frac{l}{\mu A} = 0 \text{ at } \mu = \infty$$

$$\Rightarrow N_1 I_0 = 0$$

$$\Rightarrow I_0 = 0 \text{ (} \because N_1 \neq 0 \text{)}$$

MMF Balance on-Load.

$$N_1 \vec{I}_1 - N_2 \vec{I}_2 = 0 \Rightarrow N_1 \vec{I}_1 = N_2 \vec{I}_2 \Rightarrow$$

$$\vec{I}_1 = \frac{N_2}{N_1} \vec{I}_2$$

$$\frac{\vec{E}_1}{\vec{E}_2} = \frac{N_1}{N_2} = \frac{\vec{V}_1}{\vec{V}_2} = a = \frac{\vec{I}_2}{\vec{I}_1} \quad \begin{matrix} \vec{I}_2 \xrightarrow{*} \text{conjugate} \\ \vec{I}_1 \xrightarrow{*} \text{conjugate} \end{matrix}$$

$$\vec{I}_1 = \frac{\vec{I}_2}{a} = \vec{I}_2'$$

turn/voltage ratio.

$$\Rightarrow \vec{V}_1 \vec{I}_1^* = \vec{V}_2 \vec{I}_2^* \quad \text{or} \quad \vec{E}_1 \vec{I}_1^* = \vec{E}_2 \vec{I}_2^*$$

$$\vec{S} = P + jQ = \vec{V} \vec{I}^* \quad \text{where } Q \text{ is (+)ve } \rightarrow \text{ for lagging VARs.}$$





Fig:- Phasor diagram of ideal transformer on lagg P.f. load



I_c = core loss component of exciting current.

I_0 = No load current of exciting current.

I_ϕ = Magnetizing component of exciting current.

Fig:- Ph. diagram of practical core tr. on lagg P.f. load
Hysteresis angle. (angle created by hysteresis loss)


$$I_c = I_0 \cos \phi_0$$

$$I_\phi = I_0 \sin \phi_0$$


Safe value of current \rightarrow 2 to 3% of load current.

□ MMF BALANCE OF PRACTICAL TR' ON LOAD.

$$N_1 \vec{I}_1 - N_2 \vec{I}_2 = N_1 \vec{I}_0 \Rightarrow \vec{I}_1 = \frac{\vec{I}_2}{a} + \vec{I}_0 = \vec{I}_2' + \vec{I}_0$$



Leakage flux depends upon load.



$$\vec{E}_2 = \vec{V}_2 + \vec{I}_2 R_2 + j \vec{I}_2 X_2$$


$$\Rightarrow \vec{E}_1 = a \vec{E}_2, \vec{I}_1 = \vec{I}_2 + \vec{I}_0 \quad \text{Where } \vec{I}_0 = \vec{I}_c + \vec{I}_\phi$$


$$\vec{V}_1 = \vec{E}_1 + \vec{I}_1 R_1 + j \vec{I}_1 X_1$$

18/05/14


□ COMPLETE PHASOR DIAGRAM FOR LAGGING PF LOAD.
(Step down mode $N_1 > N_2$).

$$\begin{aligned} \vec{Z}_1 &= R_1 + jX_1 \\ &= \sqrt{R_1^2 + X_1^2} \angle \tan^{-1} \frac{X_1}{R_1} \\ &= Z_1 \angle \theta_1 \end{aligned}$$





Leading pf load.



□ EQUIVALENT CKT OF 2-WDG TK. REFERRED TO PRIMARY

Representation of any device.

$$\vec{E}_2 = \vec{V}_2 + \vec{I}_2 R_2 + j \vec{I}_2 X_2$$

Multiplying by $a = \frac{N_1}{N_2}$.

$$a \vec{E}_2 = a \vec{V}_2 + a \vec{I}_2 R_2 + j \left(\frac{I_2 X_2}{a} \right) j a \vec{I}_2 X_2$$

$$\Rightarrow \vec{E}_2 = \vec{E}_1 = \vec{V}_2 + \left(\frac{I_2}{a}\right) a^2 R_2 + j \left(\frac{I_2}{a}\right) (a^2 X_2)$$

$$\Rightarrow \vec{E}_2 = \vec{E}_1 = \vec{V}_2 + \vec{I}_2' R_2' + j \vec{I}_2' X_2'$$




Fig:- Exact equivalent ckt of Tr.
T' equivalent.

* Magnetization of is primary phenomena.

Q. The parameters of equivalent ckt of a ϕ 150 kVA, 2400/240 V are $R_1 = 0.2 \Omega$, $X_1 = 0.45 \Omega$, $R_2 = 2 m\Omega$, $X_2 = 4.5 m\Omega$, $R_c = 10 k\Omega$, $X_m = 1.55 k\Omega$. Using the ckt referred to primary, determine the primary i/p voltag, i/p current and i/p power factor of Tr. operating at rated load with 0.8 lag p.f.

Ans:- $\frac{V_1}{V_2} = \frac{2400}{240}$

$$\Rightarrow I_1 = \frac{I_2 \times V_2}{V_1} = \frac{781.25 \times 240}{2400} = 78.125$$

$$150 = V_2 I_2 \cos \phi$$

$$I_2 = \frac{150 \times 1000}{240 \times 0.8}$$

$$= \frac{7812.5}{781.25 \Omega}$$

Take \vec{V}_2 as ref phasor.

$$\vec{V}_2 = a V_2 \angle 0^\circ = 10 \times 240 \angle 0^\circ = 2400 \angle 0^\circ \text{ volts.}$$

$$I_2' = \frac{\vec{I}_2}{a} \angle -\cos^{-1} 0.8 = \frac{(150 \times 10^3) / 240}{10} \angle -36.87^\circ \text{ A. } \quad \text{4}$$

$$= 62.5 \angle -36.87^\circ \text{ A}$$

$$\vec{E}_1 = 2400 \angle 0^\circ + 62.5 \angle -36.87^\circ \times \left[(10)^2 \cdot [2 + j4.5] \times 10^{-3} \right]$$

$$= 2426.92 \angle 0.35^\circ \text{ Volts}$$

$$\vec{I}_c = \frac{\vec{E}_1}{R_c} = \frac{0.2427 \angle 0.35^\circ \text{ A}}$$

$$\vec{I}_\phi = \frac{E_1}{jX_\phi} = 1.5658 \angle -89.65^\circ \text{ A}$$

$$\vec{I}_0 = \vec{I}_c + \vec{I}_\phi = 1.5845 \angle -80.84^\circ \text{ A}$$

$$\vec{I}_1 = \vec{I}_2 + \vec{I}_0 = 63.65 \angle -37.86^\circ \text{ A}$$



$$\vec{V}_1 = \vec{E}_1 + \vec{I}_1 \vec{Z}_1 = 2426.92 \angle 0.35^\circ + 63.65 \angle -37.86^\circ \times (0.2 + j0.45)$$


$$= 2454.68 \angle 0.69^\circ \text{ Volts}$$

$$\text{I/P pf} = \cos [0.69^\circ - (-37.86^\circ)] = \cos (38.55^\circ) \text{ lag}$$


$$= 0.7820 \text{ lag}$$

□ 1st equivalent approx equivalent ckt.







For lagging.



□ OPEN CIRCUIT TEST.

* To predict performance without actual loading.

Rated frequency
Variable Voltage
Ac Supply.
(eg for Auto tra.)



* a.c & s.c are carried out to predict the performance of transformer without actual loading.

OPEN CRT

1. open CRT test is carried out at rated frequency & rated voltage to determine core loss.

The core loss thus ~~calculated~~ determined is treated as constant despite minor variation in voltage & frequency during actual operation.

2. This test is carried with the instrument placed on the low voltage side with high voltage side left open circuited.

This is because ranging rated voltage supply at l.v level is easier than at h.v level. Also the instruments are economic & it is safer to work on the low voltage side.

$P_{oc}, I_o, V_{oc} \rightarrow$ Rated.


Method to calculate.

1. $R_c = \frac{(V_{oc})^2}{P_{oc}}$

$\left[\text{For //ckt} \rightarrow \tan \phi_o = \frac{R_c}{X_{\phi_o}} \right]$

2. $\phi_o = \cos^{-1} \left[\frac{P_o}{V_{oc} I_o} \right]$

3. $X_{\phi} = \frac{R_c}{\tan \phi_o}$



3. Since the no load current is limited to 5% of full load value the primary cu loss is treated negligible.

Also the voltage drop across primary impedance on no load is ignored.

4. ∵ the no load P.f is very low, it is recommended that low P.f wattmeter should be used.

Alternate method (Not use)

(a) 1. $R_c = \frac{(V_{oc})^2}{P_{o.c}}$ 2. $I_c = \frac{V_{o.c}}{R_c}$ 3. $I_\phi = \sqrt{(I_0)^2 - (I_c)^2}$ 4. $X_\phi = \frac{V_{o.c}}{I_\phi}$

(b) 1. $I_c = \frac{P_{o.c}}{V_{o.c}}$ 2. $I_\phi = \sqrt{(I_0)^2 - (I_c)^2}$ 3. $X_\phi = \frac{V_{o.c}}{I_\phi}$, $R_c = \frac{V_{o.c}}{I_c}$

(c) 1. $\phi_0 = \cos^{-1} \left[\frac{P_{o.c}}{V_{o.c} I_0} \right]$ 2. $I_c = I_0 \cos \phi_0$ & $I_\phi = I_0 \sin \phi_0$

3. $R_c = \frac{V_{o.c}}{I_c}$ & $X_\phi = \frac{V_{o.c}}{I_\phi}$

Question: with the instruments connected on h.v. side the open ckt readings for 10 KVA, 450V/120V, 50 Hz,

1- ϕ transformer are 120V, 4.2A & 80 watts. Find R & X

of // equivalent exciting ckt referred to h.v side.

Solⁿ: $R_c = \frac{(120)^2}{80} = 180 \Omega$

$\phi_0 = \cos^{-1} \left[\frac{80}{120 \times 4.2} \right] = 80.86^\circ$


$X_\phi = \frac{180}{\tan \phi_0} = \frac{180}{6.22} = 28.93 \Omega$

$a = \frac{V_{h.v}}{V_{l.v}}$
 $a = \frac{120}{50} = 2.4$
 $a = \frac{450}{120} = 3.75$

$$\therefore R_{e(HV)} = a^2 \times R_{e(LV)} = (3.75)^2 \times 180 = 2.53 \text{ K}\Omega$$


$$X_{\phi(HV)} = (3.75)^2 \times 28.93 = 406.82 \Omega$$

SHORT CIRCUIT TEST.



1. Short ckt test is carried out at rated current/ full load current to determine the full load cu loss.
2. This test carried out with the instrument placed on the H.V side while the L.V side is short ckted by thick conductor.

This is because the rated current on hv side is lower than on the lv side & therefore the instruments are economic in cost.



$$P_{sc} \rightarrow P_{cu}(pt)$$

$$I_{sc} \rightarrow I_{fl}$$

$$V_{sc} \rightarrow I_{sc} Z_{eq}$$

3. Since, the voltage required to circulate full load current is only 5% to 10% of the rated voltage, the core loss under short ckt test condⁿ is neglected. Also the exciting current at such low voltage is ignored.

4. Since wdg resistance of transformer is not affected ~~core~~ by frequency considerably, the test may be carried out at a frequency slightly different from rated frequency as well.

Method to calculate.

$$1. \vec{Z}_{eq} = \frac{V_{sc}}{I_{sc}} \angle \cos^{-1} \frac{P_{sc}}{V_{sc} I_{sc}} = R_{eq} + jX_{eq} \text{ Ans}$$

Alternate Method.

$$1. R_{eq} = \frac{P_{sc}}{(I_{sc})^2} \quad 2. Z_{eq} = \frac{V_{sc}}{I_{sc}} \quad 3. X_{eq} = \sqrt{(Z_{eq})^2 - (R_{eq})^2}$$

Q. With the instrument connected on hv side, the s.c test reading for 50 KVA, 2400/240 V tr. are 48V, 20.8 A and ~~600~~⁶¹⁷ watt. Find the leakage impedance, effective resistance & leakage reactance referred to low voltage side.

$$\text{Sol}^n: Z_{eq} = \frac{48}{20.8} \angle \cos^{-1} \frac{617}{48 \times 20.8} = \frac{48}{20.8} \angle 51.83$$

$$= 2.30 \angle 51.83 = 1.42 + j1.80. \quad 7$$

$$R_{eq(11V)} = \frac{R_{eq(hv)}}{a^2} = \left(\frac{V_{HV}}{V_{LV}} \right)^2 \times 1.42$$

$$= \frac{10000 \times 1.42}{100} = 1426 \text{ m}\Omega$$

$$X_{eq(11V)} = \frac{X_{eq(hv)}}{a^2} = \frac{10000 \times 1.80}{100} = 180 \text{ m}\Omega$$

$$= 18.14 \text{ m}\Omega$$

Q. A 2200/200V, 50Hz, 1- ϕ tr has exciting current of 0.6 A at a core loss 361 watt, when its H.V is energized at rated voltage. Calculate the two components of exciting current.

Q. If the transformer of part A supplies a load current of 60A at 0.8 P.f on its L.V side then calculate the primary current & its p.f. Ignore leakage impedance drop.

Solⁿ:- $R_c = \frac{V_o.c}{P_o.g} = \frac{2200}{361} = 6.09$


$$\phi_0 = \cos^{-1} \left[\frac{361}{2200 \times 0.6} \right] = 74.12$$

$$X_m = \frac{R_c}{\tan \phi_0} = \frac{6.09}{3.515} = 1.732$$

with Voltage as reference phasor

$$\vec{I}_0 = 0.6 \left[\cos^{-1} \frac{361}{2200 \times 0.6} \right]$$

$$= 0.1641 - j0.5771$$



$$\vec{I}_1 = \frac{I_2}{a} + \vec{I}_0 = \frac{60}{10} \angle -\cos^{-1}(0.8) + (0.1641 - j0.5771)$$

$$= 6.488 \angle -40.08^\circ \text{ A.}$$

PER UNIT VALUE

$$R_{(pu)} = \frac{R_{eq(\Omega)}}{V_{rated}/I_{rated}} = \frac{I_{rated} \times R_{eq(\Omega)}}{V_{rated}} = \text{Full load Resistive drop in p.u.}$$

Multiplying by I_{rated}

$$\Rightarrow \frac{(I_{rated})^2 \times R_{eq(\Omega)}}{V_{rated} \times I_{rated}} = \frac{(I_{rated})^2 \times R_{eq(\Omega)}}{S_{rated}} = \text{Full load cu loss in p.u.}$$

$$X_{(pu)} = \frac{X_{eq(\Omega)}}{V_{rated}/I_{rated}}$$

$$= \frac{(I_{rated})^2 \times X_{eq(\Omega)}}{V_{rated}} = \text{Full load Reactive drop in p.u.}$$

$$= \frac{(I_{rated})^2 \times X_{eq(pu)}}{S_{rated}} = \text{Full load Reactive Loss in p.u.}$$

$$Z_{pu} = \frac{Z_{eq(\Omega)}}{V_{rated}/I_{rated}}$$

$$= \frac{I_{rated} \times Z_{eq(\Omega)}}{V_{rated}} = \text{Full load Impedance drop in p.u.}$$

$$= \frac{(I_{rated})^2 \times Z_{eq(\Omega)}}{S_{rated}} = \text{Full load Apparent Power Loss in p.u.}$$

Approx value.

~~R → ≈ 0.01 pu~~

R → ≈ 0.01 pu.

X → ≈ 0.10 pu.


X_φ → ≈ 25 pu.

$$R_c \rightarrow \approx 100 \text{ pu} \rightarrow P_{\text{core}} = 0.01 = \frac{V^2}{R_c}$$

$$= \frac{(1)^2}{R_c} = R_c = \frac{1}{0.01}$$

$$\Rightarrow R_c = 100 \text{ pu.}$$

□ VOLTAGE REGULATION.



V.R of a transformer is defined the rise in ^{o/p. secondary.} Voltage expressed as a fraction of full load rated voltage when full load at a specified P.f. is reduced to zero keeping the primary i/p voltage constant.

$$\text{Voltage Regulation} = \frac{\text{No load Voltage} - \text{Full load Voltage}}{\text{Full Load Voltage}}$$

where Full Load Voltage = V_{rated}.

$$\vec{V}_{in} = \vec{V} + \vec{I} \vec{Z}_{e2}, \text{ Regulation} = \frac{V_{in} - V}{V} = \frac{V_{in}}{V} - 1$$

$$\text{Regulation} = V_{in(\text{pu})} - 1 \text{ pu.}$$

Ques:- A transformer has per unit impedance of 0.12 pu resistance of 0.01. calculate the phase difference b/w o/p voltage & i/p voltage at (a) 0.8 P.f lag (b) unity P.f (c) 0.8 P.f lead. and hence determine voltage regulation

Solⁿ :- $Z_{pu} = 0.1$, $R_{pu} = 0.01$.

(a) $\vec{V}_{in} = 1 \angle 0^\circ + 1 \angle -\cos^{-1}(0.8) Z_{eq}$

where, $Z_{eq} = 0.1 \angle \cos^{-1} \frac{0.01}{0.10}$

$\Rightarrow \vec{V}_{in} = 1 \angle 0^\circ + 1 \angle -\cos^{-1}(0.8) \times 0.1 \angle \cos^{-1} \frac{0.01}{0.10}$
 $= 1.0702 \angle 3.94^\circ$

Regulation = $V_{in(p.u)} - 1 = 1.0702 - 1 = 0.0702 = 7.02\%$

(b) $\vec{V}_{in} = 1 \angle 0^\circ + 1 \angle \cos^{-1}(0.8) \times 0.1 \angle 84.26^\circ$

$\Rightarrow \vec{V}_{in} = 1.0149 \angle 5.63^\circ \text{ pu}$

Regulation = $V_{in(p.u)} - 1 = 1.0149 - 1 = 0.0149 = 1.49\%$


(c) $\vec{V}_{in} = 1 \angle 0^\circ + 1 \angle \cos^{-1}(0.8) \times 0.1 \angle 84.26^\circ$

$= 0.9522 \angle 5.16^\circ \text{ pu}$

Reg = $0.9522 - 1 = -0.0478 \text{ pu} = -4.78\%$

□ APPROXIMATE REGULATION.

Lagging.



$$\text{Actual Regulation} = \frac{OB - OA}{OA} = \frac{OC - OA}{OA}$$

$\because \delta$ is very small.

$$V_o \cos \delta \approx V_{in} \quad \text{i.e. } OD \approx OC$$

$$\text{Thus Approx Reg} = \frac{OD - OA}{OA}$$

$$\therefore \text{Approx Reg}^n = \frac{AD}{OA} = \frac{AB \cos(\theta_{eq} - \phi)}{OA} = \frac{I Z_{eq} \cos(\theta_{eq} - \phi)}{V}$$

$$\boxed{\text{Approx Reg}^n = Z_{pu} \cos(\theta_{eq} - \phi)} \quad \checkmark$$

where ϕ is (+)ve for lagging pf.

$$\text{Approx Reg}^n = Z_{pu} \cos(\theta_{eq} - \phi)$$

$$= Z_{pu} [\cos \theta_{eq} \cdot \cos \phi + \sin \theta_{eq} \cdot \sin \phi]$$


$$= (Z_{pu} \cos \theta_{eq}) \cos \phi + (Z_{pu} \sin \theta_{eq}) \cdot \sin \phi$$

$$= \boxed{R_{pu} \cos \phi + X_{pu} \sin \phi} \quad \text{book.}$$

Maximum Regulation.

When $\phi = \theta_{eq}$ & then $\text{Max}^m \text{Reg}^n = Z_{pu}$.

Corresponding pf = $\cos \theta_{eq}$ lagging = $\frac{R_{pu}}{Z_{pu}}$ lagging.



No approximation involve because $\delta = 0^\circ$.

Zero Regulation.

Regulation is zero when

$$\theta_{eq} - \phi = 90^\circ \quad (\text{where } \phi \text{ is +ve for lag P.f.})$$


$$\Rightarrow \phi = \theta_{eq} - 90^\circ \quad (\text{ " " " " " " " })$$

$$= -(90^\circ - \theta_{eq}) \quad (\text{ " " " " " " " })$$

$$\boxed{\phi = (90^\circ - \theta_{eq}) \text{ leading}}$$

P.f. at Zero Regⁿ = $\cos(90^\circ - \theta_{eq})$ leading

$$= \sin \theta_{eq} \text{ leading} = \frac{X_{eq}}{Z_{eq}} \text{ leading}$$



$$\phi = 90^\circ - \theta_{eq} \text{ leading}$$

Zero Reg approx.

* Minimum Regulation is obtained when $\phi = 90^\circ$ leading.

$$\text{Then min}^m \text{ Reg} = Z_{pu} \cos(\theta_{eq} - (-90^\circ))$$

$$= Z_{pu} \cos(\theta_{eq} + 90^\circ) = -Z_{pu} \sin \theta_{eq}$$

$$= -X_{pu}$$





Fig: Phasor diagram at min^m Reg


□ REGULATION:

1. Regulation is a figure of merit of a transformer & its low value is desirable.
2. The per unit impedance must be brought down for reducing voltage regulation.
3. Z_{pu} can be reduced by reducing R_{pu} or X_{pu} .
4. The Resistance is already kept at an optimum value due to efficiency consideration. This leaves the leakage reactance to be reduced for reducing voltage regulation.





5. Leakage Reactance can be reduced by reducing leakage flux. Leakage flux can be reduced by keeping physically closed together. In core type transformer this physical proximity is obtained by concentric cylindrical way.

6. In shell type transformer it is obtained by sandwich wdg also called pancaked wdg / interleaved wdg.



gives better support against electromagnetic forces.

In core type transformer the leakage flux can also be reduced by increasing the window height to width ratio.



1. POWER AND DISTRIBUTION TRANSFORMER.

Power Transformer either operates on Full load or Switched off. Therefore voltage regulation is not a significant factor for a power transformer.

However a distribution tr. operates at varying load depends on demand of consumer & therefore $V.R$ is figure of Merit becomes very significant for a distribution tr. Accordingly the p.u. impedance of a distribution tr. may as low as 0.015 p.u.


* Whereas in a power tr. it may be as high as 0.15 p.u.

* A high value of P.u impedance in a power tr. has the advantage that it reduces the fault MVA level of the power system.

* As compared to L.V rating transformer the leakage reactance of h.v rating transformer is the thicker insulation makes the wdg further apart.

□ EFFICIENCY.

$$\eta = \frac{\text{O/P watts}}{\text{i/p watts}} \quad \text{or} \quad \frac{\text{O/P}}{\text{O/P} + \text{losses}} \quad \text{or} \quad \frac{\text{Input} - \text{Losses}}{\text{Input}} = \left(1 - \frac{\text{Losses}}{\text{I/P}}\right)$$



□ CONDITION FOR MAXIMUM EFFICIENCY

$$\eta = \frac{VI \cos \phi}{VI \cos \phi + I^2 R_{eq} + P_2}$$

* If the load P.f is variable & the load current is constant then max^m efficiency is obtained when the load P.f is unity.

* However if load P.f is constant and load current is variable then the condⁿ for max^m efficiency is obtained as follow

Dividing Num & Deno by 'I'

$$\eta = \frac{V \cos \phi}{V \cos \phi + I^2 R_{eq} + P_i} \Rightarrow \frac{V \cos \phi}{V \cos \phi + I R_{eq} + \frac{P_i}{I}}$$

Efficiency is max^m when denominator is minimum.

$$\text{i.e. } \frac{d}{dI} \left(V \cos \phi + I R_{eq} + \frac{P_i}{I} \right) = 0$$

$$\Rightarrow 0 + R_{eq} - \frac{P_i}{I^2} = 0$$

$$\Rightarrow \boxed{I^2 R_{eq} = P_i} \quad \therefore \quad \boxed{I_{\eta_{max}} = \sqrt{\frac{P_i}{R_{eq}}}}$$

$$P_{cu(max)} = P_i$$

multiplying by v we get-

$$V I_{\eta_{max}} = V \sqrt{\frac{P_i}{R_{eq}}}$$

$$V I_{\eta_{max}} = V I_j \times \sqrt{\frac{P_i}{(I_j)^2 R_{eq}}} \Rightarrow$$

$$\boxed{S_{\eta_{(max)}} = S_j \times \sqrt{\frac{P_i}{P_{cu(j)}}}}$$

j → means known load.

E.g. (A) when $S_j = S_{fl}$

(B) when $S_j = S_{(17\%)}$

$$S_{\eta_{(max)}} = S_{fl} \times \sqrt{\frac{P_i}{P_{cu(fl)}}}$$

$$S_{\eta_{(max)}} = S_{(17\%)} \times \sqrt{\frac{P_i}{P_{cu(17\%)}}}$$

$$\boxed{\eta_{max} = \frac{S_{\eta_{max}} \cos \phi}{S_{\eta_{max}} \cos \phi + 2 P_i}}$$

Alternate Approach for $S_{\eta_{max}}$

$$P_{cu} \propto S^2 \quad \therefore \frac{P_{cu}(\eta_{max})}{P_{cu(j)}} = \left[\frac{S_{\eta_{max}}}{S_j} \right]^2$$

$$\Rightarrow \sqrt{\frac{P_2}{P_{cu(j)}}} = \frac{S_{\eta_{max}}}{S_j}$$

□ EFFICIENCY CONSIDERATION IN POWER AND DISTRIBUTION TR.

* A power transformer operates on full load or switched off hence its max^m efficiency is designed on full load. Accordingly the designed iron loss = full load copper loss & it therefore high.

* The load on a distribution tr. depends upon the consumers demand (the avg. loading is 70-75% of its full load rating). Obviously therefore max^m efficiency of a distribution transformer is designed corresponding to 70-75% of full load & hence the iron loss has to be kept low at the time of design.


* Iron loss is reduced by reducing the flux density in the core. This requires an increase in cross sectional area of the core & consequently results into a higher iron to cu ratio as compared to a power tr. of the same capacity (KVA rating) & voltage rating.

Therefore the physical size of a distribution tr. is comparatively larger. However since the

distribution transformer is designed with low iron loss. Its operating efficiency is comparatively greater than that of power tr.

Que:- For a 200 kVA 4000/1000 V 1- ϕ transformer. Draw the equivalent ckt referred to L.V. side & insert all the value. It is given that the transformer efficiency at unity P.f is 97% both at Full load & at 60% of Full load. The no load P.f is 0.25 & the full load regulⁿ at a lagging P.f of 0.8 is 5%.

Solⁿ:-



On Full load.

$$0.97 = \frac{1 \times 1.0}{1 \times 1.0 + P_i + P_{cu(fl)}} \Rightarrow P_i + P_{cu(fl)} = 0.0309 \text{ --- (A)}$$

On 60% Load.

$$0.60 = \frac{0.6 \times 1.0}{0.6 \times 1.0 + P_i + (0.6)^2 P_{cu(fl)}} \Rightarrow P_i + 0.36 P_{cu(fl)} = 0.0186 \text{ --- (B)}$$

Solving a and b we get

$$P_i = 0.0117 \text{ pu}, P_{cu(fl)} = 0.0192 \text{ pu.}$$

$$\text{Regul}^n = 0.05 = R_{pu} \cos \phi + X_{pu} \sin \phi.$$

$$\Rightarrow 0.05 = 0.0192 \times 0.8 + X_{pu} \times 0.6$$

$$\Rightarrow X_{pu} = 0.0577 \text{ pu.}$$

$$\Rightarrow P_2 = \frac{V^2}{R_c} \Rightarrow 0.0117 = \frac{(1)^2}{R_c} \Rightarrow R_c = 85.47 \text{ pu.}$$

$$\Rightarrow \phi_0 = \cos^{-1}(0.25) = 75.52^\circ.$$

$$\therefore X_\phi = \frac{85.47}{\tan 75.52^\circ} = 22.07 \text{ pu}$$

$$Z_{\text{Base (L.V)}} = \frac{(\text{Rated } V)^2}{\text{Rated } S_{\text{rated}}} = \frac{(1000)^2}{200 \times 10^3} = 5 \Omega.$$

Actual Value = P.u. value \times Base Value

Que:- The max^m efficiency of a 500 KVA 3300/500 V, 50 Hz 1- ϕ transformer is 97% and occurs 75% full load with P.f. 0.8. Calculate the regulation at full load at 0.8 P.f. lagging.

$$\text{Sol}^n :- 0.97 = \frac{0.75 \times 1.0}{0.75 \times 1.0 + P_2 + P_{cu(f)} \times (0.75)^2}$$

$$\Rightarrow 0.97 (0.75 + P_2 + P_{cu(f)}) = 0.75$$

$$\Rightarrow P_2 + P_{cu(f)} = 0.02319$$

\therefore Max^m efficiency.

$$\Rightarrow 0.97 = \frac{0.75 \times 1.0}{0.75 \times 1.0 + 2P_2} \Rightarrow P_2 = 0.0116 \text{ pu}$$

$$\Rightarrow 0.0116 = (0.75)^2 \times P_{cu(f)} \Rightarrow P_{cu(f)} = 0.0206 \text{ pu.}$$

$$\Sigma_{\text{pu}} = 0.10 \left/ \frac{\cos^{-1} \frac{0.0206}{0.10}}{0.10} \right. = 0.10 \left/ 78.11^\circ \right. \text{ pu.}$$

$$\Rightarrow \phi = \cos^{-1}(0.8)$$

$$\text{Regulation} = Z_{pu} \cos(\theta_{eq} - \phi)$$

$$= 0.10 \cos[78.11^\circ - \cos^{-1}(0.8)] = 0.0752 \text{ pu} = 7.52\%$$

$P_e \propto f^2 B_m^2$ $\propto (f B_m)^2$ $\propto V^2$ $P_e = \text{constant}$	$P_h \propto f B_m^2$ $\propto f \left(\frac{V}{f}\right)^2$ $\propto \frac{V^2}{f^{(n-1)}} \Rightarrow P_h \propto \frac{1}{f^{(n-1)}}$
--	--

$$V = \sqrt{2} \pi f (B_m \times AC)$$

$$V \propto f B_m$$

□ ALL DAY EFFICIENCY / ENERGY EFFICIENCY.

$$\eta_{\text{all day}} = \frac{\text{Output Kwh in 24 hrs}}{\text{Input Kwh in 24 hrs}}$$

$$= \frac{\text{Output Kwh in 24 hrs}}{\text{O/p Kwh in 24 hrs} + P_{cu} \text{ in 24 hrs} + P_i \text{ in 24 hrs}}$$

$$= \frac{\text{Output Kwh in 24 hrs}}{\text{O/p Kwh in 24 hrs} + P_{cu} \text{ in 24 hrs} + \underbrace{P_i \text{ in 24 hrs}}_{\substack{\text{Constant} \\ P_i (\text{kw}) \times 24}}}$$

Que:- A 500 KVA transformer has a max^m η of 98.6% at 350 KVA unity P.f. during the day it is loaded as follow
 In the 1st 6 hrs the loading is 300 KVA, 0.8 p.f lag.
 during next 4 hrs: the loading is 240 KW, 0.6 p.f lead
 and after that 5 hrs. No load. and next 9 hrs: 225 KVA unity P.f. calculate all day η .

$$\text{Ans:} \Rightarrow 0.986 = \frac{350 \times 1.0}{350 \times 1.0 + 2P_i} \Rightarrow P_i = 2.4848 \text{ kw}$$

$$\text{And also } P_{cu(350)} = 2.4848$$

6 hrs

$$\text{O/p Kwh} = (300 \times 0.8) \times 6 = 1440 \text{ Kwh}$$

$$P_{cu(kwh)} = \left[2.4848 \times \left(\frac{300}{350} \right)^2 \right] \times 6$$

$$P_{cu} \propto I^2$$

$$P_{cu(kwh)} = 10.953 \text{ kWh}$$

4 hrs

$$O/p \text{ kWh} = 240 \times 4 = 960 \text{ kWh}$$

$$P_{cu(kwh)} = 2.4848 \times \left(\frac{240/0.6}{350} \right)^2 \times 4 =$$

$$P_{cu(kwh)} = 12.982 \text{ kWh}$$

5 hrs

$$O/p \text{ kWh} = 0$$

$$P_{cu(kwh)} = 0$$

9 hrs

$$O/p \text{ kWh} = (225 \times 1.0) \times 9 = 2025 \text{ kWh}$$

$$P_{cu(kwh)} = 2.4848 \times \left(\frac{225}{350} \right)^2 \times 9 =$$

$$P_{cu(kwh)} = 9.242 \text{ kWh}$$

Total of 24 hrs


$$O/p \text{ kWh} = 4425 \text{ kWh}$$

$$P_{cu(kwh)} = 33.177 \text{ kWh}$$

$$P_i(kwh) = 2.4848 \times 24 = 59.6352 \text{ kWh}$$

$$\eta_{\text{all day}} = \frac{4425}{4425 + 33.177 + 59.6352} = 0.9795 \text{ pu} = 97.95\%$$

□ AUTO TRANSFORMER.



AC \rightarrow N_H
 BC \rightarrow N_L
 AB \rightarrow $N_H - N_L$

\because Flux is constant
 $\frac{V_H}{N_H} = \frac{V_L}{N_L}$
 $\Rightarrow \frac{V_H}{V_L} = \frac{N_H}{N_L} = a_{(auto)}$

$$a_{(auto)} = \frac{I_L}{I_H} = \frac{V_H}{V_L} = \frac{N_H}{N_L}$$


Neglecting exciting current

$$\Rightarrow (N_H - N_L) I_H = N_L (I_L - I_H)$$

$$\Rightarrow N_H I_H - N_L I_H = N_L I_L - N_L I_H \Rightarrow N_H I_H = N_L I_L$$

$$\Rightarrow \boxed{\frac{N_H}{N_L} = \frac{I_L}{I_H}} \Rightarrow V_H I_H = V_L I_L \Rightarrow \boxed{S_H = S_L}$$

□ 2 WDG TRANSFORMER FOR SAME DUTY.



Copper conversion.

Copper weight = Copper volume \times Copper density
 \propto Volume
 \propto conductor c/s area \times conductor length
 \downarrow \downarrow
 $\propto I$ $\propto N$
 $\propto NI$ i.e. MMF

$$\frac{Cu_{(auto)}}{Cu_{(2-wdg)}} = \frac{(N_H - N_L) I_H + N_L (I_L - I_H)}{N_H I_H + N_L I_L}$$

$$= \frac{N_H I_H - N_L I_H + N_L I_L - N_L I_H}{N_H I_H + N_L I_L} = \frac{2 N_H I_H}{N_H I_H + N_L I_L}$$

$$= \frac{2 N_H I_H - 2 N_L I_H}{2 N_H I_H} = \frac{N_H I_H - N_L I_H}{N_H I_H} = \frac{N_H - N_L}{N_H}$$

$$= 1 - \frac{N_L}{N_H} = 1 - \frac{1}{a_{(auto)}}$$

$$\Rightarrow C_{u(autos)} = \left[\frac{a_{(auto)} - 1}{a_{(auto)}} \right] \times C_{u(2wdg)}$$

Copper saving

$$\Rightarrow \text{Copper saving} = \frac{C_{u(2wdg)} - C_{u(autos)}}{C_{u(2wdg)}}$$

$$= 1 - \frac{C_{u(autos)}}{C_{u(2wdg)}} = 1 - \left[1 - \frac{1}{a_{(auto)}} \right]$$

$$\% \text{ Cu saving} = \frac{1}{a_{(auto)}} \times 100 \%$$

□ COMPONENTS OF POWER TRANSFORMER.

$$S_L = V_L I_L$$

$$= V_L [(I_L - I_H) + I_H] = \underbrace{V_L (I_L - I_H)}_{\text{Inductive transfer}} + \underbrace{V_L I_H}_{\text{conductive transfer}}$$

$$S_{bc} = V_L (I_L - I_H)$$

$$= V_L I_L - V_L I_H = V_H I_H - V_L I_H = (V_H - V_L) I_H$$


$$= S_{AB}$$

Ratio of power transformer

$$\frac{S_{cond})}{S_{Total}} = \frac{V_L I_H}{V_L I_L} = \frac{1}{a_{(auto)}} = \text{Cu saving}$$

$$\frac{S_{\text{inductive}}}{S_{\text{Total}}} = 1 - \frac{1}{a_{\text{auto}}}$$

□ 2-WDG TRANSFORMER USING MATERIAL OF AUTO TRANSFORMER



□ KVA ADVANTAGE OF AUTO-TRANSFORMER.

$$\begin{aligned} \frac{S_{\text{auto}}}{S_{\text{(2wdg)}}} &= \frac{V_L I_L}{V_L (I_L - I_H)} \quad \text{or} \quad \frac{V_H I_H}{(V_H - V_L) I_H} \\ &= \frac{I_L}{(I_L - I_H)} \quad \text{or} \quad \frac{V_H}{(V_H - V_L)} \\ &= \frac{I_L / I_H}{(I_L / I_H - 1)} \quad \text{or} \quad \frac{V_H / V_L}{(V_H / V_L - 1)} \end{aligned}$$


$$\frac{S_{\text{auto}}}{S_{\text{(2wdg)}}} = \frac{a_{\text{auto}}}{a_{\text{auto}} - 1} \Rightarrow S_{\text{auto}} = \frac{a_{\text{auto}}}{a_{\text{auto}} - 1} \times S_{\text{(2wdg)}}$$

Question. A 25 KVA 2500 volts / 250 volts 2-wdg tr. is to be reconnected as auto transformer. Determine the KVA rating and voltage ratio of the auto tr. for all possible connection.


Solⁿ :-

25 KVA, 2500 / 250
 ↓ ↓
 10A 100A

Connection (a)



(i) Additive Connection (Best option)




$$a_{(auto)} = \frac{2750}{2500} = 1.1$$

$$S_{(auto)} = 2500 \times 110 \text{ or } 2750 \times 100$$

$$= 275000 \text{ or } 275000$$

$$= 275 \text{ KVA or } 275 \text{ KVA}$$




$$S_{(auto)} = 250 \times 110 \text{ or } 2750 \times 10$$

$$= 27.5 \text{ KVA or } 27.5 \text{ KVA}$$

(Bad option)

(ii) Subtractive connection.




$$a_{(auto)} = \frac{2500}{2250} = \frac{10}{9} = 1.11$$

$$S_{(auto)} = 2500 \times 90 \text{ or } 2250 \times 100$$

$$= 225 \text{ KVA}$$

(Better option)



$$a_{(auto)} = \frac{2250}{250} = 9$$

$$S_{(auto)} = 250 \times 90 \text{ or } 2250 \times 10$$

$$= 22.5 \text{ KVA.}$$

□ AUTOTRANSFORMER

* It is a tr. in which a part of wdg is common to Primary & secondary ckt both.

* Unlike a two wdg tr. where power transfer is only due to inductive transfer, the power transfer in an auto transformer is due to inductive transfer as well as conductive transfer.

* As compared to 2-wdg transformer for the same duty an auto tr. uses less copper & less iron. It

* Its exciting current is also lower & it has higher efficiency & lower p.u. impedance resulting in lower Voltage Regulⁿ.

* However a low value of p.u. impedance increases the Sh. ckt current.

* The max^m advantage of an auto transformer when it is used in application where voltage ratio is close to 1. Consequently auto tr. are normally used with the voltage ratio is limited to 2:1

- * However for special requirement it can be used with a voltage ratio upto 3:1.
- * The cu saving in an auto transformer is in the same ratio as the ratio of conductive transfer to total transfer.
- * If a 2-wdg transformer has to be reconnected as auto transformer then its i.v. wdg insulation should be strengthened in order to with stand the high voltage expected during operation as auto transformer.

$$S_{\text{auto}} = (a_{(2\text{wdg})} \pm 1) \times S_{(2\text{wdg})}$$


$$S_{\text{auto}} = \left(1 \pm \frac{1}{a_{(2\text{wdg})}} \right) \times S_{(2\text{wdg})}$$

USES OF AUTO TRANSFORMER.

Auto transformers are used in following areas.

- To interconnect 2-power system with different voltage level where the voltage ratio is limited to 3.
- As boost up for line drop compensation in electric traction supply system.
- To start 3- ϕ induction motor usually squirrel cage type.
- In manual auto servo voltage stabilizer for domestic commercial & industrial application.
- As continuously variable transformer in laboratory application.

□ TERTIARY WINDING



∴ Flux is constant.

$$\frac{V_1}{N_1} = \frac{V_2}{N_2} = \frac{V_3}{N_3} \Rightarrow N_1 \vec{I}_1 - N_2 \vec{I}_2 - N_3 \vec{I}_3 = N_1 \vec{I}_0$$

$$\Rightarrow \vec{I}_1 = \frac{N_2}{N_1} \times \vec{I}_2 + \frac{N_3}{N_1} \times \vec{I}_3 + \vec{I}_0 \quad \text{Exciting current}$$

Taking conjugate

$$\Rightarrow \vec{I}_1^* = \frac{N_2}{N_1} \times \vec{I}_2^* + \frac{N_3}{N_1} \vec{I}_3^* + \vec{I}_0^*$$

⇒ multiplying by V_1

$$\Rightarrow \vec{V}_1 \vec{I}_1^* = \left(\frac{N_2}{N_1} \times \vec{V}_1 \right) \vec{I}_2^* + \left(\frac{N_3}{N_1} \times \vec{V}_1 \right) \vec{I}_3^* + \vec{V}_1 \vec{I}_0^*$$

$$\Rightarrow \vec{V}_1 \vec{I}_1^* = \vec{V}_2 \vec{I}_2^* + \vec{V}_3 \vec{I}_3^* + \vec{V}_1 \vec{I}_0^*$$

$$\Rightarrow \boxed{S_1 = S_2 + S_3 + S_0}$$

Ques: The ratio of ~~turn~~ no. of turn/phase, primary, secondary & tertiary is 10:2:1 with lagging current of 45A at 0.8 P.f. in the secondary 50A P.f 0.71 in the tertiary wdg. Find primary current & P.f. Neglect losses & exciting current.


Solⁿ: Taking voltage as reference phasor.

$$\Rightarrow I_1 = \frac{2}{10} \times 45 \angle -\cos^{-1}(0.8) + \frac{1}{10} \times 50 \angle -\cos^{-1}(0.71)$$

$$= 13.97 \angle -39.69^\circ \text{ A}$$

$$\therefore \text{1/p P.f} = \cos 39.69^\circ \text{ lagging} = 0.7695 \text{ lagg.}$$

Ques:



An ideal transformer has 3-wdg 100 turns ^{on} primary wdg P, 160 turn on Secor. wdg S & 60 turn on tertiary wdg T. Winding S feeds 10 A to a resistive load whereas a pure capacitance load across wdg T takes 20 A.

Part (a) :- calculate the current in primary wdg & P.f in case transformer magnetizing current is neglected.

art (b) :- with polarity marking as shown, with the polarity on wdg S & T also. Taking voltage as reference phase.

$$\underline{\text{Sol}^n} :- \vec{I}_1 = \frac{160}{100} \times 10 \angle 0^\circ + \frac{60}{100} \times 20 \angle 90^\circ$$
$$= 20 \angle 36.87^\circ \text{ A}$$

$$\text{i/p P.f} = \cos 36.87^\circ \text{ leading} = 0.8 \text{ leading}$$

□ TERTIARY WINDING.

* Tertiary wdg is the additional or third wdg is a Δ m. i.e. provided in addⁿ to usual primary & secondary wdg for special requirements.

* It is used to provide a 3rd voltage level in unit auxiliary transformers in the generating station.

* To connect reactive power compensating equipment in substation.

* To provide power for lighting and pumping purposes in substation.

* For Bulk power application a 3-wdg transformer is used to interconnect 3-power system at different voltage level.

* In star-star transformer if tertiary Δ wdg is used to overcome relating to harmonics, unbalance & flow of zero sequence current. Such a wdg if unloaded is called stabilizing wdg.

□ 3- ϕ TRANSFORMER.

$$V = V_m \sin \omega t$$

$$-i = I_m \sin(\omega t - \phi)$$

$$P_{(1-\phi)} = Vi = V_m \sin \omega t I_m \sin(\omega t - \phi)$$

$$= \frac{V_m I_m}{2} \times 2 \sin \omega t \sin(\omega t - \phi)$$

$$\Rightarrow P_{(1-\phi)} = \frac{V_m}{\sqrt{2}} \times \frac{I_m}{\sqrt{2}} \left[\cos(\omega t - \omega t + \phi) - \cos(\omega t + \omega t - \phi) \right]$$

$$= VI \left[\cos \phi - \cos(2\omega t - \phi) \right]$$


$$= VI \cos \phi - VI \cos(2\omega t - \phi)$$

↓
Double frequency in 1- ϕ

In 2- ϕ resultant is $\sqrt{2}$ times.

\therefore - we use 3- ϕ where no double frequency & resultant is also balanced.


□ POLARITY TEST.



Suppose $V' > V$.

Additive polarity.

↓
Not use is high kVA times.



$V' < V$
Subtractive polarity
 Mostly used above 100 kV



□ PHASOR GROUPS.

Group 1 : $0^\circ \rightarrow Yy0, Dd0, DZ0$

Group 2 : $180^\circ \rightarrow Yy6, Dd6, DZ6$


Group 3 : $30^\circ \text{ lag } (-30^\circ) \rightarrow Yd1, Dy1, YZ1$

Group 4 : $30^\circ \text{ lead } (+30^\circ) \rightarrow Yd11, Dy11, YZ11$



□ BRITISH PRACTICE.

1) Phase Sequence is ABC.



* To change phase sequence change any two but not three.

2) H.V. "A-N" phasor at 0 o'clock or 12 o'clock.


3) H.V. line 'A' terminal taken from A_2 .

4) $\vec{V}_{A_2A_1}$ & $\vec{V}_{a_2a_1}$ are in phase.

1.E5-2013:

Que:- A 1- ϕ transformer of turn ratio 3:1 is connected 110V AC mains. It draws a primary current of 1.4 at unity P.f when delivering power to a load with an efficiency of 85%. If the no load current of the xmer is 0.34 A, determine a power factor at no load.




Solⁿ: Data inappropriate. [max^m efficiency should be taken].



Star combⁿ - 2

Delta combⁿ - 2

Yy0





$$a_t = \frac{N_{HV}}{N_{LV}}$$


Phase Voltage Transformation Ratio = $\frac{V}{\sqrt{3}} : \frac{V}{\sqrt{3} a_t} = a_t : 1$

Line " " " = $\frac{V : V}{a_t} = a_t : 1$



$S_{HV} = \sqrt{3} VI$ | $S_{LV} = \sqrt{3} \times \left(\frac{V}{a_t}\right) (a_t I)$
 $= \sqrt{3} VI = S_{HV}$






Same Previous fig



Dd0.







∴ A delta-delta connection can be formed using any of one of the two possible conn combⁿ, the British practice is to form HV side delta with the combⁿ A₁B₂, B₁C₂, C₁A₂.



Phase Voltage Transformation Ratio = $V : \frac{V}{a_t} = a_t : 1$

Line " " " = $V : \frac{V}{a_t} = a_t : 1$






$S_{HV} = \sqrt{3} VI$, $S_{LV} = \sqrt{3} \left(\frac{V}{a_t} \right) (a_t I) = \sqrt{3} VI = S_{HV}$

Dd6





Y_{d1}






Phasor Voltage transformation ratio = $\frac{V}{\sqrt{3}} : \frac{V}{\sqrt{3}a_t} = a_t : 1$

L_{ine} " " " "



" " = $V : \frac{V}{\sqrt{3}a_t} = \sqrt{3}a_t : 1$

$S_{HV} = \sqrt{3}VI$, $S_{LV} = \sqrt{3} \left(\frac{V}{\sqrt{3}a_t} \right) \sqrt{3}a_t I = \sqrt{3}VI = S_{HV}$

Yd11





Dy1



Note:- The delta limb is decided by the star limb





Phase Voltage transformation ratio = $V : \frac{V}{a_t} = a_t : 1$

Line " " " = $V : \frac{\sqrt{3}V}{a_t} = \frac{a_t}{\sqrt{3}} : 1$



$$S_{HV} = \sqrt{3} VI \quad , \quad S_{LV} = \sqrt{3} \left(\frac{\sqrt{3} V}{a_t} \right) \left(\frac{a_t I}{\sqrt{3}} \right) = \sqrt{3} VI = S_{HV}$$


DY II



Que:- A 50 HP 440 Volts 3- ϕ I.M. with an efficiency of 0.9 and a p.f. of 0.85 on full load is supplied from a 6600/440V Δ -Y transformer. Ignoring the magnetizing current calculate the current in the high & low voltage wdg. when motor is running.

Sol:- $\eta_{s.m} = 0.85$

$\Rightarrow 0.85 = \frac{254 \times I}{440 \times \sqrt{3} \times \cos\phi}$




$440 \times \sqrt{3} \times \cos\phi =$

$\Rightarrow 50 \times 746 = VI \cos\phi$

$\Rightarrow 37300 = 254 \times I \times 0.85$

$\Rightarrow I = 172.4$

$\frac{50 \times 746 / 0.9}{\sqrt{3} \times 440 \times 0.85} = 63.98A$



Que:- A Y/Y/ Δ with primary, secondary & tertiary voltage of 11 kV, 1 kV and 0.4 kV has a magnetizing current of 3A. There is a balance load of 600 kVA at 0.8 p.f lagging on the secondary wdg and a balance load of 150 kW on the tertiary wdg. Neglecting losses, find primary, secondary & tertiary phase current if the primary p.f is 0.82 lagging.

Sol:- $\vec{S}_1 = \sqrt{3} \times 11 \times I_1 / \cos^{-1}(0.82)$ KVA

$\vec{S}_2 = 600 / \cos^{-1}(0.8)$ KVA

$\vec{S}_3 = \frac{150}{\cos\phi_3} / \phi_3$ KVA (Assuming lagging p.f. load on tertiary)

$\vec{S}_4 = \sqrt{3} \times 11 \times 3 / 90^\circ$ KVA

$$\vec{S}_1 = \vec{S}_2 + \vec{S}_3 + S_0$$

$$\Rightarrow 15.623 I_1 + j 10.905 I_1 = 630 + j [360 + 150 \tan \phi_3 + 33\sqrt{3}]$$

Equating Real part

$$\Rightarrow I_1 = \frac{630}{15.623} = 40.325 \text{ A.}$$

Substituting value of I_1 & equating Imaginary part.

$$\Rightarrow \phi_3 = 8.56^\circ.$$

$$\Rightarrow 150 \times 10^3 = \sqrt{3} \times (0.4 \times 10^3) \times I_{3(\text{line})} \times \cos 8.56^\circ$$

$$\Rightarrow I_{3(\text{line})} = 218.945 \text{ A.}$$

$$\therefore \text{Tertiary delta wdg current} = \frac{218.945}{\sqrt{3}} = 126.41 \text{ A.}$$

□ 3- ϕ TRANSFORMER CONNECTION.

$$S = \sqrt{3} VI$$

For star $\rightarrow \therefore \downarrow I = \frac{\downarrow S}{\sqrt{3} (V)}$ Low capacity, High Voltage.

For Delta $\rightarrow \uparrow I = \frac{\uparrow S}{\sqrt{3} (\downarrow V)}$ High ^{capacity} Voltage, Low Voltage.

According to the general recommendation a Star connection is favoured for low capacity high voltage application whereas a delta connection is recommended for high capacity low voltage application.

In a Xmer the capacity is same on both side and therefore as a general rule the H.V side is connected in star while L.V side is connected in delta.

* In view of the above a delta-star applⁿ is used for step up applⁿ.

* Whereas a star-delta connection is used for step down applⁿ in transmission & sub-transmission applⁿ.

* However in distribution system ^(3- ϕ as well as 1- ϕ) mixed loading is required and therefore a neutral is required on secondary side that happens to be l.v. side. Therefore distribution x'mer are an exception where a Δ/Y -connection is used in step down applⁿ.



* A Δ/Δ connection is used where 3- ϕ loads have to be supplied at low voltage level.

The Δ/Δ connection has further advantages if a bank of 3- ϕ single ϕ x'mer is being used & one transformer has to be removed due to any reason, then the remaining 2- x'mer may still be used as open delta connection also known as V-connection to feed continue to feed 3- ϕ loads at a reduced capacity of 57.7%.



* Although a Y-Y connection is quite attractive for high voltage applⁿ, it is seldom used without a tertiary Δ in order to avoid problems related to harmonics & other problems due to unbalanced loading and flow of zero sequence current.

However, there is a recent trend to use 3 limbed core type x'mer in star-star connection for generator transformer applⁿ even without a tertiary

□ OPEN DELTA OR V- CONNECTION



$$a_t = \frac{N_{HV}}{N_{LV}} = 10:1 \text{ (suppose)}$$




$$S_{\Delta-\Delta} = \sqrt{3} VI$$

$$S_{vee} = \sqrt{3} V \left(\frac{I}{\sqrt{3}} \right) = VI$$

$$\therefore \frac{S_{vee}}{S_{\Delta-\Delta}} = \frac{1}{\sqrt{3}} = 0.577 = 57.7\%$$

$$I_a = I_b = I_c = I$$

$$\vec{S}_{Load} = \sqrt{3} VI / \phi$$



$$\begin{cases} \vec{S}_c = VI \angle \phi + 30^\circ \\ \vec{S}_a = VI \angle (30^\circ - \phi) = VI \angle \phi - 30^\circ \end{cases}$$

where ϕ is (+)ve for lagging

$$\begin{aligned} \Rightarrow \vec{S}_c + \vec{S}_a &= VI \angle \phi + 30^\circ + VI \angle (30^\circ - \phi) \neq VI \angle \phi \\ &= \sqrt{3} VI (\cos \phi + j \sin \phi) \\ &= \sqrt{3} VI \angle \phi = S_{\text{Load}} \end{aligned}$$

Question:
A 3- ϕ 1000 KVA 0.866 lagging p.f load is supplied by a V connection ^{at 400V}. Determine the KVA o/p and operating p.f of each X'mer. Neglect exciting current & all losses.

$$\text{Sol}^n \Rightarrow S_{\text{Load}} = 1000 \text{ KVA} \Rightarrow S_{\text{V}} = \frac{1}{\sqrt{3}} \times 1000 = 577.35$$

$$\Rightarrow S_{\text{Load}} = \frac{1000}{\cos^2(0.866)} = 1000 \angle 30^\circ$$

i.e. $\phi = 30^\circ$.

$$S_1 = \frac{S_L}{\sqrt{3}} \angle \phi + 30^\circ = \frac{1000}{\sqrt{3}} \angle 60^\circ = 577 \angle 60^\circ \text{ KVA}$$



$$S_1 = 577 \text{ KVA; operating p.f} = \cos 60^\circ \text{ lag}$$

$$S_2 = \frac{S_L}{\sqrt{3}} \angle \phi - 30^\circ = \frac{1000}{\sqrt{3}} \angle 30^\circ - 30^\circ = 577 \angle 0^\circ \text{ KVA}$$

$$S_2 = 577 \text{ KVA, operating p.f} = 1.0$$

SCOTT CONNECTION

1. 3-Phase to 2-Phase Conversion



$a_m =$ Turn Ratio of Main $\times \mu_m$

$a_T =$ Turn Ratio of Teaser $\times \mu_T$

$$a_m = \frac{N_1}{N_2}$$

$$a_T = \frac{\left(\frac{\sqrt{3}}{2} N_1\right)}{N_2} = \frac{\sqrt{3}}{2} a_m$$


$$V_b = \frac{V_1}{a_m}$$

$$V_a = \frac{\frac{\sqrt{3}}{2} V_1}{a_T} = \frac{\frac{\sqrt{3}}{2} V_1}{\frac{\sqrt{3}}{2} a_m} = \frac{V_1}{a_m} = V_b$$

Unity P.f.
 $I_a = I_b = I_2$

$$\vec{I}_B = \vec{I}_{bc} - \frac{\vec{I}_A}{2}$$

$$\vec{I}_c = -\vec{I}_{bc} - \frac{\vec{I}_A}{2}$$



$$S_{\text{main}} = V_1 \times I_1, \quad S_{\text{Teasers}} = \frac{\sqrt{3}}{2} V_1 \times I_1$$

$$\therefore \frac{S_{\text{main}}}{S_{\text{Teasers}}} = \frac{2}{\sqrt{3}} \approx 1.15 = 15\%$$

Que: Two 1- ϕ furnaces A & B are supplied at 80v by means of a Scott connected transformer ^{connection} from 3- ϕ 6600 v system. The voltage of furnace A is leading calculate the line current on the 3- ϕ side when
 (a) furnaces take 800 kW each at 0.8 p.f. lag.
 (b) furnace A takes 500 kW at unity P.f & furnace B take 800 kW at 0.707 P.f lagging.

Solⁿ: Taking V_b as reference.

$$V_b = 80 \angle 0^\circ, \quad V_a = 80 \angle 90^\circ$$

$$a_M = \frac{6600}{80} = 82.5$$

$$a_T = \frac{\sqrt{3}}{2} a_M = \frac{\sqrt{3}}{2} \times 82.5 = 71.44$$


Part (a)

$$\vec{I}_b = \frac{800 \times 10^3}{80 \times 0.8} \angle -\cos^{-1}(0.8) = 12500 \angle -36.87^\circ \text{ A}$$

$$\vec{I}_a = \frac{800 \times 10^3}{80 \times 0.8} \angle 90 - \cos^{-1}(0.8) = 12500 \angle 53.13^\circ \text{ A}$$

$$\therefore \vec{I}_{bc} = \frac{I_b}{a_M} = 151.52 \angle -36.87^\circ \text{ A}$$

$$\vec{I}_A = \frac{\vec{I}_a}{a_T} = 174.95 \angle 53.13^\circ \text{ A}, \quad \vec{I}_B = \vec{I}_{bc} - \frac{\vec{I}_A}{2} = 174.96 \angle -66.87^\circ$$



$$\vec{I}_c = -\vec{I}_{BC} - \frac{I_A}{2} = 174.96 \angle 173.13^\circ \text{ A}$$

Part (b)

$$\vec{I}_b = \frac{800 \times 10^3}{80 \times 0.707} \angle -\cos^{-1}(0.707) = 14144.27 \angle -45^\circ \text{ A}$$


$$\vec{I}_a = \frac{500 \times 10^3}{80 \times 1} \angle 90^\circ = 6250 \angle 90^\circ$$

$$\therefore \vec{I}_{BC} = \frac{\vec{I}_b}{a_m} = 171.45 \angle -45^\circ \text{ A}$$

$$\vec{I}_A = \frac{I_a}{a_T} = 87.47 \angle 90^\circ, \quad \vec{I}_B = \vec{I}_{BC} - \frac{\vec{I}_A}{2} = 204.72 \angle -53.69^\circ$$

$$\vec{I}_c = -\vec{I}_{BC} - \frac{\vec{I}_A}{2} = 143.89 \angle 147.41^\circ \text{ A}$$

□: PARALLEL OPERATION OF TRANSFORMER.



$$E_A > E_B \Rightarrow \frac{V_1}{a} > \frac{V_1}{b} \Rightarrow a < b \text{ multiplying by } I_c$$

$$\Rightarrow I_c a < I_c b \Rightarrow \frac{I_c}{a} > \frac{I_c}{b}$$

condition to be satisfied for // operation.

(A) For 1- ϕ & 3- ϕ Transformer.

1. Same polarity \rightarrow MUST.
2. Equal Voltage Ratio \rightarrow MUST
(& Same Voltage Rating)

Note :- A small difference in Voltage ratio may be permitted if unavoidable.

3. Same Per unit Impedance for proportional ^{load} sharing \rightarrow Desirable
Name plate Z_{pu}

4. Same $\frac{X}{R}$ ratio (i.e. same O_{eq}) for same p.f. operation \rightarrow Desirable.

(B) For - 3- ϕ transformer only.

5. Same phase Sequence \rightarrow MUST.


6. Zero-phase difference \rightarrow MUST

This means that X'mer belonging to the same phase group may alone be paralleled.

□ LOAD SHARING

EQUAL VOLTAGE RATIO

i.e. $E_A = E_B$.



$$E_A = E_B = \frac{V_1}{a}$$

The per unit load on Transformer.

$$\vec{I}_j \cdot \vec{Z}_{j(\Omega)} = \text{constant}$$

$$\Rightarrow \vec{I}_j \propto \frac{1}{\vec{Z}_{j(\Omega)}}$$

$$\Rightarrow \vec{V}^* \vec{I}_j \propto \frac{1}{\vec{Z}_{j(\Omega)}}$$

$$\Rightarrow \vec{S}_j^* \propto \frac{1}{\vec{Z}_{j(\Omega)}}$$

$$\Rightarrow \vec{S}_j^* \propto \frac{1}{\vec{Z}_{j(\text{P.U.})} \times Z_{\text{base}(j)}}$$

$$\Rightarrow \vec{S}_j^* \propto \frac{1}{\vec{Z}_{j(\text{P.U.})} \times \left[\frac{(V_{\text{rated}})^2}{S_{j(\text{rated})}} \right]}$$

$$\Rightarrow \vec{S}_j^* \propto \frac{S_{j(\text{rated})}}{\vec{Z}_{j(\text{P.U.})}}$$

$$\Rightarrow \frac{\vec{S}_j^*}{S_{j(\text{rated})}} \propto \frac{1}{\vec{Z}_{j(\text{P.U.})}}$$

$$\Rightarrow \boxed{\vec{S}_j^*(\text{pu}) \propto \frac{1}{\vec{Z}_{j(\text{pu})}}}$$

Note → This means that the P.u. loading on a transformer is inversely proportional to its P.u. impedance & therefore the xmer with lowest P.u. impedance would have highest P.u. loading & consequently reach full load first.

For Proportional Load Sharing:

$$S_j \propto S_{j(\text{rated})} \Rightarrow \frac{S_j}{S_{j(\text{rated})}} = \text{constant}$$

$$\Rightarrow S_{j(\text{pu})} = \text{constant}$$

$$\therefore S_{j(\text{pu})} \propto \frac{1}{Z_{j(\text{pu})}}$$

∴ $\frac{1}{Z_{j(\text{pu})}}$ (for Proportional Load Sharing)

Note This means that proportional load sharing requires same p.u. loading & this can only be obtained if the name plate pu impedance is same for all x'mer.

Que: → 2. 1-φ x'mer rated 1000 KVA and 500 KVA respectively are connected in // on both h.v & l.v sides they have equal Voltage ratings of 11 kV/400 V & their p.u impedances are $(0.02 + j0.07)$ & $(0.0455 + j0.0788)$ respectively

(a) How will the following loads be shared

- (i) 360 KVA at 0.9 P.f lag.
- (ii) 500 kW at unity P.f.

Solⁿ: $X_A^r = 1000$, $X_B^r = 500$

$X_A^r = 1000$ KVA, $X_B^r = 500$ KVA, $S_L = 360 / \cos^{-1}(0.9)$

$Z_A = (0.02 + j0.07) = 0.0728 / 74.05^\circ$ p.u.

$Z_B = (0.0455 + j0.0788) = 0.0909 / 59.99^\circ \approx 0.0910 / 60^\circ$ p.u.

Selecting common base VA = 1000 KVA.

$Z_{A(new)} = \text{same}$, $Z_{B(new)} = 0.0910 / 60^\circ \times \left(\frac{1000}{500}\right)$

$Z_{B(new)} = 0.182 / 60^\circ$ p.u.

$\vec{S}_A^* = \frac{\vec{Z}_{B(new)}}{\vec{Z}_{B(new)} + \vec{Z}_A} \times \vec{S}_L^* = \frac{0.182 / 60^\circ}{0.0728 / 74.05^\circ + 0.182 / 60^\circ} \times 360 / \cos^{-1}(0.9)$

$= 258.73 / -29.84^\circ$ KVA.

i.e. 224.42 kW at 0.8674 P.f lag.

$\vec{S}_B = \vec{S}_L - \vec{S}_A$

$= 360 / 25.84^\circ - 258.73 / 29.84^\circ = 103.49 / 15.8^\circ$ KVA

i.e. 99.58 kW at 0.9622 P.f. lag.

Part (v)

$$(ii) \vec{S}_L = \frac{500}{1.0} \angle 0^\circ \text{ KVA.}$$

$$\vec{S}_A = \frac{0.182 \angle 60^\circ}{0.0728 \angle 74.05^\circ + 0.182 \angle 60^\circ} \times 500 \angle 0^\circ$$

$$\vec{S}_A = 359.34 \angle -4^\circ \text{ KVA}$$

i.e. 358.47 kW at 0.9976 P.f lag

$$\vec{S}_B = \vec{S}_L - \vec{S}_A = 500 \angle 0^\circ - 359.34 \angle -4^\circ$$

$$\vec{S}_B = 143.74 \angle -10.04^\circ \text{ KVA}$$

i.e. 141.54 kW at 0.984 P.f load.

Part (b) what is the largest value of 0.8 P.f. lagging load that can be delivered by 11 comb² at the rated voltage. Determine the load share & P.f. of the ~~two~~ 2 transformer under these condⁿ.

solⁿ:- ∴ P.u. $Z_A < Z_B$

∴ Transformer 'A' would reach full load first.

When $S_A = 1000 \text{ KVA}$

$$\text{Then, } \frac{\vec{S}_B^*}{\vec{S}_A^*} = \frac{\vec{Z}_A(\Omega)}{\vec{Z}_B(\Omega)} \Rightarrow \frac{\vec{S}_B^*}{\vec{S}_A^*} = \frac{\vec{Z}_A}{\vec{Z}_B(\text{new})}$$

$$\Rightarrow \vec{S}_B^* = \vec{S}_A^* \times \frac{\vec{Z}_A}{\vec{Z}_B(\text{new})}$$

$$\therefore \vec{S}_L^* = \vec{S}_B^* + \vec{S}_A^*$$

$$= \vec{S}_A^* \left[1 + \frac{\vec{Z}_A}{\vec{Z}_B} \right]$$

$$\vec{S}_A^* = 1000 \angle -\phi_A \quad \text{[Assuming lag operation of A]}$$

$$\Rightarrow \vec{S}_L^* = 1000 \angle -\phi_A \left[1 + \frac{0.0728 \angle 74.05^\circ}{0.182 \angle 60^\circ} \right]$$

$$\Rightarrow \vec{S}_L^* = 1000 \angle -\phi_A [1.3914 \angle 4^\circ] = 1391.4 \angle 4^\circ - \phi_A$$

$$\Rightarrow S_L \angle -36.87^\circ = 1391.4 \angle 4^\circ - \phi \Rightarrow S_L = 1391.4 \text{ kVA}$$

$$\therefore \phi_A = 40.87^\circ, \text{ i.e. } \vec{S}_A = 1000 \angle 40.87^\circ$$


i.e. 756.2 kW at 0.7562 lag.

$$\vec{S}_B = \vec{S}_L - \vec{S}_A = 1391.4 \angle 36.87^\circ - 1000 \angle 40.87^\circ = 399.97 \angle 26.83^\circ$$

i.e. 356.92 kW at 0.8923 p.f. lag.

□ PHASOR DIAGRAM

Equal Voltage ratio, Same $\frac{X}{R}$ ratio, Lagging P.f. load.




* Impedance lies in semi-circle.

Small transformer impedance angle = 70° to 76°

Large " " " " = 76° - 80° .

$\phi_A > \phi_B$ different $\frac{X}{R}$ ratio, Equal Voltage ratio, Lagg. P.f. load



Gate-2014

Que:-

$$V_s = \sqrt{2} \pi f \Phi_m N$$

$$\Rightarrow \Phi_m N = \text{constant}$$

$$\Rightarrow \frac{N \int \vec{H} \cdot d\vec{l}}{s} \times N = \text{constant}$$

$$\Rightarrow N^2 \alpha s \quad \therefore \int \vec{H} \cdot d\vec{l} = \text{constant}$$

$$\propto \frac{l}{\text{Area}}$$

$$N^2 \propto \frac{l}{R_{\text{radius}}^2} \Rightarrow N \propto \frac{l}{R_{\text{radius}}}$$


□ UNEQUAL VOLTAGE RATIO.

$$\vec{E}_A \neq \vec{E}_B$$

By Millman's theorem.

$$(i) \vec{V} = \vec{I}_{sc} \vec{Z}_{\text{parallel}}$$

$$\text{Where } \vec{I}_{sc} = \sum_{j=1}^n \frac{\vec{E}_j}{\vec{Z}_j}$$



$$\frac{1}{Z_p} = \frac{1}{Z_b} + \sum_{j=1}^n \frac{1}{Z_j}$$

$$2) \vec{I}_j = \frac{\vec{E}_j - \vec{V}}{\vec{Z}_j} \quad \text{where } j = 1, 2, 3, \dots, n \quad \text{Index notation form}$$

$$3) \vec{S}_j = \vec{V} \vec{I}_j^* \quad \text{where } j = 1, 2, 3, \dots, n.$$

$$\vec{S}_L = \sum_{j=1}^n \vec{S}_j$$

Calculation check.

$$\vec{S}_L = \frac{V^2}{\vec{Z}_L^*}$$

Que: → Two transformers A & B are connected in parallel to a common load $0.2 + j1.5 \Omega$. Their impedances in secondary turn are $0.8 \times Z_A = 0.15 + j0.5 \Omega$ & $Z_B = (0.1 + j0.6)$. Their no load terminal voltage are $E_A = 207 \angle 0^\circ$ and $E_B = 205 \angle 0^\circ$. Find the power of P. f. of each transformer.

$$\vec{I}_{sc} \Rightarrow \vec{V} = \vec{I}_{sc} \vec{Z}_{||}$$

$$\Rightarrow \vec{I}_{sc} = \frac{207 \angle 0^\circ + 205 \angle 0^\circ}{0.15 + j0.5 \Omega + 0.1 + j0.6} = \frac{207 + j0 + 205 + j0}{0.25 + j1.1}$$

$$= \frac{412 \angle 0^\circ}{1.128 \angle 77.19^\circ} \Rightarrow 365.24 \angle -77.19^\circ$$

$$I_{sc} = \frac{207 \angle 0^\circ}{0.15 + j0.5} + \frac{205 \angle 0^\circ}{0.1 + j0.6}$$

$$= \frac{207 \angle 0^\circ}{0.522 \angle 73.36^\circ} + \frac{205 \angle 0^\circ}{0.608 \angle 80.53^\circ}$$

$$= 396.55 \angle -73.36^\circ + 337.17 \angle -80.53^\circ$$

$$\Rightarrow I_{sc} = 733.72 \angle -76.63^\circ \text{ A}$$

$$\Rightarrow \frac{1}{Z_p} = \frac{1}{Z_L} + \frac{1}{Z_A} + \frac{1}{Z_B}$$

$$\Rightarrow Z_p = 0.2585 \angle 72.85^\circ \Omega$$

$$\Rightarrow \vec{V} = \vec{I}_{sc} Z_p = 189.25 \angle -3.78^\circ$$

$$\Rightarrow \vec{I}_A = \frac{\vec{E}_A - \vec{V}}{\vec{Z}_A} = 42.21 \angle -38.81^\circ \text{ A}$$

$$\Rightarrow \vec{I}_B = \frac{\vec{E}_B - \vec{V}}{\vec{Z}_B} = 33.57 \angle 42.87^\circ \text{ A}$$

$$\vec{S}_A = \vec{V} \vec{I}_A^* = 7.988 \angle 35.03^\circ \text{ KVA}$$


i.e. 6.541 kW at 0.8189 p.f. lag.

$$\vec{S}_B = -\vec{V} \vec{I}_B^* = 6.353 \angle 39.09^\circ \text{ KVA}$$

i.e. 4.931 kW at 0.7762 p.f. lag.


□ PHASOR DIAGRAM

$E_A > E_B$, $O_A = O_B$ lag p.f. Load.




□. MAGNETISING CURRENT PHENOMENON.

- * If the applied voltage to a transformer is sinusoidal then the core flux should also be sinusoidal.
- * If the magnetization curve of the core material could have been linear then the magnetization current would also have been sinusoidal.
- * Due to economic reasons modern transformers are operated with high flux density that drives the core into deep saturation.




consequently the magnetizing current is peaky consisting of dominant peaking 3rd harmonic component.




* The third harmonic component of magnetizing current can flow only if the electric ckt permits.

Therefore it can easily flow 1- ϕ transformer of 1- ϕ ckt.


However in 3- ϕ ckt these 3rd harmonic component constitutes zero sequence current & therefore they can only flow a star neutral is connected to source neutral or it can flow in a closed Δ .





* If the electric ckt doesn't permit flow of 3rd harmonic component of magnetizing current then magnetizing current remain sinusoidal if non triplen higher harmonic odd harmonics are neglected.


* A sinusoidal magnetizing current results into a flat topped core flux containing dominant depressing 3rd harmonic flux component.




* A 3rd harmonic flux can get established only if magnetic ckt permits.

Therefore it can get easily established in transformer having independent magnetic ckt such as


3- ϕ bank of 3- ϕ transformer, 3- ϕ shell type transformer & 5 limbed (or 4 limbed) core type transformer.



* If the magnetic ckt permits the 3rd harmonic flux then it results into a peaky emf in primary as well as secondary wdg causing high insulation stress in addition to a very objectional phenomena known as oscillating neutral.



$$\vec{V}_{a3} = \vec{V}_{b3} = \vec{V}_{c3} = V_3$$



Better View of oscillating neutral.

The above problems are encountered because the electric circuit didn't permit flow of 3rd harmonic component in magnetizing current. In 3- ϕ transformer if the star neutral of the primary is connected to the source neutral a path for 3rd harmonic current would be available.

However such a solⁿ would not be recommended as now the source phase voltage that may contain 3rd harmonic component would be impressed across the transformer wdg resulting into flow of 3rd harmonic current in the transmission line of secondary side & that would create objectionable communication interference.

The other solⁿ is to provide closed Δ . Therefore it is recommended the x^lmer should be connected in Y/ Δ , Δ / Δ or if a Y/Y connection is used then it should be provided with tertiary Δ .

Note \Rightarrow For load current \rightarrow mmf balance is must otherwise only magnetizing current will flow.

The presence of Δ wdg permits the flow of 3rd harmonic currents in the closed Δ that substitutes the missing 3rd harmonic current in the primary line & restores harmonic variation to the core flux.

It may be noted that only 1 to 2% of the 3rd harmonic flux in the core is sufficient to circulate the required 3rd harmonic in the closed Δ .


The above problem are experienced in those transformers that have magnetically independent ckt. However in a 3 limb core type transformer the magnetic ckt is interlinked & therefore the 3rd harmonic flux finds a very high reluctance path through air and tank walls resulting into extremely weak 3rd harmonic flux although at the cost of tank wall heating.

Therefore in large transformer a copper ring surrounds the core to reduce the tank wall heating. Thus 3 limbed core type xmer may be used by Y/Y connection without a tertiary Δ .

However if unbalanced is expected to exceed 10%, then it would be advised to provide a tertiary Δ . The presence of tertiary Δ also establishes the neutral prevents current choking & permits unbalanced load.

In a 3 limbed core type xmer the core flux remains almost sinusoidal but the magnetizing current contain 5th & 7th harmonic. Since these can't be suppressed by electric connection, if there

Presence is objectional if 5 limb or 4 limb core should be used.




If the applied voltage is sinusoidal under steady state condⁿ the core flux should change from $-\phi_m$ to $+\phi_m$ during to the +ve half cycle of the applied voltage.

* If at the instant of switching, the instantaneous value of applied voltage is ^{same} stay at +ve peak then the core flux rise from its natural zero value to $+\phi_m$ in a quarter cycle resulting into trouble free switch ON of the transformer.

* However if at the instant of switching the instantaneous value of applied voltage is zero and say going toward +ve then the core flux should rise from natural zero value to $+2\phi_m$ in half cycle.

This doubling of flux is known as doubling effect & is accompanied by huge magnetising inrush current reaching 5 times full load current.




Cylindrical pole.

$\frac{1}{3} \rightarrow$ Pole.


$\frac{2}{3} \rightarrow$ wdg.

Nickel, Molybdenum, Vanadium
Chromium.

$P \neq 4$



SALIENT POLE ROTOR.




] SINUSOIDAL FLUX DENSITY DISTRIBUTION IN THE AIR GAP OF SYN. GENERATOR.

* The desired waveform the generated voltage is sinusoidal.

* A sinusoidal voltage may only be obtained when the flux density distribution in the air gap is sinusoidal.

* In salient pole m/c, the field mmf wdg is concentric but concentrated & therefore the field mmf is constant. Hence a sinusoidal flux density distribution is obtained by varying the airgap of the poles. This is done by shaping the pole such that the air gap at the centre of pole & goes on increasing as one moves away from the centre of the pole.

* Of course the variation in the airgap should be compatible with the sinusoidal flux density distribution in the air gap.




* In a cylindrical rotor the air gap is constant but the field wdg is distributed in space although it is concentric. Hence the reluctance of the air gap is constant.

be obtained by making the field mmf sinusoidal.

This is obtained by providing max² no. of field turns in the slots adjacent to the interpole axis and the no. of field turn in subsequent slot goes on decreasing as one moves towards the pole such that the minimum number of poles is provided in the slots adjacent to the poles.


With such an arrangement the field mmf is stepped that approaches a sinusoidal as the variation in the no. of turns is done compatible with sinusoidal function. A perfectly sinusoidal field mmf may only be obtained if a number of field wdg slots is infinite.

INDUCED EMF EQ^N



$$\Phi = \text{flux per pole} = \left(\frac{2}{\pi}\right) B_m \times \frac{\pi DL}{P}$$

N_{ph} = No. of turns per phase.



$$E_{aa'} = N_{ph} \Phi \cos \omega t.$$

$$e_{aa'} = - \frac{d\lambda_{aa'}}{dt}$$

$$= - \frac{d}{dt} (N_{ph} \phi \cos \omega t)$$

$$= - \left[N_{ph} \phi \frac{d}{dt} (\cos \omega t) + N_{ph} \cos \omega t \frac{d\phi}{dt} \right]$$

$$e_{aa'} = - \left[N_{ph} \phi \omega (-\sin \omega t) + N_{ph} \cos \omega t \frac{d\phi}{dt} \right]$$

$$e_{aa'} = \underbrace{N_{ph} \phi \omega \sin \omega t}_{\text{Speed Voltage}} - \underbrace{N_{ph} \cos \omega t \frac{d\phi}{dt}}_{\text{Transformer Voltage}}$$

Since field excitation in syn. m/c is always dc, $\frac{d\phi}{dt} = 0$

Therefore,
$$e_{aa'} = N_{ph} \phi \omega \sin \omega t$$

$$= \underbrace{N_{ph} \phi \omega}_{\text{max}^m \text{ value}} \cos(\omega t - 90^\circ)$$

$$\text{RMS } E_{ph} = \frac{N_{ph} \phi \omega}{\sqrt{2}}$$


$$\therefore E_{ph} = \frac{N_{ph} \phi (2\pi f)}{\sqrt{2}}$$

$$E_{ph} = \sqrt{2} \pi f \phi N_{ph} \text{ Volts/phase.}$$


Valid for full pitched concentrated wdg.

1 CHORDED WINDING.

Chording angle = α



Full pitched wdg.



$$E_{res} = 2 \cos \frac{\alpha}{2}$$

$$\therefore \text{Chording factor, } K_c = \cos \frac{\alpha}{2}$$

$$\therefore E_{ph} = K_c \times \sqrt{2} \pi f \Phi N_{ph}$$

↓
Valid for Chorded but concentrated wdg.


For n^{th} harmonic → Replace α by $n\alpha$.

$$K_c \quad K_c(n) = \cos \frac{n\alpha}{2}$$


To eliminate n^{th} harmonic :- $\frac{n\alpha}{2} = 90^\circ \Rightarrow \alpha = \frac{180^\circ}{n}$

Practical Value of $\alpha = 30^\circ$.

□ DISTRIBUTION FACTOR



$E_{\text{resultant}}$
For distributed wdg.



For concentrated wdg.

β = Angle b/w adjacent slots.

$$\Rightarrow \beta = \frac{360^\circ}{\text{No. of slots}} \text{ mech.}$$

$$\Rightarrow \beta = \frac{P}{2} \times \frac{360^\circ}{\text{No. of slots}} \text{ elect}$$

$$\Rightarrow \beta = \frac{180^\circ}{\text{No. of slots per pole}} \text{ elec}$$

m = (No of slots per pole) per phase

$$\text{Distribution Factor} = \frac{2R \sin \frac{m\beta}{2}}{m \times 2R \sin \frac{\beta}{2}} = K_d$$

$$K_d = \frac{\sin \frac{m\beta}{2}}{m \cdot \sin \frac{\beta}{2}}$$

β = Phase spread
or
Phase Breadth
or
Phase Belt

* For n^{th} harmonic (Replace β by $n\beta$).

$$K_d(n) = \frac{\sin m \frac{(n\beta)}{2}}{m \cdot \sin \frac{(n\beta)}{2}}$$

* Approx K_d ; $\sin \frac{\beta}{2}$ is very small.

$$\sin \frac{\beta}{2} \approx \frac{\beta}{2} \text{ (in radians)}$$

$$\text{Then } K_d = \frac{\sin \frac{m\beta}{2}}{\frac{m\beta}{2}}$$

$$\Rightarrow K_d = \frac{\sin \frac{\text{Phase Spread}}{2}}{\frac{\text{Phase Spread}}{2}}$$

* For Chorded & Distributed Wdg

$$E_{ph} = K_c K_d \times \sqrt{2} \pi f \Phi N_{ph} \text{ Volts per phase.}$$

$$= K_w \times \sqrt{2} \pi f \Phi N_{ph}$$

where $K_w = \text{winding factor}$

$$\Rightarrow K_w = K_c K_d$$

Question: A 3- ϕ 2 pole 3000 rpm star connected cylindrical rotor turbo generator has following data.

No. of slots = 60, Max^m flux density in air gap = 1.32 T

Mean air gap diameter = 1.12 m, Effective axial length

= 3m, No. of turns per phase = 10. Calculate line-to

line voltage on an n/n load if the coil span is 150°.

$$\text{So } \alpha = 180^\circ - 150^\circ = 30^\circ \quad \therefore K_c = \cos \frac{30^\circ}{2} = 0.9659$$

$$\Rightarrow \beta = \frac{360^\circ}{60^\circ} \text{ mech} = 6^\circ \text{ mech} = \frac{P}{2} \times 6^\circ = \frac{2}{2} \times 6^\circ = 6^\circ \text{ elec.}$$

$$m = \frac{60/2}{3} = 10$$

$$K_d = \frac{\sin \frac{10 \times 6^\circ}{2}}{10 \cdot \sin \frac{6^\circ}{2}} = 0.9554$$

$$\Rightarrow K_w = 0.9228$$

$$\phi = \frac{2}{\pi} \times 1.32 \times \frac{\pi \times 1.12 \times 3}{2} = 4.4852 \text{ Wb per pole}$$


$$f = \frac{PN}{120} = \frac{2 \times 3000}{120} = 50 \text{ Hz.}$$

$$E_{ph} = 0.9659 \times 0.9554 \times \sqrt{2} \pi \times 50 \times 4.4852 \times 10$$




$$= 9092.13 \text{ VOLTS (L-N)}$$

$$E_{(LL)} = \sqrt{3} \times 9092.13 \approx 15.75 \text{ KV}$$


□ ARMATURE REACTION IN SYNCHRONOUS MACHINE.



$a' \otimes$ unity Internal PF.



GENERATOR




Directly Magnetising

$\because F_f < F_r$
Then Generator is underexcited

Zero pf Lead.

MOTOR




Directly Magnetising Armature \times

$\because F_f > F_r$


The motor is overexcited.

Zero pf Lead.



Both cross magnetising &


Demagnetising Armature \times



P.f. lead.

a' O

GENERAL PHASOR DIAGRAM



$$\vec{V} = \vec{E}_f + \vec{E}_{ar} + \vec{E}_{al} - I_a R_a$$

E_f = Internal voltage or Excitation voltage.
or open ckt. voltage.

E_r = Air gap voltage.

E_{ar} = Armature Reaction voltage.


E_{al} = Armature Leakage Flux voltage.

$$\Rightarrow \vec{E}_f = \vec{V} + \vec{I}_a R_a - \vec{E}_{al} - \vec{E}_{ar}$$

X_l : Armature Leakage Reactance.

X_{ar} : Armature Reaction Reactance / Magnetising Reactance.

$$\vec{E}_f = \vec{V} + \vec{I}_a R_a + j \vec{I}_a X_l + j \vec{I}_a X_{ar}$$



$$= \vec{V} + \vec{I}_a R_a + j \vec{I}_a (X_l + X_{ar})$$

$$\begin{aligned} \vec{E}_f &= \vec{V} + \vec{I}_a R_a + j \vec{I}_a X_s \\ &= \vec{V} + \vec{I}_a (R_a + j X_s) \end{aligned}$$

$$\begin{aligned} X_s &= X_{ar} + X_l \\ &= \text{Synch. Reactance} \end{aligned}$$


$$\vec{E}_f = \vec{V} + \vec{I}_a Z_s$$

$$Z_s = R_a + j X_s = \text{Syn. Impedance}$$



$$= \sqrt{(R_a)^2 + (X_s)^2} \angle \tan^{-1} \frac{X_s}{R_a}$$

$$Z_s = Z_s / \phi_s$$




EQUIVALENT CKT.




□ OPEN AND SHORT CIRCUIT TEST.



Open ckt Test.



Short ckt Test



Linear


$$X_s = \frac{V_{o.c.}}{\text{Short ckt current}}$$

$$\Rightarrow X_s = \frac{K_1 I_f}{K_2 I_f} = \frac{K_1}{K_2} = \text{constant}$$

Saturated

$$X_s = \frac{\text{Constant}}{K_2 I_f}$$

$$\propto \frac{1}{I_f}$$



* Definition of I_{sc} :-

I_{sc} by definition is that value of short ckt armature current that is obtained with that value of field current which gives rated voltage on open & circuit.

$$X_{s(sat)} = \frac{V_{rated}}{I_{sc}} \quad \left| \text{at } I_f = 0 \right.$$

Saturated Syn.

reactance $X_s(adj)$

* MODIFIED AIR GAP LINE.

It is occ of an equivalent unsaturated m/c that gives rated voltage at the same field current as the actual machine.

□ SHORT CIRCUIT RATIO.

It is defined as ratio of field current required to give rated voltage on open ckt. to the field current required

to give rated current on short ckt.

$$\text{Short circuit Ratio (SCR)} = \frac{A}{OB}$$

$$\text{SCR} = \frac{I_{sc}}{I_{rated}} \left[= I_{sc(pu)} \right]$$

$$= \frac{V_{rated}}{I_{rated} X_{s(sat)}}$$

$$= \frac{V_{rated}}{I_{rated} X_{s(sat)}}$$

$$\Rightarrow \text{SCR} = \frac{Z_{base}}{X_{s(sat)}}$$

$$= \frac{1}{X_{s(sat)} / Z_{base}}$$

$$\text{SCR} = \frac{1}{X_{s(sat)} \text{ pu}}$$

$$\text{SCR} \propto \frac{A^2 \text{ gap}}{\text{No. of turns per phase}}$$

A machine with a low SCR has low air gap and small physical size. Obviously therefore it is low cost machine.

However a low SCR means high synch. reactance that results into bad voltage regulation and produces max^m power developed.

With a small radius the moment of

Inertia is low therefore m/c is less steamed.

Therefore Turbogenerators that have cylindrical rotor are being manufactured with small air gap so that they remain economic. Since they become less stable, IEEE recommends that the SCR of turbogenerator should be above 0.88 but not less than 0.95.

On the other hand hydrogenerators being low speed m/c require large no. of poles & therefore are big in size.

The air gap is also larger and therefore a SCR of hydrogenerator is usually 1.0 to 1.6. This increases the cost of m/c but higher moment of inertia and the low syn. reactance makes the m/c more stable.

IEEE recommends that the SCR of hydrogenerator should be according to customer requirements but never less than 0.8.


□ ZERO POWER FACTOR CHARACTERISTICS (ZPFC)

OR


POTIER CHARACTERISTICS

V vs I_f when $I_a = I_{rated}$ at ZPF lag.

* It is the plot of Terminal Voltage against field current when armature current is maintained at zero power factor lag.



EXPERIMENTAL ZPFC.



* Since change in I_f or change in load affect terminal voltage and armature current both, it is recommended that a field current is varied for terminal voltage & subsequent the load is adjusted for rated current.

Ex:

I_f	V	I_a
3.4 A	150V	100A
3.6 A	153V	110A
3.6 A	157V	100A

↑ vary excitation


↙ Vary load

Locus of Point B is ZPFC also called potier characteristics.

II. VOLTAGE REGULATION.

Regulation of an Alternator is defined as the rise in terminal voltage expressed as a fraction of full load rated voltage when full load at a specified power factor is thrown off keeping excitation constant.



III. VOLTAGE REGULATION BY EMF METHOD / SYNCH. REACTANCE



$$\therefore \text{Voltage Regulation} = \frac{OQ - OP}{OP} \text{ per unit.}$$

* Voltage Regulⁿ obtained by this method is higher than actual & therefore this method is called pesimistic method.



□ VOLTAGE REGULATION BY MMF METHOD / AMPERE TURN



$$\left. \begin{aligned}
 OA &\equiv F_r(j_{\text{enal}}) \\
 OB &\equiv F_{ar}(\text{Total}) \\
 AC &= OB \\
 OC &\equiv F_f
 \end{aligned} \right\} \text{voltage Regl}^{\%} : \frac{OQ - OP}{OP} \text{ per unit.}$$

The voltage Regl[%] obtained by this method is lower than actual & therefore this method is called optimistic method.

□ VOLTAGE REGULATION BY ZPF METHOD OR POTIER METHOD.



$OA \equiv F_r$
 $AB \equiv F_{ar}$ (from potier Δ)
 $\therefore OB = F_f$

* In the ZPF method of determination of voltage Reglⁿ the quantities are treated as they are i.e. voltages as EMF & Amp turns as MMF.

The voltage Reglⁿ obtained by this method is therefore neither pessimistic nor optimistic but almost realistic.


* This method had been used for quite a long time before American Standard Association proposed modification of

MMF method for determination of voltage Regulation of Synchron generators.

* ONE P.U. FIELD CURRENT.

One p.u field current is that current that gives rated voltage on air gap line.

VOLTAGE REGULATION BY ASA METHOD OR ASA MODIFICATION OF MMF METHOD.



$$\% \text{ Reg}^n = \frac{OQ - OP}{OP} \text{ P.u.}$$

$OA \equiv F_r(\text{Final})$ of unsaturated m/c.

$AB \equiv F_{or}(\text{Total})$ taken from S.C.C. Data.

$\therefore OB \equiv F_f$ of unsaturated m/c.

$CD \equiv$ Additional field MMF required to overcome saturated at E_r (ie f_r) level.

$BE = CD$

$\therefore OE \equiv F_f$ of Actual m/c under actual operating condⁿ.


* ASA modification of MMF method acknowledges the fact that the MMF of an unsaturated m/c should be combined with another MMF of an unsaturated m/c.

Accordingly $\vec{F}_r(\text{final})$ is found out not from the o.c.c. but from air gap line, when it is combined with $\vec{F}_r(\text{total})$ which comes from an unsaturated m/c, the total field MMF F_f is obtained for an unsaturated m/c.

It is further realised that the degree of saturation of the syn. m/c would depend upon resultant air gap MMF. Hence, E_r is first calculated using potier drop & the additional field MMF required to overcome saturation for air gap voltage E_r is determined as horizontal intercept CD b/w air gap line & o.c.c. This additional MMF is arithmetically added to ~~effect~~ the unsaturated m/c to determine the actual F_f of the m/c under actual operating condⁿ. Vol. Req^t is then obtained by determining E_f corresponding to final F_f .

Vol. Req^t obtained by this method has been found to be satisfactory for cylindrical as well as salient pole m/c and is recommended method for determination of Vol. Req^t of syn. generator of all type.

□ POWER ANGLE EQUATION.



GENERATOR.

$$\vec{E}_f = \vec{V} + \vec{I}_a \vec{Z}_s$$

$$\Rightarrow \vec{I}_a = \frac{\vec{E}_f - \vec{V}}{\vec{Z}_s}$$

$$= \frac{E_f \angle \delta - V \angle 0^\circ}{Z_s \angle \theta_s}$$

$$\vec{I}_a = \frac{E_f}{Z_s} \angle \delta - \theta_s - \frac{V}{Z_s} \angle -\theta_s$$

$$\vec{S}_{out} = P_{out} + j Q_{out} = \vec{V} \vec{I}_a^*$$

$$= V \angle 0^\circ \left[\frac{E_f}{Z_s} \angle \delta - \theta_s - \frac{V}{Z_s} \angle -\theta_s \right]^*$$

$$= V \angle 0^\circ \left[\frac{E_f}{Z_s} \angle \theta_s - \delta - \frac{V}{Z_s} \angle \theta_s \right]$$

$$\vec{S}_{out} = \frac{VE_f}{Z_s} \angle \theta_s - \delta - \frac{V^2}{Z_s} \angle \theta_s \quad \text{--- (1)}$$

$$\therefore P_{out} = \frac{VE_f}{Z_s} \cos(\theta_s - \delta) - \frac{V^2}{Z_s} \cos \theta_s$$

For Max^m P_{out} $\Rightarrow \delta = \theta_s$.

$$\& \text{ Then } P_{out(max)} = \frac{VE_f}{Z_s} - \frac{V^2}{Z_s} \cos \theta_s$$

$$\vec{S}_{dev} = P_{dev} + j Q_{dev} = \vec{E}_f \vec{I}_a^*$$

$$= E_f \angle \delta \left[\frac{E_f}{Z_s} \angle \delta - \theta_s - \frac{V}{Z_s} \angle -\theta_s \right]^*$$

$$= E_f \angle \delta \left[\frac{E_f}{Z_s} \angle \theta_s - \delta - \frac{V}{Z_s} \angle \theta_s \right]$$



$$\vec{S}_{dev} = \frac{E_f^2}{Z_s} \angle 0_s - \frac{VE_f}{Z_s} \angle 0_s + \delta \quad \text{--- (ii)}$$

$$\therefore P_{dev} = \frac{E_f^2}{Z_s} \cos 0_s - \frac{VE_f}{Z_s} \cos (0_s + \delta)$$

P_{dev} is max^m when $\delta = (180^\circ - 0_s)$. & this decides static stability limit.

$$\& P_{dev(max)} = \frac{E_f^2}{Z_s} \cos 0_s + \frac{VE_f}{Z_s}$$

MOTOR



MOTOR.

$$\vec{E}_f = \vec{V} - \vec{I}_a R_a$$

$$\Rightarrow \vec{I}_a = \frac{\vec{V} - \vec{E}_f}{-Z_s}$$

$$= \frac{V \angle 0^\circ - E_f \angle -\delta}{Z_s \angle 0_s}$$

$$\Rightarrow \vec{I}_a = \frac{V}{Z_s} \angle -0_s - \frac{E_f}{Z_s} \angle -(0_s + \delta)$$

$$\begin{aligned} \vec{S}_{dev} &= P_{dev} + jQ_{dev} = \vec{E}_f \vec{I}_a^* \\ &= E_f \angle -\delta \left[\frac{V}{Z_s} \angle -0_s - \frac{E_f}{Z_s} \angle -(0_s + \delta) \right]^* \\ &= E_f \angle -\delta \left[\frac{V}{Z_s} \angle 0_s - \frac{E_f}{Z_s} \angle (0_s + \delta) \right] \end{aligned}$$

$$\Rightarrow \vec{S}_{dev} = \frac{VE_f}{Z_s} \angle 0_s - \delta - \frac{E_f^2}{Z_s} \angle 0_s \quad \text{--- (iii)}$$

$$P_{dev} = \frac{VE_f}{Z_s} \cos (0_s - \delta) - \frac{E_f^2}{Z_s} \cos 0_s$$

P_{dev} is max^m, when $\delta = \theta_s$. & this decides static stability limit.

$$\& P_{dev(max)} = \frac{VE_f}{Z_s} - \frac{E_f^2}{Z_s} \cos \theta_s.$$

$$\vec{S}_{in} = P_{in} + jQ_{in} = \vec{V} \vec{I}_a^*$$

$$= V \angle 0^\circ \left[\frac{V}{Z_s} \angle -\theta_s - \frac{E_f}{Z_s} \angle -(\theta_s + \delta) \right]^*$$

$$= V \angle 0^\circ \left[\frac{V}{Z_s} \angle \theta_s - \frac{E_f}{Z_s} \angle \theta_s + \delta \right]$$

$$\Rightarrow \vec{S}_{in} = \frac{V^2}{Z_s} \angle \theta_s - \frac{VE_f}{Z_s} \angle \theta_s + \delta \quad \text{--- (iv)}$$

$$\therefore P_{in} = \frac{V^2}{Z_s} \cos \theta_s - \frac{VE_f}{Z_s} \cos(\theta_s + \delta)$$

When $R_a = 0$.


$$\vec{Z}_s = X_s \& \theta_s = 90^\circ \therefore$$

$$\text{Generator :- } P_{out} = P_{dev} = P = \frac{VE_f}{X_s} \sin \delta.$$

$$\text{Motor :- } P_{dev} = P_{in} = P = \frac{VE_f}{X_s} \sin \delta = P_{(max)} \sin \delta$$

where, $P_{(max)} = \frac{VE_f}{X_s}$ at $\delta = 90^\circ$

□ POWER ANGLE CURVE / CHARACTERISTICS.



Reactive Power ; (Q). , $R_a = 0$.

$$\text{Generator ; } Q_{out} = \frac{V}{x_s} (E_f \cos \delta - V)$$

$$\text{Motor ; } Q_{in} = \frac{V}{x_s} (V - E_f \cos \delta)$$

GENERATOR

Case I :- $E_f \cos \delta = V$ i.e Normally excited Generator then
 $Q_{out} = 0$ & \therefore operating at unity P.F.

Case II :- When $E_f \cos \delta > V$ i.e overexcited Generator.
then, $Q_{out} = (+)ve$ i.e supplying lagging watts and
therefore operating at lagging P.f.

Case III :- When $E_f \cos \delta < V$ i.e underexcited generator.
then, $Q_{out} = (-)ve$ i.e supplying leading watts & therefore
operating at leading P.f.


MOTOR

Case I :- $E_f \cos \delta = V$ i.e Normally excited motor then
 $Q_{in} = 0$ & \therefore operating at unity P.f.

Case II :- $E_f \cos \delta > V$ i.e overexcited motor. then
 $Q_{in} = (-)ve$ i.e taking leading watts & therefore
operating at leading P.f.

Case III: $E_f \cos \delta < V$; i.e. underexcited motor then, $Q_{in} = (+)ve$ i.e. taking lagging watts & therefore operating at lagging P.f.


□ EFFECT OF CHANGE IN EXCITATION AT CONSTANT (KW) OUTPUT



FOR MOTOR

↑ Increasing kw.

↓ Locus of I_a at constant kw.



7 V AND INVERTED V CURVE.




Fig:- V CURVE.





Fig:- INVERTED V CURVE.

COMPOUNDING CURVE :- Compounding curve of a generator is a plot of the field current against armature current that is required to maintain a constant terminal voltage when constant p.f. load is varied.




Que:- A cylindrical rotor syn. generator with syn. reactance of 1.6 pu & negligible armature resistance is connected to infinite bus at rated voltage

(a) determine the excitation emf & power angle when it delivers full load current at 0.8 pf lag. Hence calculate

Voltage Reglⁿ of generator.

$$\begin{aligned} \text{Sol}^n:- E_f &= -\vec{V} + jI_a X_s \\ &= 1 \angle 0^\circ + j1.0 \angle -\cos^{-1}(0.8) \times 1.6 \\ &= 2.341 \angle 33.15^\circ \text{ pu.} \end{aligned}$$

$$\therefore \text{Voltage Regl}^n = \frac{E_f(\text{pu})}{V} - 1 = 1.34 \text{ pu} = 134\%$$



(b) with the excitation as in part A the gen. is made to operate at 0.95 lag. calculate the corresponding armature current and power angle.

$$\text{Sol}^n:- \Rightarrow 2.341 \angle \delta = 1 \angle 0^\circ + jI_a \angle -\cos^{-1}(0.95) \times 1.6$$

$$\Rightarrow 2.341 \angle \delta = 1 + 1.6 I_a \angle 71.81^\circ \quad \text{--- (A)}$$

$$\Rightarrow 2.341 \angle \delta = (1 + 1.6 I_a \cos 71.81^\circ) + j(1.6 I_a \sin 71.81^\circ)$$

Squaring & equating Magnitude

$$(2.341)^2 = (1)^2 + 2 \times 1 \times 1.6 I_a \cos 71.81^\circ + (1.6 I_a)^2$$

$$\Rightarrow (1.6)^2 I_a^2 + (2 \times 1.6 \cos 71.81^\circ) I_a + (1 - 2.341^2) = 0$$

Solving the quadratic equation.

$$\Rightarrow I_a = 1.1421 \text{ pu} \quad \text{or} \quad I_a = -1.5323 \text{ pu}$$

↓
Accept

↓
Rejected ($\because I_a$ is \rightarrow ve if we take this value it will become motor)

From eqⁿ (A)

$$\Rightarrow \delta = \angle [1 + 1.6 \times 1.1421 \angle 71.81^\circ]$$

$$\Rightarrow \delta = 47.87^\circ$$

c) With the excitation in part A determine the max^m power of p & the corresponding armature current & power factor?

$$\text{sol}^n: P_{\max} = \frac{V E_f}{X_s} \text{ at } \delta = 90^\circ$$

$$= \frac{1 \times 2.341}{1.6} = 1.463 \text{ pu.}$$

$$\boxed{I_a = \frac{\vec{E}_f - \vec{V}}{jX_s}} \Rightarrow I_a = \frac{2.341 \angle 90^\circ - 1 \angle 0^\circ}{j1.6}$$

$$\Rightarrow I_a = 1.591 \angle 23.13^\circ \text{ pu} \quad \therefore \text{pf} = \cos 23.13^\circ \text{ leading}$$

$$\text{pf} = 0.9196 \text{ leading } [\because V = 1 \angle 0^\circ]$$

d) If the steam $\frac{1}{2}$ of part A remains unchanged, calculate the excitation emf and power angle at which pf becomes 0.95 lagging.

$$\text{sol}^n: P = VI_a \cos \phi$$

$$\propto I_a \cos \phi$$

$$\Rightarrow I_{a2} \cos \phi_2 = I_{a1} \cos \phi_1$$


$$\Rightarrow I_{a2} \times 0.95 = 1.0 \times 0.8$$

$$\Rightarrow I_{a2} = 0.8421 \text{ pu.}$$

$$\vec{E}_{f2} = \vec{V} + j \vec{I}_{a2} X_s$$

$$= 1 \angle 0^\circ + j 0.8421 \angle -\cos^{-1}(0.95) \times 1.6$$

$$\vec{E}_{f2} = 1.9123 \angle 42.02^\circ \text{ pu}$$



(e) If the steam i/p of part a remains unchanged calculate the excitation emf and power angle at which power factor becomes 0.85 leading.

$$\text{Sol}^n: \because P = V I_a \cos \phi$$

$$\propto I_a \cos \phi$$

$$\Rightarrow I_{a2} \cos \phi_2 = I_{a1} \cos \phi_1$$

$$\Rightarrow I_{a2} \times 0.85 = 1.0 \times 0.8$$

$$\Rightarrow I_{a2} = 0.9412 \text{ pu.}$$

$$\Rightarrow \vec{E}_{f2} = \vec{V} + j \vec{I}_{a2} X_s$$

$$= 1 \angle 0^\circ + j 0.9421 \angle \cos^{-1}(0.85) \times 1.6$$

$$E_{f2} = 1.2966 \angle 80.83^\circ \text{ pu}$$

f) calculate the min^m excitation for the same steam i/p as in part A & determine corresponding armature current & p.f.

$$\text{Sol}^n: 0.8 = \frac{1.0 \times E_{f(\min)}}{1.6} \times \sin 90^\circ$$

$$\Rightarrow E_{f(\min)} = 1.28$$

gt P is not given.

$$P = \frac{V E_f}{X_s} \sin \delta$$

$$\propto E_f \sin \delta$$

$$= \text{constant}$$

$$E_{f(\min)} \sin 90^\circ = 2.341 \sin 33.15^\circ$$

$$\Rightarrow E_{f(\min)} = 1.28 \text{ pu.}$$

$$\vec{I}_{a2} = \frac{1.28 \angle 90^\circ - 1 \angle 0^\circ}{j1.6} = 0.0152 \angle 38^\circ \text{ pu.}$$

$$\therefore \text{p.f.} = \cos 38^\circ \text{ leading} = 0.788 \text{ leading.}$$

g) If the steam i/p of part A remains unchanged but the excitation is increased by 30% calculate the new armature current & p.f.

30%:-

$$\Rightarrow 0.8 = \frac{1.0 \times (1.3 \times 2.341)}{1.6} \sin \delta_2$$

$$\Rightarrow \delta_2 = 24.87^\circ$$

$$\text{OR } P = \frac{V E_f \sin \delta}{X_s}$$

$$\propto E_f \sin \delta$$

$$= \text{constant}$$


$$\therefore 1.3 E_{f1} \sin \delta_2 = E_{f1} \sin 33.15^\circ$$

$$\Rightarrow \delta_2 = 24.87^\circ$$

$$\Rightarrow \vec{I}_{a2} = \frac{1.3 \times 2.341 \angle 24.87^\circ - 1 \angle 0^\circ}{j1.6}$$

$$= 1.3607 \angle -53.99^\circ \text{ pu}$$

$$\therefore \text{p.f.} = \cos 53.99^\circ \text{ lag} = 0.5879 \text{ lag.}$$



h) For a power angle of 20° calculate the two possible values of excitation emf if the generator delivers 30% of full load current. Note the corresponding p.f. & power o/p?

Solⁿ:-


$$\Rightarrow E_f \angle 20^\circ = 1 \angle 0^\circ + j0.3 \angle \phi \times 1.6$$

$$\Rightarrow E_f \angle 20^\circ = 1 + 0.48 \angle 90^\circ + \phi$$

$$\Rightarrow 0.48 \angle 90^\circ + \phi = E_f \angle 20^\circ - 1$$

$$= (E_f \cos 20^\circ + j E_f \sin 20^\circ) - 1$$

$$= (E_f \cos 20^\circ - 1) + j (E_f \sin 20^\circ)$$



Squaring and equating magnitude.

$$\Rightarrow (0.48)^2 = E_f^2 - 2E_f \cos 20^\circ + 1$$

$$\Rightarrow E_f^2 - (2 \cos 20^\circ) E_f + (1 - 0.48^2) = 0$$

Solving the Quadratic eqⁿ

$$E_{f1} = 0.6029 \text{ pu} \quad \text{and} \quad E_{f2} = 1.2765 \text{ pu.}$$

Low E_f

$$\Rightarrow 90^\circ + \phi = \angle [0.6029 \angle 20^\circ - 1]$$

$$\Rightarrow 90^\circ + \phi = 154.56^\circ$$

$$\therefore \phi = 64.56^\circ \Rightarrow \text{pf} = \cos 64.56^\circ \text{ lead} = 0.4296 \text{ leading}$$

$$\therefore P = 1 \times 0.30 \times 0.4296 = 0.1289 \text{ pu.}$$

High E_f

$$\Rightarrow 90^\circ + \phi = \angle [1.2765 \angle 20^\circ - 1]$$



$$\Rightarrow 90^\circ + \phi = 68.44^\circ \Rightarrow \phi = -24.56^\circ$$

$$\text{pf} = \cos 24.56^\circ \text{ lag} = 0.9095 \text{ lag.}$$


$$\therefore P = 1 \times 0.30 \times 0.9095 = 0.2729 \text{ pu.}$$

□ SYNCHRONOUS COMPENSATOR.

$$Q_{in} = \frac{V}{X_s} (V - E_f)$$



Zero pf lag



Gen



$$Q_{out} = \frac{V}{X_s} (E_f \cos \delta - V)$$

when $\delta = 90^\circ$ or $E_f = 0$

$$Q_{out} = -\frac{V^2}{X_s}$$

$= -V^2 X_{SCR} \rightarrow$ line charging capability.

□ TRANSITION FROM GENERATOR ACTION TO MOTOR ACTION.






Fig: OVEREXCITED GENERATOR ON NO-LOAD:






Fig: OVEREXCITED GENERATOR WITH MECHANICAL LOAD ON SHAFT.






eg: OVEREXCITED MOTOR WITH MECHANICAL LOAD ON SHAFT

ex: A 3- ϕ star connected load takes 50A in current at 0.707 lagging p.f with 220 volts b/w the lines. A 3- ϕ star connected round rotor syn. motor, having a syn. reactance X_s of 1.27 Ω per phase is connected in parallel with the load. The power developed by motor is 33 kW at an power angle of 30°. Calculate the overall power factor of the motor & the load.

sol:-

$$S_{\text{load}} = \sqrt{3} \times 220 \times 50 \angle \cos^{-1}(0.707) \text{ VA}$$

$$= 19.053 \angle 45^\circ \text{ KVA}$$



$$\Rightarrow 33 \times 10^3 = \frac{220 \times E_{f(L-L)}}{1.27} \sin 30^\circ$$

$$\Rightarrow E_{f(L-L)} = 381 \text{ volts.}$$

$$Q_{\text{motor}} = \frac{220}{1.27} (220 - 381 \cos 30^\circ)$$

$$\Rightarrow Q_{\text{motor}} = -19.047 \text{ KVAR.}$$

$$\therefore \vec{S}_{\text{motor}} = (33 - j19.047) \text{ KVA.}$$

$$\vec{S}_{\text{in}} = \vec{S}_{\text{load}} + \vec{S}_{\text{motor}}$$

$$\vec{S}_{\text{in}} = 19.058 \angle 45^\circ + (33 - j19.047)$$

$$\vec{S}_{\text{in}} = 46.806 \angle -6.84^\circ \text{ KVA}$$

$$\text{Overall p.f.} = \cos 6.84^\circ \text{ lead} = 0.9929 \text{ lead.}$$

Pr 5.90 P.S. BH

Que: A 230 V 4 pole 50 Hz star connected syn motor has $R_a + jX_s = 0.6 + j3 \Omega$ per phase. It's field current so adjusted that the motor draws 10 A at unity p.f from rated voltage source. Now with the field current unchange the load on the motor is increased till it draws 40 Amp from the supply. Find the torque developed & New p.f.

$$\begin{aligned} \text{At unity pf} \\ \vec{S}_f := \vec{E}_f &= \frac{230}{\sqrt{3}} \angle 0^\circ - 10 \angle 0^\circ \times (0.6 + j3) \\ &= 130.29 \angle -13.31^\circ \text{ VOLTS (L-N)} \end{aligned}$$

When load is increased \rightarrow Motor becomes underexcited & operates at lagging pf.

$$\Rightarrow 130.29 \angle -\delta_2 = \frac{230}{\sqrt{3}} \angle 0^\circ - 40 \angle -\phi_2 \times 3.06 \angle 78.69^\circ$$

$$\begin{aligned} \Rightarrow 130.29 \angle -\delta_2 &= 132.79 - 122.4 \angle 78.69^\circ - \phi_2 \\ &= [132.79 - 122.4 \cos(78.69^\circ - \phi_2)] - j [122.4 \sin(78.69^\circ - \phi_2)] \end{aligned}$$

Squaring & equating magnitudes.

$$(130.29)^2 = (132.79)^2 - 2 \times 132.79 \times 122.4 \cos(78.69^\circ - \phi_2) + (122.4)^2$$

$$\Rightarrow = \cos(78.69^\circ - \phi_2) = 0.4811$$

$$\Rightarrow \phi_2 = 17.45^\circ$$


$$\begin{aligned} \text{New pf} &= \cos 17.45^\circ \text{ Lag.} \\ &= 0.954 \text{ lagging.} \end{aligned}$$

$$P_{\text{dev}} = P_{\text{in}} - \text{Armature copper loss.}$$

$$\begin{aligned} &= \sqrt{3} \times 230 \times 40 \times 0.954 - 3 \times 40^2 \times 0.6 \\ &= 12321.86 \text{ watts.} \end{aligned}$$

$$\tau_{\text{dev}} = \frac{P_{\text{dev}}}{\omega_{\text{sm}}} = \frac{12321.86}{\frac{2}{P} \times (2\pi f)} = \frac{12321.86}{\frac{2}{4} \times 2\pi \times 50} = 78.44 \text{ s}$$

▣ PARALLEL OPERATION OF SYNCHRONOUS GENERATOR.



$$\text{Governor Reg.} = \frac{52 \text{ Hz} - 50 \text{ Hz}}{50 \text{ Hz}}$$

$$\text{Drop} = 0.04 = 4\%$$

$$\text{OR' DROP} = \frac{52 \text{ Hz} - 50 \text{ Hz}}{200 \text{ MW}}$$


$$= \frac{2 \text{ Hz}}{200 \text{ MW}} = 0.01 \text{ Hz/MW}$$

Speeder Gear is also known as control gear or speed changer, is a device that simply shifts the

Governor characteristics parallel to itself on being given a raise or lower command.

Que:- Two identical 2000 kW, ^{50 Hz.} alternators operates in parallel, the Governor of first m/c is such that ^{the} frequency rises uniformly from 50 Hz on full load to 52 Hz on no load. The corresponding uniform speed rise of the 2nd m/c is 50 Hz to 52.5 Hz.

(a) If each m/c is fully loaded at rated frequency, what will be load on each m/c when the total load is 2400 kW.



For m/c-A

$$\Rightarrow \frac{P_A}{2000} = \frac{52 - f}{52 - 50} \quad \text{--- (A)}$$

for m/c B.

$$\Rightarrow \frac{2400 - P_A}{2000} = \frac{52.5 - f}{52.5 - 50} \quad \text{--- (B)}$$

Solving eq^s (A) & (B) we get

$$P_A = 1111.11 \text{ kW}, \quad f = 50.89 \text{ Hz.}$$

$$P_B = 2400 - 1111.11 \text{ kW} = 1288.89 \text{ kW}$$


(b) Calculate the max^m load at which one of the m/c would become unloaded.

$$\text{Sol}^n:- \frac{P_L}{2000} = \frac{52.5 - 52}{52.5 - 50}$$

$$\Rightarrow P_L = 400 \text{ kW.}$$

Que:- Two identical 2000 kW alternators operate in parallel. The governor of 1st m/c is such that the frequency drops uniformly from 50 Hz on no load to 48 Hz on full load. The corresponding uniform frequency drop of the second m/c is from 50 Hz to 47.5 Hz.

(a) How will the two m/c share the load of 3000 kW.



$\frac{P_A}{2000} = \frac{50 - f}{50 - 48} \quad \text{--- (A)}$	$\frac{3000 - P_A}{2000} = \frac{50 - f}{50 - 47.5} \quad \text{--- (B)}$
--	---

Solving eqⁿ (A) & (B) we get

$$\Rightarrow P_A = 1666.67 \text{ kW, } f = 48.33 \text{ Hz.}$$

$$P_B = 3000 - 1666.67 = 1333.33 \text{ kW.}$$

(b) What is the max^m load that can be delivered without overloading either m/c.

$$\frac{P'_B}{2000} = \frac{50-48}{30-47.5} \Rightarrow P'_B = 1600 \text{ kW.}$$

∴ Max^m load = 3600 kW.

□ SYNCHRONISATION.


condition to be satisfied Before Synchronisation.

- 1) Equal frequency.
- 2) Equal voltage.
- 3) Same phase sequence in 3- ϕ m/c.
- 4) Zero phase displacement at instant of synchronisation.



Additional.

- 5) Same waveform.

□ DARK LAMP METHOD.




□ ROTATING LAMP METHOD. OR' DARK & BRIGHT LAMP METHOD.
'OR'.
SIEMENS & HALSKE METHOD.




L₁ : DARK
L₂, L₃ : EQUALITY
BRIGHT

L₁ : a-R.
L₂ : b-B.
L₃ : c-Y.



□ SYNCHROSCOPE



Synchronisation by Synchroscope method.

Step I :- Match the frequency of the incoming m/c with that of running m/c. It is recommended that the incoming frequency be kept slightly higher.

Step II:- Match the incoming voltage with the running voltage. It is again recommended that the incoming voltage be kept slightly higher.

Step III:- Switch ON the Synchroscope & the check "Synchronisation relay" if available. Switch OFF anti motoring protection if provided.

Step IV:- Find control/Tune incoming frequency so that the Synchroscope pointer moves very slowly in the fast direction. When the Synchroscope pointer reaches at 11 o'clock position give a command to the breaker switch to close the breaker. It is expected that the breaker contact would actually closed at 12 o'clock position, a position that represent zero phase displacement.

Step V:- Switch OFF the Synchroscope & check Synchronisation relay. Take some initial load as recommended and adjust excitation for desired P.f.

Step VI:- Switch ON the anti motoring protection when adequate recommended load have been taken on the set.

Ques:- A Synch. m/c is synchronised with an infinite Bus at rated voltage & the steam i/p to prime mover is increased till Syn. m/c started operating at rated kVA. The m/c has Syn. Impedance $Z_s = 0.02 + j0.8$ pu. Determine the operating pf of the alternator & its load angle.

solⁿ:-

$$Z_s = (0.02 + j0.8) \text{ pu.}$$

$$\Rightarrow X_s = 0.80025 \angle 88.57^\circ \text{ pu.}$$

$$\Rightarrow \angle \delta = \angle 0^\circ + \angle \phi \times 0.80025 \angle 88.57^\circ$$

$$\Rightarrow \angle \delta = 1 + 0.80025 \angle 88.57^\circ + \phi$$

$$\Rightarrow 0.80025 \angle 88.57^\circ + \phi = \angle \delta - 1 \quad \text{--- (A)}$$

$$\Rightarrow 0.80025 \angle 88.57^\circ + \phi = (\cos \delta - 1) + j(\sin \delta)$$

Squaring & equating magnitude.

case of zero
V.R. Regulation

$$\Rightarrow (0.80025)^2 = \cos^2 \delta - 2 \cos \delta + \sin^2 \delta + 1$$

$$\Rightarrow (0.80025)^2 = 2 - 2 \cos \delta$$

$$\Rightarrow \delta = 47.17^\circ$$

$$\Rightarrow 88.57^\circ + \phi = \angle [1 \angle 47.17^\circ - 1] = 113.57^\circ$$

$$\Rightarrow \phi = 25.02^\circ$$

$$\text{P.f.} = \cos 25.02^\circ \text{ leading} = 0.9062 \text{ leading.}$$

□ STARTING OF SYNCHRONOUS MOTOR.

When the stator wdg of an ordinary syn. motor is switched ON the stator flux rotates at syn. speed in the direction of leading phase axis to lagging phase axis.

An excited rotor is unable to overcome its inertia & catch up with the fast revolving stator field & consequently simply vibrates

Syn. motor is not self starting.


Hence a special measures have to be undertaken to start Syn. motor.

ON LOAD START

On load start or load start is obtained by Variable frequency starting or damper wdg starting.

In variable frequency starting the initial supply frequency is kept very low but keeping $\frac{V}{f}$ ratio constant to prevent overfluxing. At low frequency the stator flux moves slowly and therefore the excited rotor is easily able to overcome its inertia & gets magnetically locked with the stator field. The frequency is gradually increased keeping $\frac{V}{f}$ ratio constant until rated frequency & rated voltage are reached.

The other method for ON Load start is damper winding starting :- It consists of conductors embedded in the pole face that run along the length of poles & are short ckted at both ends by short ckting rings thus making a structure similar to the squirrel cage of induction motor.



When the stator wdg of such a motor is switched ON, the rotor accelerates its load due to induction torque created by damper wdg. When the rotor reaches normal speed which is slightly

below syn. speed the rotor (field) wdg is excited. The rotor poles get magnetically locked with the stator pole because the relative speed happens to be very low. Subsequently the rotor continues to rotate at syn. speed and the m/c becomes syn. motor.

At syn. speed the damper torque becomes zero and the motor continues to run only with excitation power however, if there is a departure from synchronism during operation the damper wdg develop the lenz law current to restore syn. speed and therefore prevent oscillation of the rotor about its mean stable position, a phenomenon called HUNTING. It is recommended that a resistor having resistance 7-10 times the resistance of field wdg be connected across the field wdg before the switching on stator wdg. This is done to ensure that very high induced voltage in the field wdg at start doesn't damage the field ckt insulation.

However if such a resistor is not available then the field wdg should be short ckt at start. This has an added advantage that the field wdg also contributes towards accelerating torque.

Such a motor is called / Synchronous motor. 10

NO - LOAD STARTING

No load start is obtained by auxiliary motor starting. The auxiliary motor also called pony motor may be an induction motor or D.C. motor.

If the auxiliary motor is an I.M then its no. of poles are equal to the no. of poles of the syn. motor. However if no. of poles of syn. motor is large then the no. of poles of auxiliary I.M. may be kept less by 2 poles.

If the auxiliary I.M. has two poles less than when the auxiliary motor is switched on it accelerates the rotor of the syn. motor in the same direction ^{as the} prospective stator field and takes it above the syn. speed of the syn. motor. At this stage the auxiliary I.M. is removed & then the stator wdg of sync. motor is switched on. As the speed drops & approaches sync. speed of the sync. motor the field wdg is excited. By the time the field current builds up the rotor is near syn. speed & the rotor poles get easily magnetically locked with the stator field.

Subsequently the motor continues to run as syn. motor & mechanical load than applied at shaft.

If the auxiliary I.M. has the same no. of poles as the sync. motor than it is able to accelerate the rotor of syn. motor in the prospective direction of stator flux to a speed i.e. less than the sync. speed of the sync. motor.

At this stage the stator wdg of syn. motor is switched on. Subsequently the field wdg of the syn. motor is excited. Since the relative speed b/w the rotor & the stator field is low the rotor magnetic poles get easily locked with the stator field. Subsequently the motor continues to run as syn. motor. The auxiliary motor is then removed and mechanical load on the shaft than may be applied.


If the rotor wdg is excited before the stator wdg excited than synchronisation would become necessary.

If the stator wdg is excited right from start than high induced voltage in the field wdg would damage the field ckt insulation.

If the auxiliary motor is a d.c. motor and there is a provision of speed control then it is recommended to sync. m/c as a generator.

Subsequently the auxiliary dc motor may be removed & the m/c would then become a syn. motor.

However if speed control is not possible than the same method should be adopted as with auxiliary i.m. starting.





Application Guide

□ SYNCHRONISING POWER

Two identical M/c on NO load.

$$\sin \frac{\Delta\delta}{2} = \frac{I_s X_s}{E_f}$$



Synchronising power, $P_s = \Delta P = E_f I_s \cos \frac{\Delta\delta}{2}$

$$= E_f \left[\frac{E_f}{X_s} \sin \frac{\Delta\delta}{2} \right] \cos \frac{\Delta\delta}{2}$$

$$= \frac{E_f^2}{2X_s} \left(2 \sin \frac{\Delta\delta}{2} \cos \frac{\Delta\delta}{2} \right)$$

$$P_s = \Delta P = \frac{E_f^2}{2X_s} \sin(\Delta\delta)$$



Since $\Delta\delta$ is small.

$\sin(\Delta\delta) \approx \Delta\delta$ electrical rad.

Synchronising power coefficient, $S_p \triangleq \frac{\Delta P_s}{(\Delta\delta)} = \frac{\Delta P}{\Delta\delta}$

$$S_p = \frac{E_f^2}{2X_s} \text{ Watt per elect rad.}$$

M/C CONNECTED TO INFINITE BUS.



$$\text{Synchronising Power, } P_s = \Delta P = \frac{VE_f}{X_s} [\sin(\delta + \Delta\delta) - \sin\delta]$$

$$\Rightarrow P_s = \Delta P = \frac{VE_f}{X_s} [\sin\delta \cdot \cos(\Delta\delta) + \cos\delta \sin(\Delta\delta) - \sin\delta]$$

$$\Rightarrow P_s = \frac{VE_f}{X_s} [\cos\delta \sin(\Delta\delta) - \sin\delta \{1 - \cos(\Delta\delta)\}]$$

$$\Rightarrow P_s = \frac{VE_f}{X_s} [\cos\delta \sin(\Delta\delta) - \sin\delta \times 2 \sin^2 \frac{(\Delta\delta)}{2}]$$

$\therefore \sin \frac{\Delta\delta}{2}$ is small, $\sin^2 \frac{\Delta\delta}{2} \approx 0$.

$$\therefore P_s = \Delta P = \frac{VE_f}{X_s} \times \cos\delta \sin(\Delta\delta) \text{ watts.}$$

\therefore Since $(\Delta\delta)$ is small

$\sin(\Delta\delta) \approx (\Delta\delta)$ elect rad.

$$\text{Then } P_s \approx \Delta P = \frac{VE_f}{X_s} \cos\delta \times (\Delta\delta) \text{ watts}$$

Synchronizing power coefficient, $S_p = \frac{P_s}{(\Delta\delta)} = \frac{\Delta P}{\Delta\delta}$


$$= \frac{VE_f}{X_s} \cos\delta \text{ W per elect rad.}$$

$$S_p = P_{(max)} \cos\delta$$

$$P = P_{(max)} \sin\delta$$

$$\therefore \frac{dP}{d\delta} = P_{(max)} \cos\delta \Big|_{\delta=0}$$

$$S_p = P_{(max)} \text{ at } \delta = 0^\circ \text{ (at no load)}$$



This is the reason that it is recommended to synchronise sync generator on no load.

Linearised Analysis.


$$P = P_{(max)} \sin\delta$$

In the range

$$-30^\circ \leq \delta \leq +30^\circ$$

$$\sin\delta \approx \delta \text{ elect rad.}$$

$$\text{Then } P = P_{(max)} \times \delta$$



This is the reason that it is recommended to operate syn. m/c with a power angle limited to 30° .

Que:- Calculate the Synchronising coefficient in kW & Nm for mechanical degree at full load for 50 Hz 1000 kVA 0.8 pf lag 6.6 kV, 8 pole Y connected syn. Generator of a negligible resistance & syn. reactance of 0.8 pu.

$$\text{Sol}^n:- \vec{E}_f = 1 \angle 0^\circ + j \sqrt{-\cos^{-1}(0.8)} \times 0.8$$

$$= 1.6125 \angle 23.39^\circ \text{ pu.}$$

$$\Rightarrow S_p = \frac{VE_f}{X_s} \cos \delta \Big|_{\delta = 23.39^\circ}$$

$$= \frac{1.0 \times 1.6125 \cos 23.39^\circ}{0.8}$$

$$= 1.85 \text{ pu per elect rad.}$$

$$\Rightarrow S_p = 1.85 \times 1000 \text{ kW per elect rad.}$$

$$= 1850 \text{ kW per elect rad.}$$

$$S_p = 1850 \times \frac{1}{180^\circ} \text{ kW per elect degree.}$$


$$= 32.289 \text{ kW per elect degree.}$$

$$\Rightarrow S_p = 32.289 \times \frac{8}{2} \text{ kW per mech degree.}$$

$$\Rightarrow S_p = 129.156 \text{ kW per mech degree.}$$

$$\text{Syn. Torque Coefficient} = \frac{129.156 \times 10^3}{\frac{2}{8} \times 2\pi \times 50} = 1644.45 \text{ Nm per mech degree.}$$

□ SALIENT POLE M/C - BLONDEL'S TWO REACTION THEORY.



- * If saliency neglected $X_s = X_d$.
- * The initial challenge is locating the q-axis.

$$I_q = I_a \cos \psi$$

$$I_d = I_a \sin \psi$$

$$\vec{E}' = \vec{V} + j I_a X_q$$

Then: $E_f = E' + I_d (X_d - X_q)$

OR $E_f = V \cos \delta + I_d X_d$

$$\Rightarrow P = V \cos \delta \times I_q + V \sin \delta \times I_d$$


$$= \frac{V \cos \delta}{X_q} \times I_q X_q + \frac{V \sin \delta}{X_d} \times I_d X_d$$

$$= \frac{V \cos \delta}{X_q} \times V \sin \delta + \frac{V \sin \delta}{X_d} (E_f - V \cos \delta)$$

$$= \frac{V E_f \sin \delta}{X_d} + \frac{V^2}{2} (2 \sin \delta \cos \delta) \left(\frac{1}{X_q} - \frac{1}{X_d} \right)$$

$$= \frac{V E_f \sin \delta}{X_d} + \frac{V^2}{2} \left(\frac{1}{X_q} - \frac{1}{X_d} \right) \sin 2\delta$$

Excitation Power
Reluctance Power.



Que:- Reactances X_d and X_q of a Salient pole Syn. Generator are 1 pu and 0.6 pu respectively. The armature resistance is negligible (a) calculate Excitation Voltage & power angle when generator delivers rated kVA at 0.8 pf lagging ^{current} & rated terminal voltage.

Sol:- a) $\vec{E}' = 1 \angle 0^\circ + j 1 \angle -\cos^{-1}(0.8) \times 0.6$
 $= 1.422 \angle 19.44^\circ$ pu.

$\therefore I_d = I_a \sin \psi$

$= 1.0 \sin(\delta + \phi)$

$= 1.0 \sin(19.44 + 36.87^\circ) \quad \because \cos^{-1}(0.8) = 36.87^\circ$

$= 1.0 \sin 56.31^\circ$

$= 0.8321$ pu.

$E_f = E' + I_d (X_d - X_q) \quad \text{OR} \quad V \cos \delta + I_d X_d$

$\Rightarrow E_f = 1.775$ pu.

b) calculate Excitation Voltage & power angle neglecting saliency for same operating condⁿ as in part (a).

Solⁿ:- Neglecting saliency, $X_d = X_q$. i.e. $X_s = X_d$

$$\begin{aligned} \therefore E_f(\text{cylindrical}) &= 1 \angle 0^\circ + j1 \frac{-\cos^{-1}(0.8) \times 1}{1} \\ &= 1.7889 \angle 28.57^\circ \text{ pu.} \end{aligned}$$

(c) With the steam $\frac{2}{p}$ in part (a) remaining constant the power angle is 36° . Calculate the excitation emf, armature reaction current & power factor.

Solⁿ:- $\Rightarrow P = 1.0 \times 1.0 \times 0.8$
 $= 0.8 \text{ pu.}$

$$\Rightarrow 0.8 = \frac{1 \times E_f \sin 36^\circ}{1} + \frac{(1)^2}{2} \left(\frac{1}{0.6} - \frac{1}{5} \right) \sin 2 \times 36^\circ$$

$$\Rightarrow E_f = 1.0226 \text{ pu.}$$

Here $I_d X_d = E_f - V \cos \delta$.

$$\Rightarrow I_d = 0.1566 \text{ p.u.}$$

$$\Rightarrow E' = E_f = I_d (X_d - X_q)$$

$$\frac{0.8}{V \cos \delta} + I_d X_q$$

$$\Rightarrow E' = 0.96 \text{ pu.}$$

$$\Rightarrow \vec{I}_a = \frac{\vec{E}' - \vec{V}}{jX_q} = \frac{0.96 \angle 30^\circ - 1 \angle 0^\circ}{j0.6}$$

$$\Rightarrow \vec{I}_a = 0.8479 \angle 19.36^\circ \text{ pu.}$$

$$\text{pf} = \cos 19.36^\circ \text{ Leading} = 0.9435 \text{ leading.}$$

(d) Calculate max^m power o/p of the salient pole of gen. with the excitation of part (A) also calculate corresponding armature current & p.f.

$$\text{Sol}^n := \frac{dP}{d\delta} = 0.$$

$$\Rightarrow P = \frac{1 \times 1.775}{1} \sin\delta + \frac{(1)^2}{2} \left(\frac{1}{0.6} - \frac{1}{1} \right) \sin 2\delta$$

$$= 1.775 \sin\delta + \frac{1}{3} \sin 2\delta$$

For max^m power

$$\Rightarrow \frac{dP}{d\delta} = 0 \quad \text{i.e.} \quad 1.775 \cos\delta + \frac{2}{3} \cos 2\delta = 0$$

$$\Rightarrow 1.775 \cos\delta + \frac{2}{3} \cos 2\delta = 0.$$

$$\Rightarrow 1.775 \cos\delta + \frac{2}{3} (2 \cos^2\delta - 1) = 0$$

Solving the quadratic eqⁿ we get

$$\Rightarrow \cos\delta = 0.3055 \Rightarrow \delta = 72.21^\circ$$

$$\therefore P_{\max} = 1.775 \sin 72.21^\circ + \frac{1}{3} \sin(2 \times 72.21^\circ)$$

$$= 1.6901 + 0.1939$$

$$= 1.884 \text{ p.u.}$$

$$\Rightarrow I_d = \frac{E_f - V \cos\delta}{X_d} = \frac{1.775 - 1 \times \cos 72.21^\circ}{1} = 1.4695 \text{ p.u.}$$

$$\Rightarrow E' = E_f - I_d (X_d - X_q) \quad \text{or} \quad V \cos\delta + I_d X_q = 1.1872 \text{ p.u.}$$

$$\Rightarrow I_a = \frac{E' - V}{jX_q} = \frac{1.1872 \angle 72.21^\circ - 1 \angle 0^\circ}{j0.6} = 2.1628 \angle 29.41^\circ$$

$$\therefore \text{pf} = \cos 29.41^\circ \text{ leading} = 0.8711 \text{ leading.}$$

e) Calculate the minimum excitation E_{mf} for the steam p/p as in part (a) & hence determine armature current &

P.f.!

$$\text{Sol}^n := 0.8 = \frac{1 \times E_f}{1} \sin\delta + \frac{(1)^2}{2} \left(\frac{1}{0.6} - \frac{1}{1} \right) \sin 2\delta$$

$$\Rightarrow E_f = 0.8 \csc\delta - \frac{2}{3} \cos\delta$$

For E_f to be min^m.

$$\Rightarrow \frac{d}{d\delta} (E_f) = 0$$

$$\Rightarrow 0.8 (-\operatorname{cosec} \delta \cot \delta) - \frac{2}{3} (-\sin \delta) = 0$$

$$\Rightarrow 0.8 \operatorname{cosec} \delta \cot \delta = \frac{2}{3} \sin \delta$$

$$\Rightarrow \operatorname{cosec}^2 \delta \cot \delta = 0.8334$$

$$\Rightarrow (1 + \cot^2 \delta) \cot \delta = 0.8334$$

$$\Rightarrow \cot^3 \delta + \cot \delta - 0.8334 = 0$$

\Rightarrow Solving the cubic eqⁿ

$$\Rightarrow \cot \delta = 0.6083 \Rightarrow \delta = 58.69^\circ$$

$$\therefore E_f(\min) = 0.8 \operatorname{cosec} 58.69^\circ - \frac{2}{3} \cos 58.69^\circ$$

$$= 0.5899 \text{ pu.}$$

$$\Rightarrow I_d = \frac{0.5899 - 0.5197}{1.0} = 0.0702 \text{ pu.}$$

$$\Rightarrow E' = E_f - I_d (x_d - x_q) \text{ or } V \cos \delta + I_d x_q$$

$$\Rightarrow E' = 0.5618 \text{ pu.}$$

$$\therefore \vec{I}_d = \frac{0.5618 \angle 58.69^\circ - 1 \angle 0^\circ}{j0.6} = 1.4257 \angle 55.87^\circ \text{ pu.}$$

$$\therefore \text{pf} = \cos 55.87^\circ \text{ lead} = 0.5611 \text{ lead.}$$

(f) Determine the max^m power of the salient pole generator when it loses excitation while still connected to infinite bus. what is corresponding armature current & p.f.

$$\text{Sol}^n \Rightarrow E_f = 0 \Rightarrow P = 0 \neq \frac{1}{3} \sin 2\delta$$

$$\therefore P_{\max} = \frac{1}{3} \text{ at } \delta = 45^\circ$$

$$\Rightarrow I_d = \frac{V \cos \delta}{X_d}$$

$$\Rightarrow I_d = \frac{1 \times \cos 45^\circ}{1}$$

$$\Rightarrow I_d = 0.7071 \text{ pu.}$$

$$\Rightarrow E' = E_f + I_d (X_d - X_q)$$


or

$$V \cos \delta - I_d X_q$$

$$\Rightarrow E' = 0.2828 \text{ pu.}$$

$$\Rightarrow I_a = \frac{0.2828 \angle 45^\circ - j \angle 0^\circ}{j 0.6} = 1.3744 \angle 75.97^\circ \text{ pu}$$

$$\therefore \text{pf} = \cos 75.97^\circ = 0.2424 \text{ leading.}$$



g) For a power angle of 15° calculate the two possible value of Excitation emf if the generator delivers 60% of full load current. Determine corresponding pf & Power osp.

$$\text{SOL}^n :- I_q X_q = V \sin \delta \text{ (Always)}$$

$$\therefore I_q = \frac{1.0 \sin 15^\circ}{0.6} = 0.4314 \text{ pu.}$$


$$I_d = \sqrt{(I_a)^2 - (I_q)^2} = 0.417 \text{ pu.}$$

$$\text{Then, } E_{f(1)} = V \cos \delta - I_d X_d = 0.5489 \text{ pu.}$$

$$E_{f(2)} = V \cos \delta + I_d X_d = 1.3829 \text{ pu.}$$

$$E'_{(1)} = E_{f(1)} + I_d (X_d - X_q) \text{ or } E'_{(1)} = V \cos \delta - I_d X_q = 0.7157 \text{ pu}$$

$$E'_{(2)} = E_{f(2)} - I_d (X_d - X_q) \text{ or } V \cos \delta + I_d X_q = 1.2161 \text{ pu.}$$



$$\vec{I}_{a(1)} = \frac{E_{(1)} - \vec{V}}{jX_q} = \frac{0.1157 \angle 15^\circ - 1 \angle 0^\circ}{j0.6}$$

$$= 0.6 \angle 59.03^\circ \text{ pu}$$

$$\therefore \text{pf} = \cos 59.03^\circ = 0.5146 \text{ leading}$$

$$P = 1.0 \times 0.6 \times 0.5146 = 0.3088 \text{ pu}$$


At high Excitation

$$\vec{I}_{a(2)} = \frac{\vec{E}'_{(2)} - \vec{V}}{jX_q} = \frac{1.2161 \angle 15^\circ - 1 \angle 0^\circ}{j0.6}$$

$$= 0.6 \angle -29.03^\circ \text{ pu} \quad \therefore \text{pf} = \cos 29.03^\circ = 0.8744 \text{ lag}$$

$$\Rightarrow P = 1 \times 0.6 \times 0.8744 = 0.5246 \text{ pu}$$

□ UNDER EXCITED GENERATOR (PF lead)



$$P = VI_R \cos \phi$$

$$= V I_a \cos(\psi + \delta)$$

$$= V I_a (\cos \psi \cdot \cos \delta - \sin \psi \cdot \sin \delta)$$

$$= V \cos \delta (I_a \cos \psi) - V \sin \delta (I_a \sin \psi)$$


$$\Rightarrow P = V \cos \delta I_q - V \sin \delta I_d$$

$$= \frac{V \cos \delta}{X_q} \times I_q X_q - \frac{V \sin \delta}{X_d} \times I_d X_d$$


$$= \frac{V \cos \delta}{X_q} \times (V \sin \delta) - \frac{V \sin \delta}{X_d} (V \cos \delta - E_f)$$

$$= \frac{V E_f}{X_d} \sin \delta + \frac{V^2}{2} \left(\frac{1}{X_q} - \frac{1}{X_d} \right) \sin 2\delta.$$



II OVER EXCITED MOTOR. (PF lead)



I UNDER EXCITED MOTOR (lag pf)




□ DETERMINATION OF X_d & X_q BY SLIP TEST.



Min^m current
 Max^m voltage
 at $V_f (o.c) = 0$ X_d

$$\Rightarrow X_d = \frac{\text{Max}^m \text{ voltage}}{\text{Min}^m \text{ current}}$$



Max^m current
 X_q Min^m voltage



$$X_q = \frac{\text{Min}^m \text{ voltage}}{\text{Max}^m \text{ current}}$$

at $V_f (o.c) = \text{peak}$


VARIATION FREQUENCY = 2 x SLIP TEST

□ CONSTANT FLUX LINKAGE THEOREM.

In the closed ckt having no resistance or voltage source, the flux linkage can't be changed.



□ SYMMETRICAL SHORT CKT AT THE TERMINALS OF AN UNLOADED SYNCH. GENERATOR.



Subtransient Reactance, $X_d'' = \frac{E_f}{(0a/\sqrt{2})} \approx 0.10 \text{ to } 0.15 \approx X_l$

Transient Reactance, $X_d' = \frac{E_f}{0b/\sqrt{2}} \approx 0.30 \text{ to } 0.35 \text{ pu.}$

Synchronous Reactance $X_d = \frac{E_f}{0c/\sqrt{2}} \approx 1.0 \text{ pu to } 2.0 \text{ pu}$

- * The phase that has zero initial flux linkage is being considered after a sudden symmetrical short circuit occurs at the terminals of unloaded alternator.
- * The Armature current on short circuit is zero pf lagging current and therefore has a directly demagnetising armature $\propto I_a^2$ on the main field (along the direct axis)
- * The flux linkage of the field wdg & the damper wdg would be reduced due to armature $\propto I_a^2$ effect.
- * A/c to constant flux linkage theorem the flux linkage of a closed circuit having no resistance or voltage source can't change.


Hence the damper wdg as well as field wdg induced current that try to maintain their flux linkage. This is equivalent addⁿ excitation to the field resulting into a very high current in the first 3-5 cycle this period is known as subtransient period & current is known as subtransient current that decays with damper/decay time constant. The associated reactance is known as subtransient reactance used for fault studies (fault)

Subsequently the current in the armature is controlled due to sudden increase in the field current & this current may stay for 10-20 cycle.

This current decays w.r to time constant of the field ckt. This period is known as transient period & the current is known as transient current. The associated reactance is known as transient reactance & is used for transient stability studies.



When the transient periods end steady state follows & the associated reactance is called synchronous reactance & used for normal operation studies.

In any armature phase that has some initial flux linkages, the armature current contains a dc offset that decays with armature time constant.



The current in the field wdg on symmetrical short ckt rises abruptly & decays with a dc offset. The envelop of field current decays with armature time constant whereas axis of symmetry that happens to be dc offset decays with field time constant.

3- ϕ INDUCTION MOTOR.



Rotor phase sequence = $\alpha Y B$.

* Slip, $s = \frac{N_s - N}{N_s}$

* Speed of stator flux w.r.t stator body, $N_s = \frac{120f}{P}$

* Speed of rotor body = N

* Speed of stator flux w.r.t rotor body = $N_s - N = sN_s$

Rotor frequency, $f_r = \frac{P(N_s - N)}{120}$

$= \frac{P(sN_s)}{120}$

$f_r = sf$

* Speed of rotor flux w.r.t rotor body = $\frac{120f_r}{P}$

$= \frac{120(sf)}{P}$



$= sN_s$

* Speed of rotor flux w.r.t stator body (i.e. in space) = $N + sN_s = N_s$

* Speed of rotor flux w.r.t stator flux = $N_s - N_s = 0$

□ CONDITION TO BE SATISFIED FOR PRODUCTION OF STEADY STATE TORQUE IN ROTATING ELECTRICAL M/C.

1. The stator flux & rotor flux should be constant in amplitude.
2. The stator flux & rotor flux should be stationary w.r.t. each other.
3. There should be an angular displacement b/w them.



ROTOR FED I.M (INVERTED I.M)

Stator phase Sequence - XYZ.

□ EQUIVALENT CIRCUIT.

$$\text{Flux per pole} \Rightarrow \Phi = \left(\frac{2}{\pi} B_m \right) \times \frac{\pi DL}{P}$$

$$\text{Stator Produced emf, } E_1 = K_{w1} \times \sqrt{2} \pi f \Phi N_1$$

$$\text{Rotor Induced emf at standstill, } E_2 = K_{w2} \times \sqrt{2} \pi f \Phi N_2$$

where N_2 = No. of rotor turns per phase

N_1 = No. of stator " " "

$$\frac{N_1}{N_2} = a$$

where N_{e1} = No. of Effective stator Turn Per phase

N_{e2} = No. of Effective rotor Turn Per phase

Called reduction factor or Transformation Ratio.

MMF Balance on load

$$N_{e1} \vec{I}_1 - N_{e2} \vec{I}_2 = N_{e1} \vec{I}_0$$

$$\Rightarrow \vec{I}_1 = \frac{\vec{I}_2}{a} + \vec{I}_0$$

$$\vec{I}_1 = \vec{I}_2 + \vec{I}_0$$





Fig: STATOR EQUIVALENT CKT

* ROTOR EQUIVALENT CKT


A) At Standstill.



At stator frequency

X_2 = Rotor leakage Reactance at standstill

(B) In Motion At slip 's'



Rotor Eq. ckt at rotor freq.

$$s\vec{E}_2 = \vec{I}_2 R_2 + j \vec{I}_2 (sX_2)$$

$$I_2 = \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}} \quad \angle -\tan^{-1} \frac{sX_2}{R_2}$$

Rotor $\frac{2}{p}$ power = $(I_2)^2 \times R_2$ (Rotor copper loss).


$$sE_2 = \vec{I}_2 R_2 + j\vec{I}_2 (sX_2)$$

Dividing by s .

$$\vec{E}_2 = \vec{I}_2 \frac{R_2}{s} + j\vec{I}_2 X_2$$

$$I_2 = \frac{E_2}{\frac{R_2}{s} + jX_2}$$

$$= \frac{E_2}{\sqrt{\left(\frac{R_2}{s}\right)^2 + (X_2)^2}} \angle -\tan^{-1} \frac{X_2}{R_2/s}$$




At stator frequency

$$\Rightarrow I_2 = \frac{sE_2}{\sqrt{(R_2)^2 + (sX_2)^2}} \angle -\tan^{-1} \frac{sX_2}{R_2}$$

equal to equivalent Rotor current at Rotor freq

Rotor $\frac{1}{p}$ power = $(I_2)^2 \times \frac{R_2}{s}$



Exact equivalent CRT

ACTUAL POWER FLOW

$\frac{2}{p}$ Power minus (stator cu loss + stator core loss) Air gap power minus Rotor cu loss = sP_g
 or Rotor $\frac{2}{p}$ P_g

Gross Mech power Developed minus Rotational loss

D D

O/P Power

$$P_g = (I_2')^2 \times \frac{R_2'}{s}$$

$$\text{Rotor copper loss} = (I_2')^2 R_2' = s P_g$$


$$P_d = P_g - s P_g = P_g (1-s)$$

$$\text{Air Gap Torque} = \frac{P_g}{\omega_{sm}} \text{ Syn. watts.}$$

$$\text{Gross Torque Developed, } T_d = \frac{P_d}{\omega_m}$$

$$T_d = \frac{P_g (1-s)}{\omega_{sm} (1-s)} = \frac{P_g}{\omega_{sm}} = T_g$$

$$\eta_{\text{internal}}^{\text{OR Rotor}} = \frac{P_d}{P_g} = (1-s)$$



Que → A 6-pole 50-Hz 3- ϕ I.M. running on full load develops a useful torque of 160 N-m & the rotor emf is absorbed to make 120 cycles per minute. Calculate the net mechanical power developed. If the torque loss in windage & friction is 12 N-m, find the copper loss in rotor wdg, the $\frac{2}{p}$ in the motor & efficiency. Given total stator losses = 200 watts.

$$\underline{\text{Sol}^n} :- f_r = \frac{1200}{60} = 20 \text{ Hz}, \quad s = \frac{f_r}{f} = \frac{2}{50} = 0.04 \text{ pu.}$$

$$w_{sm} = \frac{2}{p} \times 2\pi f = \frac{2}{6} \times (2\pi \times 50) = 104.72 \text{ mech rad/sec}$$

$$w_m = w_{sm} (1-s) = 100.53 \text{ mech rad/sec.}$$

$$\therefore \text{Net Mech power, } P_{out} = 160 w_m = 16.085 \text{ kW}$$

$$\text{Gross Torque} = 160 + 12 = 172 \text{ Nm.}$$

$$\therefore P_g = 172 w_{sm} = 18.01 \text{ kW.}$$

$$\text{Rotor cu loss} = s P_g = 0.04 \times (18.01 \times 10^3) \text{ W} = 720.4 \text{ W.}$$

$$P_{in} = P_g + \text{Stator loss} = 18.01 + (200 \times 10^3) = 18.21 \text{ kW.}$$

$$\eta = \frac{P_{out}}{P_{in}} = \frac{16.085}{18.21} = 0.8833 = 88.33 \%$$

Que: A 3- ϕ I.M has an $\eta = 0.9$ when the load is 37 kW. at this load stator cu loss & rotor cu loss each equals iron loss. The mechanical losses are $\frac{1}{3}$ of No load loss. Calculate the slip.

$$\text{of}^2 \Rightarrow 0.9 = \frac{37}{P_{in}} \Rightarrow P_{in} = \frac{37}{0.9} = 41.111 \text{ kW}$$

$$\text{Total loss} = P_{in} - P_{out} = 41.11 - 37 = 4.111 \text{ kW}$$

$$\text{Let Stator cu loss} = \text{Iron loss} = \text{Rotor cu loss} = y$$

$$\text{Given: } \text{Mech loss} = \frac{1}{3} \times \text{No load loss}$$

$$\Rightarrow 3 \text{ mech loss} = \text{Iron loss} + \text{Mech loss}$$

$$\Rightarrow 2 \text{ Mech loss} = y$$

$$\text{Mech loss} = 0.5 y$$

$$\Rightarrow y + y + y + 0.5y = 4.111 \times 10^3 \text{ Watt}$$

$$\Rightarrow 3.5y = 4111 \Rightarrow y = 1174.6 \text{ W}$$

$$P_g = P_{2n} - 2y \text{ or } P_{out} + 1.5y = 38761.8 \text{ W}$$

$$\therefore \text{slip, } s = \frac{\text{Rotor cu loss}}{P_g} = \frac{1174.6}{38761.8} = 0.0303 \text{ pu} = 3.03\%$$

□ STEINMETZ MODEL




Fig: IEEE APPROVED STEINMETZ MODEL.

* Power flow in Steinmetz model.

$$P_{2n} \xrightarrow{\text{Minus stator cu loss}} \text{Rotor } \frac{3}{2} P \text{ i.e. } P_g \xrightarrow{\text{Minus rotor cu loss}} P_d \xrightarrow{\text{Minus rotational loss}} P_{out} + P_{fw} + P_{me} + P_{LL}$$

O/P Power, P_{ow}

* COMPUTATIONAL CONVENIENCE.

$$1) \vec{Z}_p = (jX_\phi) \parallel \left(\frac{R_2'}{s} + jX_2' \right)$$

$$Z_p = R_p + jX_p$$

$$2) I_1 = \frac{V_1}{\vec{Z}_1 + Z_p}$$

$$3) P_g = (I_1^2) \times R_p$$

Que:- A 3- ϕ Star connected 220 volts, 7.5 kW, 60Hz 6 pole I.M has the following ~~constant~~ ^{constant} per phase referred to stator in Steinmetz model
 $R_1 = 0.294 \Omega$, $X_1 = 0.503 \Omega$, $R_2' = 0.144 \Omega$, $X_2' = 0.209 \Omega$, $X_\phi = 13.25 \Omega$. The total friction windage & core losses may be assumed to be constant at 403 watts, independent of load. For a slip of 2%, compute the speed, o/p torque, o/p power, stator current, p.f and efficiency when the motor is operated at rated frequency & voltage.

$$\begin{aligned} \text{Soln:- } Z_p &= (jX_\phi) \parallel \left(\frac{R_2'}{s} + jX_2' \right) \\ &= \frac{j13.25 \times \left(\frac{0.144}{0.02} + j0.209 \right)}{j13.25 + j0.209 + \frac{0.144}{0.02}} \\ &= \frac{j95.4 - 2.769}{7.2 + j13.45} = (5.43 + j3.11) \Omega \\ &\quad \downarrow \\ &\quad R_p \end{aligned}$$

$$\vec{I}_1 = \frac{(220/\sqrt{3}) \angle 0^\circ}{Z_1 + Z_p} = 18.76 \angle -32.26^\circ \text{ Amp.}$$

$$\text{o/p pf} = \cos 32.26^\circ \text{ lag} = 0.8456 \text{ lag.}$$

$$I_g = 3 \times (I_1)^2 \times R_p = 5733.1 \text{ watt.}$$

$$P_d = I_g (1-s) = 5618.44 \text{ W}$$

$$P_{\text{out}} = P_d - P_{\text{rot}} = 5618.44 - 403 = 5215.44 \text{ W}$$

$$\omega_{sm} = \frac{2}{p} \times 2\pi f = \frac{2}{6} \times (2\pi \times 60) = 125.66 \text{ mech rad/sec}$$

$$\omega_m = \omega_{sm} (1-s) = 123.15 \text{ mech rad/sec}$$

$$\text{Speed in rpm} = \frac{60 \omega_m}{2\pi} = 1176 \text{ rpm}$$

$$\text{O/p Torque} = \frac{P_{out}}{\omega_m} = 42.85 \text{ Nm}$$

$$P_{in} = \sqrt{3} \times 220 \times 18.76 \times 0.8456 = 6044.79 \text{ Watt}$$


$$\eta = \frac{P_{out}}{P_{in}} = 86.28 \%$$

THEVENIN'S EQUIVALENT OF STEINMETZ MODEL.

$$\Rightarrow \vec{V}_{TH} = \frac{\vec{V}_1}{R_1 + jX_1 + jX_\phi} \times jX_\phi$$

$$\Rightarrow \vec{Z}_{TH} = \frac{(jX_\phi) \parallel (R_1 + jX_1)}{jX_\phi + R_1 + jX_1}$$

$$= \vec{Z}_{TH} = R_{TH} + jX'_{TH}$$



$$= \frac{V_{TH}}{(R_{TH} + \frac{R'_2}{s}) + j(X_{TH} + X'_2)} \quad (\text{all calculations on per phase basis})$$

$$\therefore I'_2 = \frac{V_{TH}}{\sqrt{(R_{TH} + \frac{R'_2}{s})^2 + (X_{TH} + X'_2)^2}}$$

$$P_g = (I'_2)^2 \times \frac{R'_2}{s}$$


$$P_g = \frac{(V_{TH})^2}{(R_{TH} + \frac{R'_2}{s})^2 + (X_{TH} + X'_2)^2} \times \frac{R'_2}{s}$$

$$\therefore T = \frac{P_g}{\omega_{sm}}$$

$$T = \frac{1}{\omega_{sm}} \times \frac{(V_{TH})^2}{\left(R_{TH} + \frac{R_2'}{s}\right)^2 + (X_{TH} + X_2')^2} \times \frac{R_2'}{s}$$

neglecting stator impedance.

$$V_{TH} = 1, R_{TH} = 0, X_{TH} = 0.$$



$$\vec{I}_2 = \frac{\vec{V}_1}{\frac{R_2'}{s} + jX_2'}$$

$$\therefore \vec{I}_2 = \frac{V_1}{\sqrt{\left(\frac{R_2'}{s}\right)^2 + (X_2')^2}} \angle -\tan^{-1} \frac{sX_2'}{R_2'}$$

$$\& \text{ Rotor pf} = \cos \frac{R_2'/s}{\sqrt{\left(\frac{R_2'}{s}\right)^2 + (X_2')^2}}$$

$$T = \frac{1}{\omega_{sm}} \times \frac{(V_1)^2}{\left(\frac{R_2'}{s}\right)^2 + (X_2')^2} \times \frac{R_2'}{s}$$


(1) At low slip ; $X_2' < \frac{R_2'}{s}$.

$\therefore (X_2')^2 \approx 0$ in denominator.

$$\boxed{I_2' = \frac{sV_1}{R_2'} \propto s}, \text{ Rotor pf} = 1$$

$$T = \frac{1}{\omega_{sm}} \times \frac{s(V_1)^2}{R_2'}$$

$$\propto s.$$



(ii) At high slip ; $\frac{R_2'}{s} < X_2'$

$\therefore \left(\frac{R_2'}{s}\right)^2 \approx 0$ in the denominator



$$I_2' = \frac{V_1}{X_2'} = \text{constant}$$

$$\text{Rotor pf} = \frac{R_2'/s}{X_2'} \propto \frac{1}{s}$$

$$T = \frac{1}{\omega_{sm}} \times \frac{(V_1)^2}{(X_2')^2} \times \frac{R_2'}{s}$$

$$\propto \frac{1}{s}$$

* T_{max} is max^m torque, Breakdown torque, pull out torque,
~~Starting torque~~ Stalling torque.



* Max^m Torque.

$$\Rightarrow T = \frac{1}{\omega_{sm}} \times \frac{(V_{TH})^2}{\left(R_{TH} + \frac{R_2'}{s}\right)^2 + (X_{TH} + X_2')^2} \times \frac{R_2'}{s}$$

$$\Rightarrow T = \frac{(V_{TH})^2 R_2' / \omega_{sm}}{s \left[\left(R_{TH} + \frac{R_2'}{s}\right)^2 + (X_{TH} + X_2')^2 \right]}$$

for Max^m Torque, the Denominator should be min^m.

$$\begin{aligned} \text{Denominator} &= s \left(R_{TH} + \frac{R_2'}{s} \right)^2 + s (X_{TH} + X_2')^2 \\ &= s \left(R_{TH}^2 + 2 R_{TH} \cdot \frac{R_2'}{s} + \left(\frac{R_2'}{s} \right)^2 \right) + s (X_{TH} + X_2')^2 \\ &= s (R_{TH}^2) + 2 R_{TH} \cdot R_2' + \frac{(R_2')^2}{s} + s (X_{TH} + X_2')^2 \end{aligned}$$

For Denominator to be minimum.

$$\frac{d}{ds} (\text{Denominator}) = 0.$$

$$(R_{TH})^2 + 0 - \left(\frac{R_2'}{s} \right)^2 + (X_{TH} + X_2')^2 = 0.$$

$$\Rightarrow \left(\frac{R_2'}{s} \right)^2 = (R_{TH})^2 + (X_{TH} + X_2')^2$$

$$\Rightarrow \boxed{\left(\frac{R_2'}{s} \right) = \sqrt{(R_{TH})^2 + (X_{TH} + X_2')^2}}$$

* The same result would be obtained by applying max^m power transfer theorem for max^m power across $\frac{R_2'}{s}$ i.e. for max^m P_g.

$$\text{Hence, } S_{(T_{max})} = \frac{R_2'}{\sqrt{(R_{TH})^2 + (X_{TH} + X_2')^2}}$$

∴ R_2' if Rotor Resistance can be varied as in S.R.I.M.

= Constant if Rotor Resistance can't be varied as in S.C.I.M

$$\begin{aligned} T_{(max)} &= \frac{1}{\omega_{sm}} \times \frac{(V_{TH})^2}{\left(R_{TH} + \frac{R_2'}{S_{(T_{max})}}\right)^2 + (X_{TH} + X_2')^2} \times \frac{R_2'}{S_{(T_{max})}} \\ &= \frac{1}{\omega_{sm}} \times \frac{(V_{TH})^2}{(R_{TH})^2 + 2R_{TH} \times \frac{R_2'}{S_{(T_{max})}} + \left(\frac{R_2'}{S_{(T_{max})}}\right)^2 + (X_{TH} + X_2')^2} \times \frac{R_2'}{S_{(T_{max})}} \\ &= \frac{1}{\omega_{sm}} \times \frac{(V_{TH})^2}{2R_{TH} \times \frac{R_2'}{S_{(T_{max})}} + 2\left(\frac{R_2'}{S_{(T_{max})}}\right)^2} \times \frac{R_2'}{S_{(T_{max})}} \\ &= \frac{1}{\omega_{sm}} \times \frac{(V_{TH})^2}{2R_{TH} + 2\left(\frac{R_2'}{S_{(T_{max})}}\right)} \end{aligned}$$

$$T_{max} = \frac{1}{2\omega_{sm}} \times \frac{(V_{TH})^2}{R_{TH} + \sqrt{(R_{TH})^2 + (X_{TH} + X_2')^2}}$$

$$T_{max} = \text{CONSTANT}$$


Neglecting stator impedance

$$V_{TH} = V_1, R_{TH} = 0, X_{TH} = 0$$

$$\text{Then } T_{(max)} = \frac{1}{2\omega_{sm}} \times \frac{(V_1)^2}{X_2'}$$

at $s(T_{max}) = \frac{R_2'}{X_2'}$

7] EFFECT OF CHANGE IN ROTOR RESISTANCE (IN SRIM)



— See fig from book. —

Increasing Rotor Resistance

8] $\frac{T}{T_{max}}$ Ratio.

$$T = \frac{1}{\omega_{sm}} \times \frac{(V_1)^2}{\left(\frac{R_2'}{s}\right)^2 + (X_2')^2} \times \frac{R_2'}{s}$$

$$T_{(max)} = \frac{1}{2\omega_{sm}} \times \frac{(V_1)^2}{X_2'}$$

$$\therefore \frac{T}{T_{(max)}} = \frac{1}{\omega_{sm}} \times \frac{(V_1)^2}{\left(\frac{R_2'}{s}\right)^2 + (X_2')^2} \times \frac{R_2'}{s} \times \frac{2\omega_{sm} X_2'}{(V_1)^2}$$

$$= \frac{2}{\frac{s}{R_2' X_2'} \left[\left(\frac{R_2'}{s}\right)^2 + (X_2')^2 \right]}$$

$$= \frac{2}{\frac{R_2'}{s X_2'} + \frac{s X_2'}{R_2'}}$$

$$\Rightarrow \frac{T}{T_{(max)}} = \frac{2}{\frac{(R_2'/X_2')}{s} + \frac{s}{(R_2'/X_2')}}}$$

$$\Rightarrow \boxed{\frac{T}{T_{(max)}} = \frac{2}{\frac{s_{Tmax}}{s} + \frac{s}{s_{Tmax}}}}$$

□ $\frac{T_s}{T_{fl}}$ ratio.

$$T_{fl} = \frac{1}{\omega_{sm}} \times (I_{fl})^2 \times \frac{R_2'}{s_{fl}}$$

$$T_s = \frac{1}{\omega_{sm}} \times (I_s)^2 \times \frac{R_2'}{1.0}$$

$$\therefore \boxed{\frac{T_s}{T_{fl}} = \left(\frac{I_s}{I_{fl}}\right)^2 \times s_{fl}}$$

Que:- A 3- ϕ I.M. has a starting torque = 1.5 times Full load torque, and max^m torque equal to 2.5 times full load torque. Determine the full load slip and the starting % current in pu.

$$\text{Sol}^n: \frac{T_{st}}{T_{fl}} = 1.5 \quad \text{and} \quad \frac{T_{max}}{T_{fl}} = 2.5$$

$$\therefore \frac{T_s}{T_{max}} = \frac{1.5}{2.5} = 0.6$$

$$\Rightarrow 0.6 = \frac{2}{\frac{s_{Tmax}}{1} + \frac{1}{s_{Tmax}}} \Rightarrow s_{Tmax} = \frac{1}{3} \text{ or } 3$$

↓
accept 7%

$$\frac{T_{fl}}{T_{max}} = \frac{2}{\frac{S_{Tmax}}{S_{fl}} + \frac{S_{fl}}{S_{Tmax}}}$$

$$\Rightarrow \frac{1}{2.5} = \frac{2}{\frac{1}{3S_{fl}} + 3S_{fl}} \Rightarrow S_{fl} = 1.5971 \text{ pu} \approx 0.0696$$

↓
Accept

$$\Rightarrow \frac{T_s}{T_{fl}} = \left(\frac{I_s}{I_{fl}} \right)^2 \times S_{fl} \Rightarrow 1.5 = (I_s \text{ pu})^2 \times 0.0696$$

$$\Rightarrow I_s \text{ (pu)} = 4.6424 \text{ pu.}$$

APPROX $\frac{I_s}{I_{fl}}$ Ratio.

* FULL LOAD OPERATION (LOW SLIP)

$$I_{fl} = \frac{SV_1}{R_2'}$$


STARTING (HIGH SLIP)

$$I_s = \frac{V_1}{X_2'}$$

$$\therefore \frac{I_s}{I_{fl}} = \frac{V_1}{X_2'} \times \frac{R_2'}{S_{fl} V_1} = \frac{S_{Tmax}}{S_{fl}}$$

$$= \frac{(R_2' / X_2')}{S_{fl}}$$

Que:- A 3- ϕ I.M is operating at full load with a slip of 3% at syn speed of 1500 rpm. It is driving a mechanical load, having a torque requirement independent of speed. For some reason the line voltage drop to 90% of rated value. Calculate the new speed. Also, whether the motor would now run




$$\alpha < 1.$$

$$\Rightarrow \frac{T_{s(\text{auto})}}{T_{fl}} = \left(\frac{\alpha I_{sc}}{I_{fl}} \right)^2 \times S_{fl}$$


$$\Rightarrow T_{s(\text{auto})} = \alpha^2 T_{s(\Delta)}$$

19/06/14

STAR DELTA STARTING



$$I_s(\lambda) = \frac{I_{sc}}{\sqrt{3}} = \frac{I_s(\Delta)}{3}$$



$$\frac{T_{st}}{T_{fl}} = \left(\frac{I_{sc}/\sqrt{3}}{I_f} \right)^2 \times S_{fl}$$



$$\Rightarrow T_s(\lambda) = \frac{1}{3} T_s(\Delta)$$

* This means that a Y- Δ starting is equivalent to auto x'mer starting with reduction $x = \frac{1}{\sqrt{3}}$.

☐ COMPARISON ON TORQUE PER LINE AMP :-

Type	$I_{s(\Delta)}$ Line	Torque	Torque/Line Amp
DOL (Δ)	$I_{s(\Delta)}$	$T_{s(\Delta)}$	$T_{s(\Delta)} / I_{s(\Delta)}$
Z	$x I_{s(\Delta)}$	$x^2 T_{s(\Delta)}$	$x T_{s(\Delta)} / I_{s(\Delta)}$
Auto	$x^2 I_{s(\Delta)}$	$x^2 T_{s(\Delta)}$	$T_{s(\Delta)} / I_{s(\Delta)}$
λ/Δ	$\frac{1}{3} I_{s(\Delta)}$	$\frac{1}{3} T_{s(\Delta)}$	$T_{s(\Delta)} / I_{s(\Delta)}$

Note :- In series ckt x constant but R is variable so that Z variable i.e. current I in the ckt drawn by semi circle.



□ CIRCLE DIAGRAM.

(Data from No Load Test & Blocked Rotor Test).








Fig:- cantilever ckt for circle diagram.



Rated frequency Variable Voltage 3-φ AC Supply.



$R_2' = \infty$
i.e. ckt will
open ckt
[∵ $s = 0$]



P_{0c} = connected for stator cu loss.

$$3\phi P_{0c} = (W_1 + W_2) - 3I_0^2 R_1$$

Fig: On no load (At $s=0$)

For no load




P_{0c} → fixed loss.


I_0 → No load current

V_{0c} → V_{rated}

$$P_{0c}(3\phi) = (W_1 + W_2) - 3I_0^2 R_1$$

Variable Voltage 3-φ AC Supply





For Blocked Rotor.

P_{BR} = Full load cu loss Blocked Rotor. (i.e $s=1$)


$I_{BR} = I_{FL} = I_{rated}$

$V_{BR} = I_{BR} \times Z_{sc}$

At V_{rated} :-

$$P_{sc} = P_{BR} \times \left(\frac{V_{rated}}{V_{BR}} \right)^2 \quad \left[\text{Includes fixed loss} \right]$$

$$I_{sc} = I_{BR} \times \left(\frac{V_{rated}}{V_{BR}} \right) \quad \left[\text{Includes excitation current} (\%) \right]$$



Select a current scale :-

$$1 \text{ cm} = x \cdot \text{Amp}$$

The pointer scale is $1 \text{ cm} = (x V_{\text{rated}}) \text{ V}$

$$\phi_0 = \cos^{-1} \left[\frac{P_{o.c.}}{V_0 I_0} \right]$$

$$OA = I_0$$

$$\phi_{sc} = \cos^{-1} \left[\frac{P_{sc}}{V_{\text{rated}} \cdot I_{sc}} \right]$$

$$OB = I_{sc}$$

$$\therefore AB = I_2' \text{ [at Standstill]}$$

At B (i.e. $s = 1$) :-

$$BE = \text{I/p power}$$

$$DE = \text{Fixed loss}$$

$$\therefore BD = \text{Total cu loss}$$

$$DF = \text{Stator cu loss}$$

$$FB = \text{Rotor cu loss}$$

$$\therefore \text{Starting Torque} = \frac{FB}{W_{sm}}$$

$$BF = \text{Rotor cu loss at } s = 1 \text{ i.e. Rotor i/p}$$

At Given I_1 :- (i.e. at operating point 'G')

$$GH = \text{I/p power}$$

$$JH = \text{Fixed loss}$$

$$JK = \text{Stator cu loss}$$

$$\therefore GK = \text{Rotor i/p i.e. } P_g$$

$$KL = \text{Rotor cu loss}$$

$$\therefore GL = \text{O/p power}$$

$$\text{Slip, } s = \frac{rL}{GK}$$

$$\text{I/P pf} = \frac{G_H}{OG}$$

$$\therefore \text{Torque, } T = \frac{GK}{\omega_{sm}}$$

$$\text{Efficiency, } \eta = \frac{G_L}{G_H}$$

$$MN = \text{Max}^m \text{ O/P}$$

$$\frac{PQ}{\omega_{sm}} = T_{(\text{max})}$$

$$\frac{R_{ext}}{R_2} = \frac{PR}{RQ} \quad (\text{for } T_{\text{max}} \text{ at start})$$


Where, R_{ext} = External Resistance.

Slip, $s = \infty$ when torque line extended.

Because, $P_g = 0$ & $I_2' \neq 0$.

$$\therefore P_g = (I_2')^2 \cdot \frac{R_2'}{s} = 0$$




$$\Rightarrow s = \infty \quad [\text{when } I_2' \neq 0]$$



□ DEEP BAR ROTOR & DOUBLE CAGE ROTOR.

* Slip ring I.M. has a provision for insertion of external rotor resistance that reduces the starting current & increasing the starting torque.

* Unfortunately a squirrel cage I.M. has no such provision & therefore its starting current is high but starting torque is low. Hence a special designed rotors are used to approach the starting performance of that of a slip ring motor.



1 → High Leakage Reactance / leakage flux / leakage voltage.

□ DEEP BAR ROTOR :-

* one of them is Deep Bar Rotor. Deep Bar rotor consist of narrow but deep bar. The bottom layer has largest leakage flux linkage. While the top layer has min^m rotor leakage flux linkage. Hence the bottom layer of the rotor bar has max^m leakage inductance of the bottom layer is the highest & goes on decreasing as one moves towards the upper layer. with the top layer having min^m leakage inductance.

* When such a motor is switched ON the rotor frequency equal to stator frequency. & at this frequency the lower layer offer great opposition to the flow of rotor current. Thus the rotor current


is pushed towards the upper layers where it is forced to flow against high resistance as the conductor cross-section available becomes small. This results into low starting current & high starting torque.

* As the speed increases, the rotor frequency decreases & therefore the leakage reactance of the lower layer reduces (gradual process of reduction). The opposition to the rotor current by the lower layer therefore start reducing. The motor current that start flowing in the lower layer as well. When the rotor attains normally speed the rotor frequency is very low & then the rotor current gets almost uniformly distributed through out the conductor cross-section resulting into improve operational running performance.

□ DOUBLE CAGE ROTOR

* The other special design rotor is the double cage rotor.

* It has two independent cages short ckted at both end by independent short ckting rings.



* The outer cage consist of a small cross section bars possibly made of a high resistivity material (like brass, bronze & aluminium etc). The inner cage consist of normal cross section bars separated from the outer cage bars within the slot by a small constriction that runs along the length of the slots.


* Due this unique constructional feature the leakage induction of the inner cage is more than that of the outer cage.

* When such a motor is switched on the rotor frequency at start equal the stator frequency & therefore the leakage reactance of the inner cage is very high. Resulting into great opposition to the flow of rotor current by the inner cage. Consequently the rotor current is pushed towards the outer cage where it is compelled to flow against high resistance resulting into reduces a starting current & increases starting torque.

* As the rotor accelerate the rotor frequency start reducing & therefore the opposition the flow of rotor current by the inner cage also start decreasing. Thus the rotor current start flowing the inner cage as well. At normal speed the rotor frequency is very low & the rotor current therefore gets proportionality distributed b/w two cages. Resulting into improved running performance.

* The presence of the constriction is necessary as

otherwise the stator mutual flux would completely miss linking the inner cage making it redundant.



□ BRAKING OF 3- ϕ INDUCTION MOTOR.


1. REGENERATIVE BRAKING.

It may be obtained by pole changing. When braking is desired, the no. of poles is increased in the ratio 2:1. The synchronous speed of the revolving field immediately become $\frac{1}{2}$ resulting into the operating slip being negative. The induction m/c becomes a generator extracting mechanical power from the shaft & supplying it back to power system. Consequently the speed reduces very fast & when it approaches the new synch. speed, the motor is switched off. to prevent its continue running below the new synch. speed. The mechanical breaks may than be applied if required.

2. PLUGGING

In this form of braking the phase sequence of running motor is reversed.

The direction of revolving field reverses immediately while the motor continues to move in the previous direction due to its inertia. The operating slip of the m/c becomes more than 1 & it develops an electromagnetic torque in the direction of new revolving field. Obviously this torque would oppose the present motion slowing down of the rotor.




The plugging torque goes on increasing while the speed continues to decrease & therefore the deceleration become fast when rotor approaches standstill, at which stage the motor to be switched off to prevent ^{it} turning in reverse direction.

During plugging electrical power is drawn from the mains & while is charged while mechanical power is derived from the shaft & the sum of these two power is dissipated as heat in the m/c. Adequate precaution must be undertaken to ensure that the motor doesn't get damage during plugging.


3. DYNAMIC BRAKING.

In this form of braking AC supply to the motor is switched off and an appropriate DC voltage is connected to its armature terminals. This establishes stationary magnetic field in the air gap the rotor develops Lenz Law currents that bring the rotor to rest. DC supply should then be disconnected.

There are various possible connections for dynamic braking depending upon no. of switches available & the option exercised would affect the braking time.



Que:- A 3- ϕ , 50 Hz, 400V, 6 pole 90 kW Δ connected I.M has the following parameters of the approximate CKT model.



$$R_1 = 1.4 \Omega, X_1 = 2 \Omega, R_2' = 0.6 \Omega, X_2' = 1 \Omega, X_\phi = 50 \Omega$$

The rotational loss is 275 W. For a slip of 0.03, 0.03 and 1.2, determine as applicable.

(a) The line current, pf and power i/p.

(b) The shaft torque and mechanical o/p

(c) The efficiency.

Soⁿ:- For slip = 0.03 (MOTORING)

$$\frac{R_2'}{s} = \frac{0.6}{0.03} = 20 \Omega$$

$$(a) \vec{I}_2' = \frac{(400/\sqrt{3}) \angle 0^\circ}{(1.4 + 20) + j(2+1)} = 10.69 \angle -7.98^\circ \text{ A}$$

$$\vec{I}_\phi = \frac{(400/\sqrt{3}) \angle 0^\circ}{j50} = 4.62 \angle -90^\circ$$

$$\text{Now } \vec{I}_1 = \vec{I}_2' + \vec{I}_\phi = 12.22 \angle -29.97^\circ \text{ A}$$

$$\therefore \text{ i/p pf} = \cos 29.97^\circ \text{ lag} = 0.8663 \text{ lag}$$

$$P_{in} = \sqrt{3} \times 400 \times 12.22 \times 0.8663 = 7.333 \text{ kW}$$

$$(b) P_g = 3 \times (I_2')^2 \times \frac{R_2'}{s} = 6.857 \text{ kW}$$

$$P_d = P_g (1-s) = 6.857 \times 0.97 = 6.651 \text{ kW}$$

$$P_{out} = P_d - P_{rot} = 6.376 \text{ kW}$$

$$\omega_{sm} = \frac{2}{P} \times 2\pi f = 104.72 \text{ mech rad/sec}$$

$$\omega_m = \omega_{sm} (1-s) = 101.58 \text{ mech rad/sec}$$

$$\text{Shaft Torque} = \frac{P_{out}}{\omega_m} = 62.77 \text{ Nm}$$

$$(c) \eta = \frac{P_{out}}{P_{in}} = 0.8695 = 86.95\%$$

For slip = 0.03 (GENERATING).

$$\frac{R_2'}{s} = \frac{0.26}{-0.03} = -20 \Omega$$

$$(a) \vec{I}_2' = \frac{(400/\sqrt{3}) \angle 0^\circ}{(14-20) + j(2+1)} = 12.26 \angle -170.83^\circ \text{ A.}$$

$$\vec{I}_\phi = \frac{(400/\sqrt{3}) \angle 0^\circ}{j50} = 4.62 \angle -90^\circ$$

$$\text{Now, } \vec{I}_1 = \vec{I}_2' + \vec{I}_\phi = 13.77 \angle -151.49^\circ \text{ A.}$$

$$\therefore \vec{I}_1(\text{gen}) = -\vec{I}_1 = -13.77 \angle -151.49^\circ \text{ A.}$$

$$\text{i.e. } \vec{I}_1(\text{out}) = 13.77 \angle 28.51^\circ \text{ A}$$

$$\therefore \begin{aligned} S_{out} \\ \text{i.e.} \\ S_{gen} \end{aligned} = \vec{V}_1 \vec{I}_1(\text{out})^* = \sqrt{3} \times 400 \angle 0^\circ \times [13.77 \angle -28.51^\circ]$$

$$= 9.54 \angle -28.51^\circ \text{ KVA}$$

$$= (8.383 - j4.554) \text{ KVA}$$

$$= 8.383 \text{ kW}$$

$$\text{o/p pf of gen} = \cos 28.51^\circ \text{ leading} = 0.8787 \text{ leading.}$$

$$(b) P_g = 3 \times (I_2')^2 \times \frac{R_2'}{s} = -9.018 \text{ kW.}$$

(represents rotor o/p)

$$P_d = P_g (1-s) = -9.018 (1 - (-0.03)) = -9.289 \text{ kW}$$

$$\begin{aligned} P_{out} = P_d - P_{rot} &= -9.289 - (275 \times 10^{-3}) \\ &= -9.564 \text{ kW.} \end{aligned}$$

(Prime mover $\frac{o}{p}$)

$$\omega_m = \omega_{sm} (1 - (-0.03))$$

$$\text{Shaft Torque} = \frac{-9.564 \times 10^{-3}}{104.72 (1 + 0.03)} = -88.67 \text{ N-m}$$

↓
Represents prime mover Torque.

$$(c) \eta_{gen} = \frac{P_{out(gen)}}{P_{in(gen)}} = \frac{8.303}{9.564} = 0.8765 = 87.65\%$$

At, $s = 1.2$ (i.e. Plugging Mode)

$$\frac{R_2'}{s} = \frac{0.6}{1.5} = 0.5 \Omega$$

$$-I_2' = \frac{(400/\sqrt{3}) \angle 0^\circ}{(1.4 + 0.5) + j(2+1)} = 65.03 \angle -57.65^\circ \text{ A}$$

$$I_\phi = \frac{(400/\sqrt{3}) \angle 0^\circ}{j50} = 4.62 \angle -90^\circ$$

$$\text{Now } \vec{I}_1 = \vec{I}_2' + \vec{I}_\phi = 68.98 \angle -59.7^\circ \text{ A}$$

$$\vec{S}_{in} = \vec{S}_1 = \sqrt{3} \times 400 \angle 0^\circ \times [68.98 \angle 59.7^\circ] \\ = 24.112 + j41.26 = 47.793 \angle 59.7^\circ \text{ kVA}$$

$$\therefore P_{in} = 24.112 \text{ kW}$$

$$\text{z/p pf} = \cos 59.7^\circ \text{ lag} = 0.5045 \text{ lag}$$

$$P_g = 3 \times (I_2')^2 \times \frac{R_2'}{s} = 6.343 \text{ kW}$$

$$P_d = P_g (1-s) = 6.343 (1-1.2) = -1.269 \text{ kW}$$

i.e. from shaft

$$P_{out} = P_d - P_{rot} = -1.269 - 0.275 = -1.544 \text{ kW}$$

i.e. derived from shaft

$$\text{Total z/p to m/c} = P_{in(elect)} + P_{mech}$$


Total losses = $P_{in} - P_{out} = 24.112 - (-1.544) = 25.656 \text{ kW}$

Shaft Torque = $\frac{P_{out}}{\omega_m} = \frac{-1.54 \times 10^3}{104.72 (1-1.2)}$


= 73.72 N-m. i.e. in the direction of rotating field.

SPEED CONTROL OF 3- ϕ I.M.

$N = N_s (1-s) \Rightarrow N = \frac{120f}{p} (1-s)$



1. BY VOLTAGE CONTROL




$T_{max} = \frac{1}{2\omega_{sm}} \times \frac{(V_1)^2}{X_2'}$


$s_{T_{max}} = \frac{R_2'}{X_2'}$

$T_s = \frac{1}{\omega_{sm}} \times \frac{(V_1)^2}{(X_2')^2} \times R_2'$

2. BY ROTOR RESISTANCE



3. BY ROTOR FREQUENCY VOLTAGE INJECTION.




$$\begin{aligned} \vec{SE}_2 &= \vec{I}_2 R_2 + j \vec{I}_2 (sX_2) + \vec{E}_{inj} \\ &= \vec{I}_2 (R_2 + j sX_2) + \vec{E}_{inj} \\ &\approx 0 \end{aligned}$$

$$sE_2 = E_{inj}$$

$$\Rightarrow \boxed{\uparrow s = \frac{\uparrow E_{inj}}{E_2}}$$

For Sub-Synch. Speed control



$$\begin{aligned} \vec{SE}_2 &= \vec{I}_2 R_2 + j \vec{I}_2 (sX_2) - \vec{E}_{inj} \\ &= \vec{I}_2 (R_2 + j sX_2) - \vec{E}_{inj} \\ &\approx 0 \end{aligned}$$

$$sE_2 = -E_{inj}$$

$$\Rightarrow \boxed{\uparrow s = -\frac{\uparrow E_{inj}}{E_2}}$$

For Super Synch. Speed control.

□ VVVf CONTROL.

$$1) T_{(max)} = \frac{1}{2\omega_{srs}} \times \frac{(V_1)^2}{X_2'}$$

$$4) \tan \phi_2 = \frac{sX_2'}{R_2'}$$

$$2) S_{(Tmax)} = \frac{R_2'}{X_2'}$$

$$3) (N_s - N) = sN_s$$

Region I : $0 < s \leq s_{(T_{max})}$

$$I_2' = \frac{sV_1}{R_2'} \quad , \quad T = \frac{1}{\omega_{sm}} \times \frac{s(V_1)^2}{R_2'}$$

Region II : $s > s_{(T_{max})}$

$$I_2' = \frac{V_1}{X_2'} \quad , \quad T = \frac{1}{\omega_{sm}} \times \frac{(V_1)^2}{(X_2')^2} \times \frac{R_2'}{s}$$

(A) Speed control below - Synchron. Speed.

by...

$$\frac{V}{f} = \text{constant control \& } f \leq \text{rated}$$


$$\Rightarrow V \propto f$$


$$1) T_{(max)} \propto \frac{1}{f} \times \frac{f^2}{f} = \text{constant} \quad \left| \quad \begin{array}{l} 3) (N_s - N) \propto sf \\ 4) \tan \phi_2 \propto sf \end{array} \right.$$

$$2) s_{(T_{max})} \propto \frac{1}{f}$$

Region I :- $I_2' \propto sf$, $T \propto sf$

Region II :- $I_2' \propto \frac{f}{f} = \text{constant}$, $T \propto \frac{1}{sf}$ $\therefore T_s \propto \frac{1}{f}$





* A constant $\frac{V}{f}$ control the operation at very low frequency would result in very low $\frac{V}{f}$ voltage & then stator impedance drop would no longer remain negligible. Hence at very low frequency the flux would become slightly weaker resulting into reduced value of T_{max} .

Hence, if the same max^m torque is required at very low frequency then the applied voltage should be slightly increased than the voltage calculated by constant $\frac{V}{f}$ ratio.

3) Speed control above synch. speed

By
Variable frequency control.



$V = \text{constant} \ \& \ f > f_{rated}$

$$1) T_{(max)} \propto \frac{1}{f^2} \quad \left| \quad 3) N_s - N \propto sf \quad \dots$$

$$2) S_{(T_{max})} \propto \frac{1}{f} \quad \left| \quad 4) \tan \phi_2 \propto sf$$


Region I: $I_2 \propto s$, $T \propto \frac{v}{f}$

Region II: $I_2' \propto \frac{1}{f}$, $T \propto \frac{1}{sf^3} \therefore T_s \propto \frac{1}{f^3}$



□ CRAWLING.

The flux density distribution in the air gap in 3- ϕ I.M contains, in addⁿ to the fundamental flux, higher order space harmonics out of which then non-triplet odd harmonics affect starting performance.



of the motor.


The sum of the fundamental torque, 5th and 7th harmonic torque creates a saddle zone near 7th space harmonic syn. speed. This saddle region contains a negative slope zone i.e. suitable for stable operation of the motor.

When such a motor is started on load the initial acceleration may be very low & therefore rotor may approach saddle region very slowly & settle at it as a (-ve) slope region i.e. close to 7th harmonic synch. speed.



This stable running at a very low speed near 7th harmonic synch. speed is known as crawling.

Crawling is accompanied by extremely high current very high losses & very low efficiency & therefore crawling is allowed to continue then the motor would be completely damaged.

SINGLE PHASE INDUCTION MOTOR



DOUBLE REVOLVING THEORY.



At $\theta = 0$

$$F(\theta=0) = F_{peak}$$

$$= F_{max} \cos \omega t$$

$$= F_{max} \left[\frac{e^{j\omega t} + e^{-j\omega t}}{2} \right]$$

$$= \underbrace{\frac{F_{max}}{2} e^{j\omega t}}_{\text{PMD MMF WAVE}} + \underbrace{\frac{F_{max}}{2} e^{-j\omega t}}_{\text{BWD MMF WAVE}}$$

PMD MMF
WAVE


BWD MMF
WAVE

At θ

$$\begin{aligned}
 F(\theta) &= F_{\text{peak}} \cos\theta \\
 &= F_{\text{max}} \cos\omega t \cos\theta \\
 &= \frac{F_{\text{max}}}{2} [2 \cos\omega t \cos\theta] \\
 &= \underbrace{\frac{F_{\text{max}}}{2} \cos(\theta - \omega t)}_{\text{FWD MMF WAVE}} + \underbrace{\frac{F_{\text{max}}}{2} \cos(\theta + \omega t)}_{\text{BWD MMF WAVE}}
 \end{aligned}$$

$$\phi = \underbrace{\frac{\phi_m}{2} \cos(\theta - \omega t)}_{\text{FWD FLUX}} + \underbrace{\frac{\phi_m}{2} \cos(\theta + \omega t)}_{\text{BWD FLUX}}$$

FWD FLUX




Forward slip, $s = \frac{N_s - N}{N_s} \Rightarrow s = 1 - \frac{N}{N_s}$

Backward slip = $\frac{N_s - (-N)}{N_s} = \frac{N_s + N}{N_s} = 1 + \frac{N}{N_s} = 1 + (1-s) = (2-s)$

$$\begin{aligned}
 \vec{I}_{\text{fwd}} &= \frac{\vec{SE}}{R + jSX} \\
 &= \frac{SE}{\sqrt{(R)^2 + (SX)^2}} \angle -\tan^{-1} \frac{SX}{R}
 \end{aligned}$$

BWD FLUX



$$\begin{aligned}
 \vec{I}_{\text{bwd}} &= \frac{(2-s)E}{R + j(2-s)X} \\
 &= \frac{(2-s)E}{\sqrt{(R)^2 + \{(2-s)X\}^2}} \angle \tan^{-1} \left(\frac{(2-s)X}{R} \right)
 \end{aligned}$$

□ PRINCIPLE OF OPERATION OF $1-\phi$ I.M. A/c TO DOUBLE REVOLVING FIELD THEORY.

A/c to double revolving field theory a sinusoidal varying field mmf is equivalent to two revolving mmf wave each with half magnitude rotating in opposite direction at synch. speed. Obviously therefore a sinusoidally varying flux created by mmf would be equivalent two revolving fluxes each of half amplitude rotating in opposite direction at synch. speed.

At stand still the rotor current created by the forward flux & the rotor current created by backward flux are equal in magnitude & are of same lagging pf. Consequently the armature \times^n effect of two current is similar on their respective fluxes resulting into equal strength of fwd flux & bwd flux at standstill. Since the flux interact with their rotor current to produce torque, equal flux interacting with equal current of equal pf produces equal torque. Hence the fwd torque & bwd torque being equal at standstill produce no motion and that is why a $1-\phi$ I.M. is not self starting.

However if an initial motion is given to the rotor by any means in any direction, it is found to accelerate in the same direction until

It reaches its normal speed. This phenomenon may be explained as follow.

If an initial motion is given, in say in the fwd direction & the speed is ω then the fwd slip s reduces. This results into the fwd rotor current to reduce & become less lagging. The demagnetising armature X^2 effect on its fwd flux reducing into stronger forward flux.


on the other hand the backward slip increases resulting into increase in the backward rotor current that becomes more lagging. It ^{demagnetising} _{armature} X^2 effect on backward flux increases making the backward flux weaker.


A stronger fwd flux dominates over weaker backward flux & accelerates the rotor ω in its own direction. As the speed increases the fwd flux becomes stronger & stronger while the backward flux becomes weaker & weaker. Obviously the fwd torque becomes stronger & the backward torque becomes weaker causing the acceleration in fwd direction to continue until the rotor reaches its normal speed.

It may be noted that although the fwd flux becomes stronger & stronger & backward

flux becomes weaker & weaker their sum remains constant & it is not unexpected since the applied voltage remains constant.

During normal operation the fwd flux glides past ^{the} bwd mmf wave at double synch speed. And ~~the~~ the bwd flux crosses the fwd mmf wave at double synch speed resulting into double frequency oscillating torque that makes 1- ϕ motor noisier & more prone to vibration as compared to a 3- ϕ I.M of the same ~~rating~~ capacity. This is also not unexpected because 1- ϕ power always contains double frequency oscillating component. The 1- ϕ I.M may therefore be put on a rubber mat or any other elastic foundation to prevent vibration & noise from spreading to the surroundings.





(Fig:- 1-φ I.M. at Standstill)




Fig:- 1-φ I.M. at Standstill w.r to double Revolving Field theory




Fig:- 1-φ I.M. at slip 's' w.r to double Revolving Field theory.

Que A 180 watt, 110V 60 Hz 4 pole 1- ϕ I.M has the following constant: $R_1 = 2.02 \Omega$, $X_1 = 2.79 \Omega$, $R_2' = 4.12 \Omega$, $X_2' = 2.12 \Omega$, $X_\phi = 66.8 \Omega$. Then core loss = 24W, Friction & windage = 13W. For a slip of 0.05, determine the stator current, P.f, Power o/p, Speed, Torque & η when this motor is running at rated voltage & frequency?

$$\underline{\text{Sol}^n} :- \vec{Z}_{fwd} = (15.931 + j20.075) \Omega$$

\downarrow
 R_{fwd}

$$\vec{Z}_{bwd} = (0.993 + j1.058) \Omega$$

\downarrow
 R_{bwd}

$$\vec{I}_1 = \frac{110 \angle 0^\circ}{\vec{Z}_1 + \vec{Z}_{fwd} + \vec{Z}_{load}} = 3.609 \angle -51.63^\circ \text{ A}$$

$$\text{P.f} = \cos 51.63^\circ \text{ lag} = 0.6207 \text{ lag}$$

$$P_g(\text{fwd}) = (I_1)^2 \times R_{fwd} = 207.04 \text{ W}$$

$$P_g(\text{bwd}) = (I_1)^2 \times R_{bwd} = 12.88 \text{ W}$$

$$T_{fwd} = \frac{P_g(\text{fwd})}{\omega_{sm}} = 1.098 \text{ N.m}$$

$$\omega_{sm} = \frac{2}{P} \times 2\pi f = \frac{2}{4} \times 2\pi \times 60 = 188.5 \text{ mech rad/sec}$$

$$\omega_m = \omega_{sm}(1-s) = 179.08 \text{ mech rad/sec}$$

$$\text{Speed in rpm} = \frac{60 \times 179.08}{2\pi} = 1710 \text{ rpm}$$

$$T_{bwd} = \frac{P_g(bwd)}{\omega_m} = 0.068 \text{ Nm}$$

$$\begin{aligned} \therefore \text{Net Airgap Torque} &= \text{Gross Torque Developed} \\ &= T_{fwd} - T_{bwd} = 1.03 \text{ Nm} \end{aligned}$$

$$\begin{aligned} \therefore \text{Gross Mech power developed i.e } P_d &= 1.03 \times \omega_m \\ &= 184.45 \text{ Watt} \end{aligned}$$

$$\therefore P_{out} = P_d - (24 + 13) = 147.45 \text{ Watt}$$

$$\text{ofp torque} = \frac{P_{out}}{\omega_m} = 0.829 \text{ Nm}$$

$$P_{in} = 110 \times 3.605 \times 0.6207 = 246.14 \text{ W}$$

$$\eta = \frac{P_{out}}{P_{in}} = \frac{147.45}{246.14} = 0.5990 = 59.9\%$$

$$\text{ofp power} = 147.45$$

$$\text{Rotational loss} = 37$$


$$\text{Forward field rotor cu loss} = s P_g = 10.352 \text{ W}$$

$$\text{Bwd Rotor cu loss} = (2-s) P_g(bwd) = (2-0.05) \times 12.88 = 25.116 \text{ W}$$

$$\text{Stator cu loss} = (I_1)^2 R_1 = (3.605)^2 \times 2.02 = 26.25 \text{ W}$$


$$\begin{aligned} \text{Yp power} &= \text{Sum of all} \\ &= 147.44 + 37 + 10.352 + 25.116 + 26.25 \\ &= 246.168 \text{ watt} \end{aligned}$$



□ REVOLVING FIELD IN 2-PHASE MOTOR.





□ RESISTANCE START SPLIT PHASE INDUCTION MOTOR.

* The auxiliary wdg is short time rated and is designed for high $\frac{R}{X}$ ratio by using fewer turns of thin wire & placing them in the top of the slot.








□ CAPACITOR TYPE MOTORS...





$$\begin{aligned} \vec{Z} &= R + j(X_L - X_C) \text{ when } X_L > X_C \\ &= R - j(X_C - X_L) \text{ when } X_C > X_L \end{aligned}$$




1. CAPACITOR START MOTOR.




2. CAPACITOR RUN MOTOR / PERMANENT SPLIT CAPACITOR MOTOR.





3. CAPACITOR START & CAPACITOR RUN MOTOR
OR
TWO VALUE CAPACITOR MOTOR.




$C_1 = 40 \mu F$
 $C_2 = 300 \mu F$ } for $\frac{1}{2}$ HP Motor



□ SHADED POLE MOTOR.



the slip speed becomes very low & the reluctance torque snaps the load into synchronism.



Subsequently the rotor continues to run at synchronism speed & is called therefore synchronism reluctance motor, because at synchronism speed the cage torque becomes zero & the motor runs only with reluctance torque.

However if during operation there is a departure from synchronism speed then the cage develops Lenz law currents to restore synchronism speed, an action similar to that of the damper winding in ordinary synchronism motor.

* The absence of rotor excitation makes the synchronism reluctance motor larger in size as compared to ordinary synchronism motor, for the same duty.

* The power factor of this motor is quite low because of the increase in air gap consequent upon removal of some rotor teeth.

* It is almost a maintenance free motor because of absence of rotor winding, slip ring, brushes & excitation system.

* The saliency of the rotor increases vibration, noise and windage loss.

* It is a constant speed motor & therefore it is used in speed sensitive applications like clocks, timers & turn tables etc.

B) HYSTERESIS MOTOR.

* The 1- ϕ hysteresis motor has its stator similar to that of permanent split capacitor motor.

However the rotor is a solid cylinder of magnetically hard steel. However to reduce the inertia & by/or cost, an annular ring of magnetically hard steel may be mounted on the cylinder of non magnetic material such as aluminium.

* When such a motor is switched on the rotor flux lags behind its magnetising mmf by the hysteresis lag angle δ . This results into hysteresis torque i.e. proportional to the product of stator flux and rotor flux & $\sin \delta$. The hysteresis torque remains constant upto synch. speed because δ depends upon the property of the material & not at the rate at which hysteresis loop is traversed.

* When speed approaches synch. value the relative speed b/w the rotor body & stator flux becomes negligible & therefore the rotor gets permanently magnetized.

Subsequently the permanent poles of the rotor get magnetically locked with the stator field. therefore the motor continues to run as a permanent magnet Synchron. motor.

- * Although a magnetically hard steel rotor has a very resistivity some amount of eddy current torque is available at starts that helps in accelerating the rotor. As the speed increases the eddy current torque decreases & becomes zero obviously at Synchron. speed.
- * At Synchron. speed there is no eddy current torque but during operation if there is a departure from Synchron. speed than the eddy current torque tries to restore Synchronism, an action similar to that of a damper wdg. in ordinary Synchron. motor
- * Unlike a Synchron. reluctance motor that snaps its load into Synchronism from I.M. action, the hysteresis motor is able to accelerate ^{any} load which it can irrespective of how large the inertia is.
- * The hysteresis motor is silent running motor because of not only the stator design but also because of its smooth rotor periphery as it has no slots or windings.
- * Since it is a constant speed motor it is quite suitable for speed sensitive silent appl. like clocks, timer & other audio & video devices.

Eddy Torque

Eddy current loss, $P_e = K_e (sf)^2 B_m^2$


Air gap power, $P_g(\text{eddy}) = \frac{K_e (sf)^2 B_m^2}{s}$

$$\therefore T_{(\text{eddy})} = \frac{P_g(\text{eddy})}{\omega_{sm}}$$

$$\therefore T_{(\text{eddy})} = \frac{P_g(\text{eddy})}{\omega_{sm}}$$

$$\therefore T_{(\text{eddy})} = \frac{K_e s f^2 B_m^2}{\omega_{sm}}$$

$\propto s$




Hysteresis Torque

Hysteresis Loss, $P_h = K_h (sf) B_m^n$



Air gap power, $P_g(\text{hys}) = \frac{K_h (sf) B_m^n}{s}$
 $= K_h f B_m^n$

$$\therefore T_{(\text{hys})} = \frac{K_h f B_m^n}{\omega_{sm}}$$


$\propto \text{Constant}$



□ AC UNIVERSAL MOTOR



□ STEPPER MOTOR



N_r = No. of rotor teeth

Rotor teeth pitch = $\frac{360^\circ}{N_r}$

m = No. of stacks

Then step size, $\Delta\theta = \frac{360^\circ}{m N_r}$

No. of steps required for 1 revolution = $\frac{360^\circ}{\Delta\theta} = m N_r$

When $N_s > N_r$; Then stator tooth pitch = $\frac{360^\circ}{N_s}$

Rotor Tooth pitch = $\frac{360^\circ}{N_r}$

\therefore Step size, $\Delta\theta = \frac{360^\circ}{N_r} - \frac{360^\circ}{N_s} = \frac{(N_s - N_r)}{N_s \cdot N_r} \times 360^\circ$

$$\text{Speed} = \frac{\Delta\theta \times \text{Pulse per Sec.}}{360} \text{ rev/Sec.}$$

$$\text{Speed} = \frac{\Delta\theta \times \text{Pulse per Sec}}{6} \text{ rpm.}$$

Defination:-

HOLDING TORQUE:- It is defined as the amount of torque required to move rotor one full step with the stator energised. Holding torque is the max^m torque produced by the motor at standstill.

DETENTE TORQUE / RESIDUAL / RESTRAINING TORQUE :- It is defined as the max^m load torque that can be applied to the shaft of an unexcited motor without causing continuous rotation. It is generally 10% of holding torque.

PULL IN TORQUE :- It is defined as the torque developed by the motor at which the motor can start synchronize stop or reverse for diffrent different values of load torque. Accordingly in the start range, the load position follows the pulses without losing steps, and came start, stop or reverse on command.

PULL OUT TORQUE :- It is defined as the torque developed by the motor at which the motor can run for different

ue of load torque if already synchronize but
can't start, stop or reverse on command.

Accordingly is slow range, since the pulse rate is very high, the load velocity here follows the pulse rate without losing step but can't start, stop or reverse on command.

It may be realized that with increasing pulse rate the motor may provide less torque because the stator wdg current pattern gets altered at high pulse rate. Consequently with less torque & with less time to drive the load from one position to the next the motor refuses to start, stop or reverse on command.

□ TYPES OF STEPPER MOTOR

1) VARIABLE RELUCTANCE :- It has unexcited rotor teeth but excited stator teeth. It can be single stack type or multiple stack type. Max^m pulse rate is as high as 1200 pulses per sec and the step size may be 15° to down to 2°.

2) PERMANENT MAGNET :- It has a permanent magnet rotor & therefore has a higher inertia than that of a comparable variable reluctance stepper motor, consequently PM stepper motor has slower accelⁿ & its max^m pulse

rate is 300 pulse per sec. It's Step size is 30 to 90°. However it produces more torque per ampere of stator current as compared to Variable Reluctance Stepper motor.

3) HYBRID :- As the name suggest, It employs a Combⁿ of VR & Permanent magnet Stepper motor. It has a rotor made of axial permanent magnet at the middle & ferromagnetic teeth at outer section. The ferromagnetic teeth acquire the polarity of the pole on which they are mounted. The hybrid motor therefore combines the small Step size feature of a Variable Reluctance type Stepper motor with the high torque feature of permanent magnet type. The max^m pulse rate is 2000 pulse per sec & possible Step size is as low as ~~0.4~~ 0.45°. However the hybrid motor is more expensive than the Variable reluctance motor on account of higher cost of material & manufacture (workmanship).

DC MACHINES.

CHRISTIAN OERSTED : Electro + Magnetism

MICHAEL FARADAY : Electro Magnet Induction

SIR ISAAC NEWTON : Modern physics
↓
Laws of Motion, Gravity.

DC Generator } DC Voltage
DC Motor } Identical construction

DC GENERATOR

A m/c which takes the advantage of Electro Magnetic Induction to convert mechanical movement into electricity (in dc voltage).

ELECTRO MAGNETIC INDUCTION.

A/c to Faraday whenever a conductor cuts magnetic flux a dynamically induced emf is produced in it. The magnitude of induced emf is directly proportional to rate of change of flux linkages.

FLUX

The amount of magnetic field around a magnet (lines of force).

Denoted by - ϕ

□ FLUX LINKAGE (λ)

The extent of interaction b/w flux & the conductor.

$$\text{Flux Linkage } (\lambda) = N\phi$$

↓
No. of conductors.

$$\Rightarrow e \propto \frac{d\lambda}{dt} \propto \frac{d(N\phi)}{dt}$$

$$\Rightarrow e = -N \frac{d\phi}{dt} \text{ Volts}$$

$$\Rightarrow e = - \left[N \frac{d\phi}{dt} \right] \times \frac{di}{di} = \left[N \frac{d\phi}{di} \right] \times \frac{di}{dt} = L \frac{di}{dt}$$

□ METHODS OF FLUX LINKAGE.

The flux can be time varying or time in varying.

A/c to Faraday there are three mode of flux linkage.


- | | | | |
|----------------------------|-----------------|------------------------------------|-----------|
| (1) Conductor (Rotating) | Relative motion | Flux (Stationary) (Time Invariant) | DC m/c |
| (2) Conductor (Stationary) | | Flux (Rotating) | Synch m/c |
| (3) Conductor (Stationary) | | Flux (Stationary) (Time Varying) | Transform |

* It requires a relative motion b/w time in varying flux & the conductor in order to get flux linkage.

* If the flux is time varying it automatically links with the conductor which are stationary.

* A/c to Faraday's law it requires three basic things in a generator.

1. Flux
2. Conductor
3. Prime Mover.



* For polarity -
 Flux going away - (-ve)
 Flux coming toward - (+ve)

* Fleming Right Hand Rule.

Fore Finger - Flux

Thumb - Direction of Rotation (motion)

Middle - Direction of current/emf.


* DC Generator - Commutator = Alternator.

* Consider a simple coil rotating clock wise b/w a pair of poles (North & South).

* Considering successive points 1 to 5 the conductor is under the influence of South poles which has one polarity induced emf. The same conductor from 5 to 1 is under the influence of North pole which has an induced emf of opposite polarity.

* At position 1 & 5 the conductor movement is exactly parallel to flux line due to which it will not cut flux & the induced emf is zero. (Axis along 1 & 5 is known as Magnetic Neutral axis which is always 90°


to the flux lines. In position 3 and 7 the conductor rotation is quite perpendicular to the flux lines due to which it will cut max^m line or max^m flux linkage & induced emf is max^m.



$$e = N \frac{d\phi}{dt} \text{ volts}$$

$$e = B l v \sin \theta \text{ volts}$$

\downarrow Flux Density \downarrow Active length \downarrow Peripheral Velocity





Alternating
Bidirectional

θ = angle b/w conductor rotation & flux

conclusion

When a conductor rotates b/w North & South poles an alternating voltage/current is induced which need to be converted in dc. In AC Generator ac is collected as a.c but in a dc generator it is collected through rotating commutator & brushes.

□ ACTION OF COMMUTATOR



If the commutator doesn't rotate alternating voltage can't be rectified as the commutator converts bidirectional (A.C) into d.c by virtue of its rotation it is also called as mechanical rectifier. Due to this reason dc m/c having rotating armature (wdg) & stationary field.

~~field~~


□ CONSTRUCTIONAL DETAILS

- COMMON POINTS.

* All rotating electrical m/c have stationary part known as stator and rotating part known as rotor with min^m ^{possible} air gap b/w them.

* Excitation is essentially dc.

* Poles have Multipolar Structure (Alternate North & South poles of even number).



1. YOKE

a) Protective covering.

b) Support poles mechanically (Poles are rivetted to the yoke)





c) It offer flux path completion. If flux per pole is Φ then the flux passing through yoke is $\frac{\Phi}{2}$

d) Therefore yoke should be good magnetic material for

(e) When m/c are operating with power electronic converter laminated yokes are preferred to reduce eddy current loss.

2. POLES.

- * To produce working flux.
- * The basic source of flux is permanent magnet which is uncontrollable in nature. Generally Electromagnets are preferred as they are controllable.



Permeability

↓
ability to permit flux

* EXCITATION



* A current carrying conductor is surrounded by magnetic field. Such a conductor is made into turns & concentrated on a core which is a ferromagnetic material. The current flowing in turns (mmf) will electromagnetise the core & it will act as strong magnet.

The polarity of the pole depends on two factors

(a) Polarity of excitation

(b) Orientation / Sense of wdg

* A pole is nothing but electromagnet which is spread out to distribute the flux uniformly on the armature & to reduce reluctance of air gap. The sp. voltage applied across field wdg is known as excitation which is always dc voltage because it will produce fixed pole.




□ ARMATURE CORE

Electromechanical energy conversion happens in the rotating part of the dc m/c which is normally but nothing but armature core, energy conversion occurs through a coupling medium i.e. magnetic field.

* The core material should be superior magnetic material with high permeability. Generally steel is used but steel has high conductivity to eddy currents. Therefore cores are laminated & alloyed with silicon around 3.5 to 4% only.

Si-Steel

ElectroTechniq
(alloy)




* By adding Si to steel the conductivity reduces without disturbing magnetic properties. Silicon also has low hysteresis coefficient 1.6. consequently produce less hysteresis loss.

* Armature core is made up of thin sheets of silicon-steel 0.4 to 1mm thickness - with a layer of insulation on either side. Each lamination act as individual core to form single core.

* The purpose of armature core is to hold conductor (wdg) which is punched into slots on the outer periphery. It is mounted on a shaft. G

□ COMMUTATOR.



Hard drawn copper segment.

Commutator is a split ring which is also mounted on shaft rotating with coil. It is made up of hard drawn copper segments with 0.8 mm thickness mica insulation.

Armature coils are connected in series through commutator. No. of commutator segments = No. of coils.

It is the image of wdg inside.

BRUSHES.

Brushes are stationary sliding contact placed on a commutator through brush holder & the spring. They offer electrical connection b/w stationary load & rotating commutator.

The collection of current should be ^{as} sparkless as possible which is known as successful commutation.

In order to achieve successful commutation the mechanical condⁿ as well as electrical condⁿ of the brush should be perfect.


Brushes are always placed on MNA for the commutation to be successful.

The brush material used are copper, carbon & Electro graphite. Generally carbon brushes are preferred as they improve commutation.

□ SHAFT AND BEARINGS.



The armature is keyed to the shaft which is held by the stator through bearings to give mechanical Σ/p or to collect mechanical Σ/p .

□ ARMATURE WINDING.




1 Turn = 2 conductor


* Conductors made into turns & multi turns to become coils which are arranged in series distributed uniformly through the peripheral of the armature core in order to improve the shape of waveform.



Concentrated in one coil
(All conductor)




Distributed wdg



Distributed uniformly


CONDUCTOR :- The length of wire lying in the magnetic field where emf is induced is known as conductor.




TURN :- Two conductor makes one turn.

$$\text{For } z \rightarrow \frac{z}{2}$$

COIL :- A coil consists of one or more turns. If there is only one turn in coil it is single turn coil (not used practically). Generally multi-turn coil are used which contains two or more no. of coil.




A coil has two coil sides which are placed in the slots with a coil span.



POLE PITCH : It is the peripheral distance b/w two adjacent pole.

Full pole pitch can be expressed






If $\gamma_s = \gamma_p$ Full pitched



COIL SPAN :

- * Distance b/w two coil sides of a coil.
- * If coil span is exactly to pole pitch it is full pitched coil where max^m emf is induced with in the coil.
- * DC armature wdg are full pitched wdg only.

360 Mech



$720^\circ \text{ E} \Rightarrow 4 \text{ poles}$



180° Elec
°: 6 poles.

$$Q_m = \frac{Q_e}{P/2}$$

$$Q_{elec} = \frac{P}{2} \cdot Q_{mech}$$

* There are always 180° elec degree under ^{one} pole.
Therefore 1 pole pitch is 180° electrical.

□ SINGLE LAYER WINDING.

If there is one coil side in one slot it is single layer wdg.



□ DOUBLE LAYER WINDING.

If there are two or more coil side in one slots arranged in two layers it is double layer wdg.

□ MULTIPLEX WINDING.

DC wdg are ^{completely} closed wdg set of wdg. If there is only one set it is simplex wdg. Where multiplicity factor is equal to 1.

If there are two such independent closed set of wdg

on the same armature it is duplex & multiplicity factor is 2.

Simplex ; $m = 1$

Duplex ; $m = 2$

Triplex ; $m = 3$

Quadruplex ; $m = 4$

* Multiplex wdg increases the current rating & the loading capability of m/c for

* For given no. of conductors multiplex wdg is increased current rating while decreasing voltage rating.

These are more advantageous in wave windings than lap windings.

3] FRONT END

The End where commutator is connected.

BACK END

The other end of commutator.

FRONT PITCH

No. of conductors spanned by one coil at the front end of the armature.

BACK PITCH

No. of conductor spanned by one coil at the back end of the armature.

COMMUTATOR PITCH.

No. of commutator segments b/w two successive coils

RESULTANT PITCH.

Distance b/w starting of first coil & its next successive coil.

27/06/14

TYPES OF WINDINGS.









Fig: open




LAP WINDING:



$y_b = +ve$
 $y_f = -ve$

$y_b \neq y_f$



$y_b - y_f, y_b > y_f \rightarrow +ve$

$y_b < y_f \rightarrow (-)ve$

Full pitched:

$$Y_b = Y_p = Y_b = Y_f$$

$$Y_A = \frac{Y_b + Y_f}{2} = \frac{Z}{P} \quad \text{--- (1)}$$

$Y_b \neq Y_f \rightarrow$ odd no. preferred.

$$Y_b - Y_f = \pm 2m \quad \text{--- (2)}$$

$Y_b > Y_f \rightarrow$ Progressive Right hand winding.

$Y_b < Y_f \rightarrow$ Retrogressive Left hand winding.

NOTE: Both Y_b and Y_f should be odd numbers in order to get symmetric wdg.

* $Y_b \neq Y_f$ because both have opposite sign to form lap winding.

Que:- Let $Z=24, P=4$. Design simplex, Lap, progressive.

solⁿ: $Y_A = \frac{Y_b + Y_f}{2} = \frac{Z}{P} = \frac{24}{4} = 6 \Rightarrow Y_b + Y_f = 12$

$$Y_b - Y_f = 2$$

$$\Rightarrow \frac{Y_b - Y_f}{2} = 1$$


$$\Rightarrow 2Y_b = 14$$

$$\Rightarrow Y_b = 7$$


$$\Rightarrow Y_b = 7, Y_f = 5$$

winding table.

$Y_b = 7$	$Y_f = 5$
$1 + 7 = 8$	$8 - 5 = 3$
$3 + 7 = 10$	$10 - 5 = 5$
$5 + 7 = 12$	$12 - 5 = 7$
$7 + 7 = 14$	$14 - 5 = 9$
$9 + 7 = 16$	$16 - 5 = 11$
$11 + 7 = 18$	$18 - 5 = 13$
$13 + 7 = 20$	$20 - 5 = 15$
$15 + 7 = 22$	$22 - 5 = 17$



* The no. of parallel path A significantly depends on no. of poles and multiplicity



Simplex

$$A = P \cdot m$$

$$A = 4 \cdot 1 = 4$$

Duplex, $A = P \cdot m = 4 \cdot 2 = 8$

Triplex, $A = P \cdot m = 4 \cdot 3 = 12$

* Lap wdg is known as parallel wdg

$$A = P \cdot m$$

* If there is more no. of parallel path current capacity will increase.

* Lap wdg = High current, Low voltage.

EQUILIZER RING : ↓

Due to any ^{un}balance induced emf across a parallel path there will be ~~unbalance~~ circulating current which interfere commutation process & cause unwanted sparking. In order to by pass these circulating current equipotential coil are tapped to respective equilizer ring located at the back end of the armature.


Equipotential coil are located at twice the pole pitch distance (360° electrically apart).

$$\text{Equipotential point} = \frac{\text{No. of conductors}}{P/2}$$

Equilizer ring is a thick solid copper conductor with low resistance. Any circulating current will be by pass through it which is at back end & doesn't enter at front end where there is commutator.

NOTE: In Lap Equilizer ring are essential due to more parallel path & any unbalance is predominant.

WAVE WINDING.



$$y_c = \frac{\text{No. of comm. segment} + 1}{\text{No. of Pairs of poles}} ; y_c = \frac{Z \pm 1}{P/2}$$

The tech. difference b/w Lap & wave lies in commutator pitch.


$$y_b = y_f \text{ or } y_b - y_f = \pm 2m ; y_A = \frac{y_b + y_f}{2} = \frac{Z \pm 2^k}{P}$$

generally done

* y_A should be integer.

$$y_c = \frac{Z/2 \pm 1}{P/2} ; y_R = y_b + y_f \quad A = 2 \cdot m$$

NOTE: The no. of parallel path are independent of no. of poles but depends on multiplexity.



Pole	Paralle path	
	Lap	wave
2	2	2
4	4	2
6	6	2
8	8	2
10	10	2


- * It is known as series wdg / 2 crt wdg.
- * High voltage rating & low current rating.
- * No need of equalizer ring because any unbalance will effects both path equally.

□ DUMMY COILS.

Ex:- Design wave wdg for 60 conductor, 15 slots, 4po m/e.

$$\text{Sol}^n :- \gamma_A = \frac{\gamma_b + \gamma_f}{2} = \frac{Z \pm 2}{P} = \frac{60 \pm 2}{4} = \frac{62}{4} \text{ or } \frac{58}{4}$$

$\therefore \gamma = 58$ to become integer
 $Z \neq 62$ because there is 15 slots only.
 $\frac{62}{4} = 15.5$ $\frac{58}{4} = 14.5$
 Not integer.




For some set of data γ_A will not be integer for such cases nearest possible no. of conductor is selected which results mechanical unbalance. In order to make the m/e balanced mechanically the missing conductors are

well insulated & placed in the missing slot as dummy not electrically connected to the rest of winding.


Ques:- Consider a 4 pole, Lap wound armature with 8 conductor which is reconnected as wave with the same conductor.

Solⁿ:- $Z=8, P=4$. Lap. $\therefore A=4$.

wdg can be represent as \rightarrow



For wave, $A=2$



$I \propto \text{No. of Parallel path (A)}$
 $V \propto \frac{1}{A}$

$$\frac{A_L}{A_w} = \frac{I_L}{I_w}$$

$$\frac{A_L}{A_w} = \frac{V_w}{V_L}$$

$$P_L = P_w$$

$$I_L^2 R_L = I_w^2 R_w$$

$$A_L^2 R_L = A_w^2 R_w$$



Ques: A 4 pole lap wound dc generator is reconnected as wave what will be change in voltage, current & power rating?

Solⁿ:- $A_L=4, A_w=2$

$$\Rightarrow \frac{4}{2} = \frac{I_L}{I_N} \quad \text{and} \quad \frac{4}{2} = \frac{V_{L0}}{V_L}$$

Ques:- 4 Pole lap wound dc generator is operating with 4 brushes. If one brush get damaged what will be changed in voltage & current rating.

Solⁿ:-



Two path only.

$$\therefore V \rightarrow V$$

$$I \rightarrow I/2$$

$$P \rightarrow P/2$$

Two adjacent brushes are damaged:-


one parallel path

$$V \rightarrow V$$


$$I \rightarrow I/4$$

$$P \rightarrow P/4$$

Two opposite brushes are damaged :- Zero.



□ RESISTANCE OF ARMATURE WINDINGS.



x = Resistance of one conductor

Z = No. of conductor

A = No. of parallel paths.

No. of conductor in series per parallel path = $\frac{Z}{A}$

Total Resistance of each ^{parallel} path = $\frac{x \cdot Z}{A}$

$$\therefore R_a = \frac{x \cdot Z}{A^2}$$

Total Resistance of armature wdg.

□ E.M.F. EQUATION:

Let P = Poles

Φ = Flux / per pole wb.

Z = No. of conductor

A = No. of parallel paths

N = Speed of rotation of Armature (rpm)

$\frac{N}{60}$ = rps.

Acc. to Faraday's Law

Avg. emf induced, $e = \frac{N d\Phi}{dt}$ Volts.

Avg. emf induced in one conductor / parallel path, $e = \frac{d\Phi}{dt}$

$d\Phi = P\Phi$ and $dt = 60/N$

$$\Rightarrow e = \frac{P\Phi}{60/N} \Rightarrow e = \frac{P\Phi N}{60}$$

Avg. emf induced per parallel path, $e = \frac{NP\Phi}{60} \cdot \frac{Z}{A}$ Volts

$$\Rightarrow E_a = \frac{NP\Phi Z}{60A} \text{ Volts}$$

$$E_g \propto \Phi N$$

Electro magnet

$$\frac{E_{g2}}{E_{g1}} = \frac{\Phi_2}{\Phi_1} \cdot \frac{N_2}{N_1}$$

Field Ampere Turn = mmf = NI

$$\frac{E_{g2}}{E_{g1}} = \frac{\Phi_2}{\Phi_1}$$

Speed constant

$$\frac{E_{g2}}{E_{g1}} = \frac{N_2}{N_1}$$


Flux constant

CLASSIFICATION OF DC GENERATORS

In order to control the terminal voltage of a generator flux should be controllable. Therefore electromagnets are used which require excitation (d.c voltage) & field wdg

Generators are classified a/c to method of excitation.


1. Separate Excitation.



1. SEPARATE EXCITATION.

$$E_g - I_a R_a - B.C.D = V$$

Where B.C.D = Brush contact drop




E_g : Generated / Induced Emf
 V : Terminal Voltage

- * It requires separate DC source for exciting the field wdg due to which it is not used for commercial applⁿ. It is used in special applⁿ only.
- * Its excitation is independent of terminal voltage & load variation.

SELF EXCITATION

The field wdg is excited by its own armature. (It requires a residual flux & necessary condⁿ to be satisfied)

SHUNT EXCITATION




$$E_g - I_a R_a - B.C.D = V$$

$$I_a = I_L + I_{sh}$$

$$* I_{sh} = \frac{V}{R_{sh}}$$

* voltage operated field.





In this method of Excitation the field wdg is connected in parallel with armature wdg through brushes called as Shunt generator. It's terminal voltage act as excitation.

It's field wdg consists of large no. of turns with thin conductor & its resistance value is very high (50-250 Ω) But armature resistance $< 1 \Omega$.

$$R_{sh} \rightarrow 50 - 250 \Omega, R_a \approx 1 \Omega.$$

* The flux remains approximately constant from no load to rated load condⁿ.

③ SERIES EXCITATION.



$$E_g - I_a (R_a + R_{se}) - BCD = V$$




$$I_a = I_{se} = I_L$$

* As the load current flows in the field wdg it requires thick conductor with less no. of turns

4] COMPOUND EXCITATION.

It contains both Shunt as well as Series excitation. The field wdg has two parts major part in Shunt & minor part in Series. Shunt fluxes always dominant series flux under normal operating condⁿ.

$\Phi_{sh} - \Phi_{se} \rightarrow$ Differentially
 $\Phi_{sh} + \Phi_{se} \rightarrow$ Cumulatively Compounded



$$E_g - I_a (R_a + R_{se}) - B.C.D = V$$

$$I_a = I_L + I_{sh}$$

$$I_{sh} = \frac{V}{R_{sh}}$$

Fig:- Long Shunt

* If the current flowing in both wdg is in the same direction both fluxes will add each other & net flux out of pole increases. Known as cumulatively compounded generator. If series field wdg terminals are reversed than series flux opposes shunt flux & the generator is differentially compounded generator.

Depending on the connection of Shunt field wdg across the armature it is again subdivided into long shunt & short shunt.

Both are identical in operating characteristics.




Fig :- Short Shunt.

Long shunt —→ cum.
—→ Diff.

Short —→ cum.
—→ Diff.

$$E_g - I_a R_a - I_L R_{se} - B.C.D = V$$

$$I_a = I_L + I_{sh}$$

$$I_{sh} = \frac{V + I_L R_{se}}{R_{sh}}$$

□ COMPOUNDING.

* Adjusting the series field ampere turns to vary the terminal voltage to be exactly rated, above rated or below rated at rated load

* Compounding is done to cumulatively compounded generator only by connecting a diverter (variable resistor) across its series field wdg.

* On no load compound generator is equivalent to shunt generator.

$$\phi_{sh} \pm \phi_{se} \text{ if } \phi_{se} = 0.$$

$$\therefore \phi_{sh}$$

* If compounding is done to exactly compensate to all the drops at rated load to make the terminal voltage exactly rated then it is known as flat/level compound generator.

220 - Flat

210 - Under

200 - Cum

* Compounding is done but the terminal voltage is not exactly rated but below rated at rated the load then it is under compound generator.

* If drops are overcompensated by the series flux then terminal voltage is more than rated known as over compounded generator.

In a flat compound generator no load induced emf is equal to rated terminal voltage - at rated load.

* By connecting a diverter & varying its resistance from zero to max^m five modes of operation can be achieved.

$R_d \rightarrow \text{max}$


↑ Over

↑ Flat

↑ Under



↑ Cumulative

$R_d \rightarrow 0$ Shunt /



□ VOLTAGE BUILD UP IN SELF EXCITATION.

Shunt Generator :-



Essential condⁿ

(a) Pole should contain initial Residual flux which can be achieved through field flashing. when the armature rotates conductor cuts Residual flux & small voltage is induced which produced small current. Best condⁿ for voltage build up is Shunt generator should be on no load.

(b) The initial current produces mmf which should add the residual flux. Therefore the field & the armature should be properly connected w.r.t field flashing.

1) (c) ~~Field A part from th~~

2) (c) Field wind properly connected to armature.


3) A part from the 3 condⁿ the resistance of the field wind should be less than critical resistance as well as speed of the generator should be greater than critical speed.

In spite of the above 5 condⁿ if the voltage build up doesn't occur it is due to improper brush contact.

$$\Phi_R \rightarrow E_g \rightarrow I_g$$

$$I_g \cdot N_{sh} \rightarrow \Phi_1 + \Phi_R \rightarrow E_g + E_1 \rightarrow I_g + I_1$$

$$(I_g + I_1) N_{sh} \rightarrow \Phi_2 + \Phi_1 + \Phi_R \rightarrow E_g + E_1 + E_2 \rightarrow I_g + I_1 + I_2$$



Poles gates saturated after a particular field current value. The cumulative voltage build up takes place upto this point, after that voltage becomes constant.


DETERMINATION OF CRITICAL RESISTANCE & CRITICAL SPEED

critical Resistance :- It is the max^m Resistance of field wdg above which the generator does not build up voltage.

critical speed :- It is the min^m speed of a generator below which voltage doesn't build up.


To determine these parameter open circuit characteristics or No load Saturation or Magnetisation Characteristics (E_o Vs I_f) is required.

Note: In order to plot these characteristics self excited generator is separately excited.



S.No	V_f	I_f	E_o
1.	0	0	6-8V
	20	0.1	Linearly
	40	0.2	
	60	0.3	


	220	1A	Saturated



length \cdot $OQ = \text{Volts}$
 let $R_{sh} = 100 \Omega$
 $R_{sh} = 150$

* The intersection of field resistance line with o.c.c. (point P) conveys the max^m voltage shunt generator can build up.

* Plot a tangent of o.c.c. which is nothing but critical field resistance line. Let it meet at point R. draw a line to meet at T.



$$R_c = \frac{\text{length (RT) in volts}}{\text{length (OT) in Amp}}$$

length of (RT) $\rightarrow N_{rated}$ (Known value)
 length of (ST) $\rightarrow N_{critical}$

$$\Rightarrow \frac{RT}{ST} = \frac{N}{N_c}$$

$$N_c = \frac{ST}{RT} \cdot N$$

- * Critical speed for a given speed is only for one value. But critical resistance depends on operating speed. Critical resistance \propto operating speed of generator.

$$R_c = R_{sh} \text{ when } m/c @ N_c$$



workbook

Q10. c.

Q66. b.


Que:- Self excited generator building up voltage normally if its fields terminals are reversed.

- (a) doesn't build up voltage
- (b) build up voltage normally
- (c) build up voltage in (-ve) polarity.
- (d) None of these



Que:- If the direction of rotation is reversed

- (a)
- (b)
- (c)
- (d)



Q.1. Due:- Field wdg as well as direction of rotation reversed.

(a)

(b)



(c)

(d)

Q.2. (a)

(a)

Q.3. VOLTAGE BUILD UP IN SERIES GENERATOR.



* The Necessary condⁿ are similar.

1. Residual flux.

2. Some load should be connected across terminal.

3. Field Armature properly connected.

4. The total resistance of the circuit should be less than critical resistance.

$$(R_a + R_{se} + R_L) < R_c$$

5. Speed of the generator should be more than critical speed.

□ COMPOUND GENERATOR:

A compound generator on no load is equivalent to shunt generator. Therefore voltage build up process is identical to shunt generator only.

□ ARMATURE REACTION.

Separately excited, $I_a = I_L$

Shunt gen. $I_a = I_L + I_{sh}$

Series gen. $I_a = I_L$

Compound gen. $I_a = I_L + I_{sh}$


$$I_{sh} = \frac{V}{R_{sh}} \rightarrow \text{low.}$$

* When the m/c is on no load the armature current is negligible there will be only main flux distributed uniformly throughout the armature in the air gap. When the m/c is loaded load current flows through armature conductors & turns produces armature mmf & armature flux which is also distributed throughout the peripheral of the armature (in the same air gap). The effect of armature flux on main field flux distribution in the air gap is called as armature reaction. It has two effects on the m/c :-

1. cross magnetisation.
2. De magnetisation.

↓
Distortion of ϕ_{main} flux which affect commutation process by shifting MNA.

2. De-Magnetisation :- It is reduction in flux which reduce induced emf of terminal voltage.




* Depending on direction of rotation the pole tips are defined as leading & trailing pole tips. The armature flux under trailing pole tips is magnetising in nature & under the leading pole it is demagnetising the main flux. Consequently the

main flux gets distorted which shifts MNA in the direction of rotation of generator to some angle θ .

If the magnetisation & demagnetisation under a pole is equal there is no net reduction in flux only distortion. Due to Magnetic Saturation of the trailing pole tips the demagnetisation under leading pole tips is slightly more than magnetisation under trailing pole tips. Therefore there is slight demagnetisation.

* The brushes are always placed on MNA for successful commutation. In order to improve commutation the brushes need to be shifted on to new MNA in the direction of rotation of generator. This leads to additional demagnetisation.

Effect of Brush Shift :-



* Due to brush shift the armature flux will have two component :-

Φ_d = Demagnetising component of armature flux
 Proportional to $\sin\theta$ which reduces main flux depending on brush shift angle θ .

Note:- If there is no brush shift $\theta = 0^\circ$, $\sin\theta = 0$, $\Phi_d = 0$ means no demagnetisation. which means all the armature flux is cross magnetising in nature.

Φ_c = Cross magnetising component of armature flux
 Proportional to $\cos\theta$.


Note:- Brushes are shifted 90° electrical i.e. all Φ_a are then $\Phi_d = \Phi_a$, $\Phi_c = 0$ that means all the armature flux is demagnetised.

□ DEMAGNETISING AMPERE TURNS PER POLE:

Demagnetising	Ampere	Turns	Per poles
↓	↓	↓	↓
2θ	$\frac{I_a}{A}$	$\frac{Z}{2}$	means 180° electrical.

* The demagnetisation due to brush shift comes with θ . The conductors lying in the region OAB & OCD offer demagnetisation. The rest of the conductors OAD & OBC offering cross magnetisation. In order to compensate this additional demagnetisation additional field ampere turns need to be provided on each pole.

Therefore demagnetising ampere turns per pole are calculated.



$$\frac{20 \cdot I_a \cdot Z}{180^\circ \cdot A \cdot 2P}$$

$$N_{sh} \cdot I_{sh} = AT_d / P$$

$$\Rightarrow N_{sh(Extra)} = \frac{AT_d / P}{I_{sh}}$$

* No. of extra turns to be added on each to compensate demagnetisation due to brush shift in a shunt generator

$$N_{sh(Extra)} = \frac{AT_d / P}{I_{sh}}$$

For Series Generator,

$$N_{se(Extra)} = \frac{AT_d / P}{I_a}$$

* The total armature ampere turns which produce armature flux. = $\frac{I_a \cdot Z}{A \cdot 2P}$

□ CROSS MAGNETISING AMPERE TURNS PER POLE.

$$AT_c / P : \left(\frac{180 - 20}{180^\circ} \right) \cdot \frac{I_a \cdot Z}{A \cdot 2P}$$

□ OTHERS EFFECT OF ARMATURE REACTION.

1. Decrease in Efficiency. Due to increase iron loss.

Note:- Due to increased flux density under pole tips iron loss increase.

2. Increase maintenance & repair.

Due to sparking the brush surface get damaged which needs regular maintenance & repair.

Increased design cost. In order to compensate armature IR^2 effect the design cost increases.


METHODS TO REDUCE ARMATURE IR^2 AND ITS EFFECTS

Pole stacking.


pole chamfering.

pole core slotting.


Compensating windings.




POLE STACKING:- poles are also made up of steel lamination. Each lamination is made into two half and stacked together to get alternate position. This will introduce high reluctance pole tips in order to reduce flux density & iron loss but net reluctance in mp increases which demands more mmf.




POLE CHAMFERING:- Min^m reluctance at the centre of the pole & increased reluctance towards pole tips. The concept is similar to above cases.



3. POLE CORE SLOTTING: The pole core is also slotted to introduced air gap which offer reluctance to armature flux & reduces it to some extent.



4. COMPENSATED WINDINGS:



- * Large rating dc m/c operating at high speed & varying load condⁿ requires compensating wdg essentially. The varying load produces variation in armature flux which links with the same armature conductors & produces statically induced emf. This leads to circulating currents & sparking at the brushes. Due to high speed it results in flash over.
- * compensating wdg is placed in pole shoe which is also slotted. It is always connected in series with armature through brushes in order to have automatic neutralisation of armature flux.

Note:- The direction of current flowing is compensated wdg in any pole shoe should be exactly opposite to current direction ⁱⁿ of the armature conductor under that pole.

Z_c = Compensating conductor


$$\Rightarrow Z_c \cdot I_a = Z \cdot \frac{I_a}{A} \quad \Rightarrow Z_c = \frac{Z}{A}$$

All the total armature flux is to be nullify by placing compensating wdg on each pole. Therefore compensating wdg conductors required on each pole face = $\frac{Z}{A \cdot P}$

$$Z_c = \frac{Z}{A \cdot P}$$

* $\frac{\text{POLE ARC}}{\text{POLE PITCH}}$ FACTOR

$$\frac{\text{Pole arc}}{\text{Pole pitch}} \approx 0.7$$





$$Z_c = \frac{Z}{A \cdot P} \cdot \frac{\text{Pole arc}}{\text{Pole pitch}}$$

□ COMMUTATION.


* Process of current reversal in the coil when it passes a brush is known as commutation. The short period where the coils remains in contact with brush is known as commutating time (T_c). If the current is completely reverse within the commutating time then the commutation is successful also called as called a linear/ideal/straight line commutation.

* If the current doesn't reverse within commutating time completely it then it produce sparking at the brushes and the commutation is not successful also called non-linear.





The current flowing through brushes is directly proportional to brush contact area.



Inductor (does not accept sudden change)

under practical condⁿ the coil undergoing commutation contain self inductance property which doesn't allow the complete change in current within the commutating time. Consequently the unchanged current will jump into the brush through sparking across trailing tip of the brushes.

Reactance voltage, e_x

There will be self induced emf in the coil under going commutation known as reactance voltage.

A/c to Lenz law the resultant opposes its cause.

$$\text{Reactance voltage, } e_x = L_{\text{self}} \frac{2I}{T}$$

The reactance voltage is opposing the change in current in the coil undergoing commutation. This reactance voltage need to nullified to improved commutation.

□ METHODS TO IMPROVE COMMUTATION.

1. Resistance commutation.
2. Emf/voltage commutation.

1. RESISTANCE COMMUTATION :- Replacing low resistance * Copper brushes with high resistance carbon brushes improve commutation.

: ~~Cu~~ → 1V brush drop

carbon → 2V brush drop ✓

* Due to the increased brush resistance it will not encourage sparking & any unchanged current will be forced to flow through coil itself.


* Carbon brushes have added advantages like :-

(a) They are smooth & self polishing in nature.

(b) They damaged less than Cu brush when sparks occurs.

* Drawbacks is due to low current density which requires increased size in the brush & brush holder. It also produce more brush contact drop than Cu.

2. VOLTAGE COMMUTATION :-




Brush Shift :-

This is first method of improving of commutation but not used after the invention of interpoles.

It is not a reliable method as the shifting of MNA from GNA depends on load. The brushes can't be shifted continuously w/c to load condⁿ once they are designed for particular load. However there is additional demagnetisation due to brush shifting.

INTERPOLES / COMMUTATING POLES / COMPOLES.



* Interpoles are small poles compared to main pole tapered in shape located b/w the main pole riveted to the same yoke these are also electromagnet should not get saturated easily. Due to this reason

their shape is narrow & the air gap under them is comparatively more than main pole.


* Interpoles act in the interpolar region on the coil undergoing commutation in order to neutralize the reactance voltage in that coil. Consequently rate of change of current is successful. It also perform another function it removes the inequality in the flux densities in the top & bottom half of the m/c.

* This is achieved by correctly selecting interpole polarity
 The polarity of interpole = polarity of main pole ahead of generator's rotation.

* Interpole wdg should be connected in series with the armature in order to have automatic neutralisation of the armature flux in the interpolar region.


* Interpole wdg turn should be selected a/c to cross magnetising ampere turn practically there will be 20 to 30% additional turns on the interpole to accomplish two function successfully, depending on additional flux density.

* As the load current flows in the interpole wdg it should not get easily saturated in order to offer automatic neutralisation.



- 1 → 3 ↓ (-ve)
- 3 → 5 ↑ (+ve)
- 5 → 7 ↓ (+ve)
- 7 → 1 ↑ (-ve)
- 3 → 1 ↑ (-ve)

$$\text{Armature flux} = \frac{\text{Armature m.f.}}{\text{Reluctance (air gap)}}$$



- * Main field flux distribution is flat topped or trapezoidal.
- * Armature mmf is triangular in shape, towards brush axis.
- * Armature flux is Saddle (or triangular) in shape.
- * Net flux due to armature & MF is peaked, in shape.

Reluctance:

- max ① → 2 ↓
2 → 3 min
3 → 4 ↑
4 → 5 max
max ⑤ → 6 ↓
6 → 7 Min
7 → 8 ↑
8 → 1 Max

$$\text{Armature Flux} = \frac{\text{Armature mmf}}{\text{Reluctance (airgap)}}$$
$$\text{Flux} \propto \frac{1}{\text{Reluctance}}$$

* The armature flux & main flux are ^{is} quadrature to each other.

* With the presence of armature flux main flux is distorted & the neutral zone (MNA) is shifted in the direction of rotation of generator. Therefore to improve commutation brushes should be given a forward shift.

* With respect to poles the armature flux is stationary

WORKBOOK.

Q62.

Armature Amp Turn/p.

$$\frac{50}{6} \times \frac{720}{2} / 6 = 500 \text{ AT Triangular}$$

□ FACTORS AFFECTING TERMINAL VOLTAGE (V) OF DC GEN.

* On no load there is no armature r_a^n effect & there is no voltage drop due to resistance.

Let the induced emf on no load be E_0

due to load, there will be slight demagnetisation due to armature r_a^n . Therefore induced emf reduced to E_g

$$E_0 - E_g = \text{Armature } r_a^n \text{ drop.}$$

* Due to armature resistance there will be armature resistance drop (brush contact drop is included in that)

* In a Separately Excited generator there are only above two factors affecting the terminal voltage but in self excited shunt generator there is an additional third factor as the excitation is its terminal voltage.

Reduction in V Intern reducing the terminal voltage itself.


CHARACTERISTICS

No load characteristics — (E_o Vs I_f)

Load characteristics —
 Internal (E_g Vs I_a)
 External (V Vs I_L)

* To know the suitability of the appl^d characteristics need to be plotted b/w the key parameter of m/c.

Separately Excited Generator :-



Application.


* It requires additional source for the excitation due to which it is rarely preferred for ordinary dc power supplies.

* It is used in 'Excitation System' of alternators (power plant generators).

DC power supplies in Air crafts, Ships etc.

Ward Leonard Speed Control method.

Shunt Generators



* From no load to rated load condition the flux is approximately constant but beyond rated value reduction in terminal voltage will significantly affect flux & internal terminal voltage. Therefore the generator can't be operated beyond that current value known as breakdown point.

* In its operating region the shunt generator can be approximated as nearly constant dc voltage source.


* Flux or terminal voltage can be adjusted with shunt regulator.

* It has drooping characteristics & best suited for \parallel operation.

Application

- * It is used in Battery charging, small rating DC power supply.


Series Generator :



- * Series generator has rising characteristics also known as variable voltage generator.
- * It is not suitable for ordinary power supply but used as boosters in DC distributors especially for long feeders.
- * Not suitable for parallel operation because it has rising characteristics.

Cumulative compound Generator :

- * Due to presence of series flux which is adding to shunt flux its voltage characteristics are better than separately or shunt generator. Depending on the degree of compounding cumulative compound generator can be operated as flat, over, under compounded.




Application

☐ DIFFER

* widely manufactured dc generator as it has flexible characteristics used in large rating dc power supply.


Differentially compound generator is

$$\phi_{sh} - \phi_{se}$$



Applications

It is used only for Arc welding.



VOLTAGE REGULATION.

Defⁿ: The change in terminal voltage when the rated load across its terminal is disconnected (provided speed and flux should be constant)

* It is expressed in terms of rated terminal voltage.

It is the % drop. It should be as min^m as possible.

Best value is zero.

Flat compound generator has best or ideal voltage Regⁿ.

Series & overcompound generator have (-)ve voltage Regⁿ.

(Not suitable for ordinary power supply).

PARALLEL OPERATION.

The basic objective of // operation is to provide an electric system of high electric inertia.

Due to large no. of generators operating in // across


Common terminal known as bus bar (also called some time infinite bus bar). The variation in terminal voltage of any one generator will hardly make a significant impact on the entire system.

* It also provides :-


1. Reliable System.
2. Increases η .
3. Future Expansions.
4. Rota Routine Maintenance & Repairs.

* To operate two dc generator in parallel it requires two necessary condⁿ :-

1. Terminal Voltage should be same.
2. polarities should be same.



* Consider two dc generator operating across bus bar in parallel at a common terminal voltage 'V' sharing a common load with induced emf E_{g1} , E_{g2} & current I_1 , I_2 respectively.



$$E_{g1} - I_1 R_{a1} = V$$

$$E_{g2} - I_2 R_{a2} = V$$

$$\Rightarrow I_1 = \frac{E_{g1} - V}{R_{a1}}$$


$$I_2 = \frac{E_{g2} - V}{R_{a2}}$$

↓
Load current shared by generator 1


* The load sharing b/w the generator significantly depends upon their induced emf.

For stable parallel operation the voltage characteristics of generator should be slightly drooping in nature.

Series generator in parallel :-



- * Let us assume two series generator operating in parallel sharing a common load if any one generator shared more load its flux increases & consequently E_g and load sharing capability increases. Due to which it get overloaded leaving the other generator underloaded due to cumulative action this will not offer stable parallel operation.
- * In order to make them parallel an equalizer bar need to be connected.
- * Cumulative compound generator requires also equalizer bar for stable parallel operation as they contain series flux.
- * Shunt generator are best suitable for parallel operation due to their drooping characteristics.



- * The generator with more drooping characteristics will share ^{less} ~~more~~ load & vice versa.

DC MOTOR.


* DC motors are more popular than any a.c. motor when it comes to highest starting torque & wide range of efficient & accurate speed control. The same dc generator can be operated as dc motor.

* PRINCIPLE

When a current carrying conductor is placed in a magnetic field it will experience a mechanical force which magnitude is given by

$$F = B i l \text{ Newtons}$$


and direction A/c to Fleming left hand rule also known as motor rule.



* consider a simple coil supplied with dc voltage through brushes & commutator placed b/w north & south pole. A/c to F.L.R. for the same rotation in the case of generator the motor will rotate in opposite direction.


Note: For example the generator rotates clockwise & the motor rotates anticlockwise the purpose of commutator is to provide unidirectional torque in the conductors.

□ MOTOR ACTION IN A GENERATOR.




* Consider a generator rotating clock wise. The current carrying conductors in a generator will experience a force a/c to motor principle because current carrying conductors placed in magnetic field. The direction of force is a/c to F.L.R applying this to a generator the force on current carrying conductor is exactly opposite to the direction of rotation of generator. The prime mover will experience this backward force known as motor action in a generator.

□ GENERATOR ACTION IN MOTOR.



$$E_b = \frac{NP\phi Z}{60A} \text{ Volts}$$

Back / count emf.



* Consider motor running in its pole anticlockwise direction. As the conductor cuts the flux emf is induced which is given by Fleming's Right hand rule. By applying it the induced emf is exactly opposite to supply voltage. Therefore it is called as back emf or counter emf.

Electro mechanical Energy conversion occurs through opposition.


According to basic laws of nature any energy conversion from one form to other occurs through opposition.

CLASSIFICATION OF DC MOTOR


Generator & motor are having identical construction.

And basic dc motor classification is as follows.

Separately Excited



SEPARATELY EXCITED DC MOTOR




$$V = E_b + I_a R_a + B e d$$

$$I_a = I_L$$

* Used as Servomotor & Spt. applⁿ.

2. SHUNT MOTOR.




$$V = E_b + I_a R_a + B e D$$

$$I_L = I_a + I_{sh}$$

$$\Rightarrow I_{sh} = \frac{V}{R_{sh}}$$

* As the supply voltage is maintain constant for normal operating cond it is a constant flux motor (Neglecting armature \times demagnetizing).


SERIES MOTOR.



$$V = E_b + I_a (R_a + R_{se}) + B e D$$

$$\Rightarrow I_a = I_{se} = I_L$$

COMPOUND MOTOR : LONG SHUNT.




$$V = E_b + I_a (R_a + R_{se}) + B e D$$

$$\Rightarrow I_L = I_a + I_{sh}$$

$$I_{sh} = \frac{V}{R_{sh}}$$

SHORT SHUNT





$$V = E_b + I_a R_a + I_L R_{se} + BCD$$

$$I_L = I_a + I_{sh}$$

$$I_{sh} = \frac{V - I_L R_{se}}{R_{sh}}$$

COMPARISON B/W GENERATOR AND MOTOR



generator delivers current

$$I_a = I_L + I_{sh}$$

$$E_g > V$$

V is Terminal voltage

E_g = induced generated emf

$E_g I_a$ = Electrical power generated

$V \cdot I_L$ = Electrical o/p or Power delivered to load.

$$E_g I_a - V I_L = \text{Total cu loss}$$

Motor draws current

$$I_L = I_a + I_{sh}$$

$$E_b < V$$

V is Supply voltage.

E_b = induced emf / back emf

$E_b I_a$ = Electrical equivalent of mechanical power developed in armature.

$V \cdot I_L$ = Electrical 2/p drawn or supplied.

$$V \cdot I_L - E_b I_a = \text{Total cu loss}$$

□ SIGNIFICANCE OF BACK EMF.

* It forms the role of opposition for electromechanical energy conversion.

$$* V = E_b + I_a R_a$$

Multiplying by I_a ($I_a \approx I_L$)

$$\Rightarrow V I_a = E_b I_a + I_a^2 R_a$$

$$\Rightarrow \text{O/P} = \text{O/P} + \text{Loss}$$

$$\Rightarrow \eta = \frac{\text{O/P}}{\text{I/P}} = \frac{E_b I_a}{V I_a} = \frac{E_b}{V} \Rightarrow \boxed{\eta \propto E_b}$$

* Efficiency of motor significantly depends on back emf (E_b should be nearer to V but not equal or greater than V) in order to have motoring operation.

$$* E_b I_a = V I_a - I_a^2 R_a$$

$$P_m = V I_a - I_a^2 R_a$$

$$\frac{dP_m}{dI_a} = 0 \Rightarrow V - 2I_a R_a = 0$$

$$\Rightarrow I_a R_a = \frac{V}{2}$$

$$\Rightarrow \boxed{E_b = \frac{V}{2}}$$

* If the back emf developed in the armature is exactly equal to half of supply voltage then motor developed max^m power developed under such condⁿ. Its efficiency is

$$\text{Only } 50\%. \quad \eta = \frac{E_b}{V} = \frac{V/2}{V} = 50\%$$

* Due to this the motors are not designed to operate at max^m power developed condⁿ but designed to give

max^m η near rated load condⁿ.

* Back emf makes emf self regulating in nature -
By controlling the armature current w/c to load condⁿ.

$$E_b = \frac{NP\phi \omega}{60A} \Rightarrow \downarrow E_b \propto \phi N \downarrow$$

$$\uparrow I_a = \frac{\overset{\text{constant}}{V} - E_b \downarrow}{\underset{\substack{\text{very low} \\ \text{taken as constant}}}{R_a}} \Rightarrow \uparrow I_a \propto \frac{1}{E_b \downarrow}$$


* As the motor is loaded, it has to develop torque by drawing armature current from the supply. During load condⁿ the speed reduces consequently E_b reduced in order to increase I_a . Increase in armature current increases electromagnetic torque developed in armature. If it equal to load torque the motor doesn't reduce its speed further & continues to run at new speed.

* If the load is disconnected the armature speed increases to increase E_b & to reduce I_a . Consequently the electromagnetic torque will reduce & the speed won't rise but the motor runs at its no load speed.

□ TORQUE OF A DC MOTOR

* It is turning or twisting movement of force about an axis which produce mechanical rotation expressed in ~~N-m~~ N-m.

$$T = f \times r$$



$$\begin{aligned} \text{Distance travelled} &= 2\pi r \\ \text{Time taken} &= \frac{60}{N} \end{aligned} \quad \left| \quad \begin{aligned} \text{Power} &= \frac{\text{Work Done}}{\text{Time}} \\ P &= \frac{2\pi r \cdot F}{60/N} \end{aligned} \right.$$

$$\Rightarrow P = \frac{2\pi N (F \cdot r)}{60}$$

$$\Rightarrow P = \frac{2\pi N T}{60} \text{ Watts}$$

$$T_a - T_{sh}$$

When the torque is developed in armature it is not readily available across the shaft for loading. Some part of it is lost while supplying rotational losses.

$$T_a - T_{sh} = \text{Rotational Loss}$$

T_a = Armature Torque.

T_{sh} = Shaft Torque / useful Torque.

$$\Rightarrow P = E_b I_a$$

$$\Rightarrow \frac{2\pi N T_a}{60} = \frac{PN \phi Z}{60 A} I_a \quad \Rightarrow \quad T_a = \frac{1}{2\pi} \cdot \phi \cdot I_a \cdot \left(\frac{ZP}{A}\right)$$

$$T_a \propto \phi \cdot I_a$$

$$\frac{T_2}{T_1} = \frac{I_{a2}}{I_{a1}}$$

($\phi = \text{constant}$)
→ For Shunt Motor.

$$\frac{T_2}{T_1} = \left(\frac{I_{a2}}{I_{a1}}\right)^2$$

→ For Series Motor ($\phi \propto I_a$)
upto saturation.

$$\frac{T_2}{T_1} \propto \phi_{se}^2$$

$$\frac{T_2}{T_1} = \frac{I_{a2}}{I_{a1}}$$

→ For Series motor
After saturation ($\phi = \text{constant}$)

$$N \propto \frac{E_b}{\Phi}$$

$$\frac{N_2}{N_1} = \frac{E_{b2}}{E_{b1}} \times \frac{\Phi_1}{\Phi_2}$$

$$\frac{N_2}{N_1} = \frac{E_{b2}}{E_{b1}} \rightarrow \text{If flux constant}$$


CHARACTERISTICS AND APPLICATIONS.

Torque vs I_a

Speed vs I_a

Speed vs Torque


SHUNT MOTOR.



$$T \propto \Phi_{sh} I_a, \quad I_{sh} = \frac{V}{R_{sh}}$$

$$\Phi_{sh} = \text{constant}$$

$$T \propto I_a$$



$$N \propto \frac{E_b}{\Phi} \Rightarrow N \propto V - I_a R_a$$

$$\Phi = \text{constant}$$


$$\uparrow N \propto \frac{E_b}{\Phi} ; \text{armature reaction or demagnetisation}$$

Shunt motor has normal starting torque but it has approximately constant speed b/w No load & rated load. Therefore it is also called as constant speed motor. It has speed control in order to run the motor at

any required speed.

Application

It has applⁿ in manufacturing as steel or Aluminium rolling, m/c tools, lathes, centrifugal pumps etc.




2. SERIES MOTOR.

$T \propto \Phi_{se} I_a$

$T \propto I_a \cdot I_a$



$T \propto I_a^2$ (upto Saturation)

$T \propto I_a$ (After ")





$N \propto \frac{E_b}{\Phi_{se}}$

$N \propto \frac{V - I_a R_a}{\Phi_{se}}$



- * Never start a series motor on no load as it speeds becomes dangerously high & damages mechanically.
- * It has highest starting torque which is exclusively used for traction purposes, cranes, hoists etc.
- * It has variable speed which can be adjusted by speed control



3. CUMULATIVE COMPOUND MOTOR.




It is used for high torque & intermittent load for example - shears & punches.

It has a definite no load speed even though there is series flux. The shunt flux will maintain the speed on no load & the series flux will increase its torque with load.

DIFFERENTIAL COMPOUND MOTOR.





- * This motor has no application.
- * On no-load compound motor is equivalent to shunt motor.
- * In differential case as the load increases net flux reduces. Hence reduce the torque. It also has unstable speed.
- * It may run in the reverse direction when motor draws large current.

□ SPEED REGULATION.

- * It is the change in speed when the load on the motor is removed (from rated to no load condⁿ). Expressed in % of speed at rated load.

$$S.R = \frac{N_0 - N}{N} \times 100$$

- * Shunt motor has best speed regulation.
- * Differential motors have negative speed regulation. Without any external control they may have zero speed regulation.

□ SPEED CONTROL

$$N \propto \frac{E_b}{\phi} \propto \frac{V - I_a R_a}{\phi} \quad \text{depends on load.}$$


\swarrow \downarrow \searrow
 ϕ R_a V
 1. 2. 3.

1. Flux / Field current control or Field weakening.
2. Armature Resistance control / Rheostatic.
3. Multiple Voltage control.

* DC motors are most popular due to their simple wide range & efficient speed control.

□ SPEED CONTROL OF SHUNT MOTOR.

1. Field weakening speed control :-




* Connecting some external resistance in series with field wdg & varying it from zero to max^m value the field current & flux varies from rated to min^m and consequently increases Speed.

The speed control is from base or rated to above rated (min^m speed in this method is rated).

- * There is a limit to reduce field current as the speed becomes dangerously high.
- * This is efficient speed control method involves less cu loss in the external resistance, less temp rise, no addⁿ requirement for cooling & no need of bulk reostat.
- * As the main flux is extensively reduced the armature effect dominates. Therefore it requires armature R²
- * Compensating method Interpoles, compensating wdg etc.
- * It requires 4-point starter especially to control the speeds over wide range.
- * Also ~~called~~ Variable torque constant power method.
- * In this method E_b remains constant.
- * During starting the field reostat should be at min^m resistance position.

Armature Resistance control / Reostatic control.



$$V = E_b + I_a R_a$$

$$E_b = V - I_a R_a$$

$$E_b = V - I_a (R_a + R_{ext})$$

$$E_b = V - I_a (R_a + R_{ext}) \quad (\text{Stalling Torque})$$

$\Rightarrow I_a (R_a + R_{ext}) = V$ then, $(E_b = 0)$, $(N = 0)$. Stalling condⁿ.

Inserting external resistance into the armature ckt & by increasing it voltage across the armature is varied consequently speed varied from rated to below rated.

* It requires large rheostat as the current flowing is high. It produces huge cu loss & temp rise. therefore additional cooling method required.

* The motor speed can be reduced by sacrificing its efficiency.

It is less efficient speed control method.

It is called as constant torque variable power speed control.

No need of 4-point starter.

No additional armature reactance effect

During starting the armature rheostat should be at its max^m resistance position.

Note:- By employing both speed control simultaneously the speed of motor can be varied from a min^m value to max^m value over a wide range.


Voltage Control

Q:- A Shunt motor running at 1000 rpm with rated voltage. If voltage is reduced to half what will be the speed?

- (A) 1000 (B) 500 (C) 250 (D) 2000

$$Q:- N \propto \frac{V - I_a R_a}{\Phi}$$

$$I_{sh} \propto V$$




$$\frac{N_2}{N_1} = \frac{V/2}{V} \times \frac{V}{V/2}$$

$$= 1000 \text{ rpm}$$

Multiple Voltage control :-

* Voltage control across shunt exci self excited shunt motor is difficult. It should be separately excited. By using a multiple voltage source voltage across the armature can be directly varied with varying its speeds.

* To control speed of large rating motor particularly under steel rolling condⁿ in either direction from rated to below rated Ward-Leonard speed control method is used. It is very expensive as it required two additional - m/c (i) separately excited generator (ii) motor for its mechanical i/p. :-




- Separately excited generator act as multiple voltage source which can produce voltage in both polarities by changing the cross over switch. The speed of the motor can be varied in both the direction. In order to reduce the speed fluctuations during load variation as well as to improve overall η due to varying load it is modified

by connecting a flywheel across a motor shaft known as Ward Leonard Ignier method.

□ SPEED CONTROL OF SERIES MOTOR.


- 1) Field Diverter. (B) Rheostatic
2. Armature Diverter. (c) Multiple Voltage control.
3. Tapped Field
4. paralleling the field coils.

1) Field Diverter.



As the current diverts series flux reduce & increase the speed. Resistance of diverter should not be made zero value as the speed becomes dangerously high.


Armature Diverter



$T \propto \phi I_a$


* As the armature current diverts the motor reacts to change if there is rated load or constant load on it & draws more current from the supply to maintain the torque which comes from field wdg increases flux & reduces speed.



(v) Tapped Field.




* Field wdg consists of tapping which can be varied through a tap changer. As the tapping are more flux is more speed is less (Vice Versa)

(vi) Paralleling the Field coils






2. Rheostatic control



$$E_b = V - I_a (R_a + R_{se} + R_{ext})$$

* By varying the resistance voltage across the motor is varied. This will lead to additional cu loss & reduce the ϕ . In order to vary the speed without using resistance a multiple voltage source can be adopted.


Workbook
Q26.



$$T \propto \phi \cdot I_a$$

$$T \propto \phi_a I_a$$


$$T \propto I_a^2$$



$$T \propto \phi \cdot I_a$$

$$T \propto \frac{I_a}{2} \cdot I_a$$

$$T \propto I_a^2$$




$$\frac{I_a}{\sqrt{2}} \rightarrow \frac{\text{Flux}}{\sqrt{2}} \rightarrow \text{Speed} \cdot \sqrt{2}$$

⊙ \downarrow

workbook.

Q3.



$$N \propto \frac{E_b}{\Phi_{sh} + \Phi_{se}} \Rightarrow N \propto \frac{E_b}{\Phi_{sh}}$$

\downarrow
zero
Redu

$$\Rightarrow T \propto \Phi I_a \uparrow$$

Q34.

$$P = \frac{E_b \cdot I_a}{2}$$

New, $P = \frac{E_b}{2} \cdot I_a$

$\therefore I_a = 2 I_a$ to develop same pow

$$\frac{N_2}{N_1} = \frac{E_{b2}}{E_{b1}} \times \frac{\Phi_1}{\Phi_2}$$


$$\Rightarrow \frac{N_2}{N_1} = \frac{E_{b1}/2}{E_{b1}} \times \frac{\Phi_1}{\Phi_1/2} \Rightarrow \text{Speed} = \underline{\underline{\text{Same}}}$$

Q38.

$$\frac{N_2}{N_1} = \frac{E_{b1}/2}{E_{b1}} \times \frac{\Phi_1}{\Phi_1} \Rightarrow N_2 = \frac{1}{2} N_1$$

Q69.


25KW, 50KW.



Q24.

$$\frac{N_2}{N_1} = \frac{E_{b2} \times \phi_1}{E_{b1} \times \phi_2}$$

$$= \frac{0.95 E_{b1} \times \phi_1}{E_{b1} \times 1.1 \phi_1} = 863$$



$$E_{b(\text{no load})} = V - I_a R_a$$

$$= 400 - 3(0.5)$$

$$E_{b(\text{no load})} = 398.5$$

$$E_{b(\text{full load})} = V - I_a R_a = 400 - 48(0.5) = 376 \text{ V.}$$

$$\frac{N_{f.L}}{N_{n.L}} = \frac{E_{b f.L}}{E_{b n.L}} = \frac{376}{398.5} = 0.94$$

WORKBOOK

Q46. $V = 200 \text{ V}$, $I_a = 20 \text{ A}$, $R_a = 0.2$

$$\frac{N_2}{N_1} = \frac{E_{b2} \times \phi_1}{E_{b1} \times \phi_2}$$

For gen. :- $\frac{N_2}{N_1} = \frac{E_{b2} \times \phi_{1g}}{E_{b1} \times \phi_{2g}}$

$$\Rightarrow \frac{N_{2m}}{N_{1g}} = \frac{E_{b2} \times \phi_{1g}}{E_{b1} \times \phi_{2m}} \Rightarrow \phi_2 = 1.1 \phi_1 \text{ (given)}$$

$$\Rightarrow E_g = V + I_a R_a = 200 + 20(0.2) = 204 \text{ V}$$


$$E_b = V - I_a R_a = 200 - 20(0.2) = 196 \text{ V}$$

$$\Rightarrow \frac{N_{2m}}{N_{1g}} = \frac{196}{204} \times \frac{\phi_1}{1.1 \phi_1} \Rightarrow N_{2m} = 0.873 N_{1g} \text{ (a) } \frac{1}{2}$$

□ STARTERS.

- * Starter ensures starting resistance to be connected in series across the armature. In order to limit high starting current.
- * If a dc motor is directly started with rated voltage across terminal as the speed is zero there is no back emf. Consequently current drawn by armature is excessively high. As the motor starts quickly back emf proportionally produced & control starting current.
- * Small motors can be directly started as the starting current means inrush / Transient current.
- * But for large motor the high inrush current will produce a voltage dip as well it may damage brush commutator contact and wdg.
- * Apart from starting resistance there are three more function of starter for its operation.
 1. Rst \rightarrow Basic function.
 2. No voltage Release.
 3. Over load Release.
 4. Field Failure prevention.
- * There are three types of starter
 - \rightarrow 3 point starter } shunt & compound
 - \rightarrow 4 point starter }
 - \rightarrow 2 point starter } series.


1. 3- POINT STARTER.



The operation of this Starter depends on field current significantly because the Hold on coil action \propto to field current (I_f). It also provides no voltage release when power supplies fails.

* During overloads the overload relay picks up & short-circuit the hold on coil to loose its magnetic action. As the spring action dominates the starter arm flyback to off position.


2. 4-POINT STARTER



When a motor is subjected to field weakening speed control method a 3-point starter doesn't support the operation because its hold on coil operation is proportion to its field current. For such speed control, 4 point starter is essential for shunt & cumulative compound motor. The hold on coil is isolated from the field wdg & connected to extra point due to which any variation in the field doesn't affect its hold on coil action.

Field failure prevention is absent but it is acceptable as they are not so frequent in nature.

Fig. 2 - POINT STARTER.



* It is exclusively for series motor. It serves all the four functions. It also provides protection against sudden discharge of loads across its shaft as the motor speed becomes dangerously high technically called racing condⁿ.



A 3 point starter can be connected to series motor but with closing the F terminal with (-)ve point.

STARTER RESISTANCE GRADING.

* Starting current should be selected acc to load requirement in the motor. If the motor start with load its starting torque should be more than load torque. Generally starting torque is 1.5 times load current.

$$I_s = 1.5 I_L$$

4 studs
3 Selection $n-1$ Selection.



- * It also control the accelⁿ time as the motor starts
- * During starting as the starter handle passes b/w the studs their current undergoes a transient change b/w a max^m & min^m value.

$$I_1 = \text{max value.}$$

$$I_2 = \text{min value.}$$

At stud ① : $I_1 = \frac{V}{R_1}$

After an instant, $I_2 = \frac{V - E_{b1}}{R_1}$

From ① → ② : $I_1 = \frac{V - E_{b1}}{R_2}$

$$\left. \begin{array}{l} I_1 = \frac{R_1}{R_2} \\ I_2 = \frac{R_2}{R_3} \end{array} \right\}$$

At stud ②

After an instant, $I_2 = \frac{V - E_{b2}}{R_2}$

From ② → ③, $I_1 = \frac{V - E_{b2}}{R_3}$


$$\left. \begin{array}{l} I_1 = \frac{R_2}{R_3} \\ I_2 = \frac{R_3}{R_a} \end{array} \right\}$$

At stud ③

After an instant, $I_2 = \frac{V - E_{b3}}{R_3}$

From ③ → ④ $I_1 = \frac{V - E_{b3}}{R_a}$

$$\left. \begin{array}{l} I_1 = \frac{R_3}{R_a} \\ I_2 = \frac{R_a}{R_a} \end{array} \right\}$$



$$\frac{I_1}{I_2} = \frac{R_1}{R_2} = \frac{R_2}{R_3} = \frac{R_3}{R_a} = K \text{ (say)}$$

$$\Rightarrow R_3 = K \cdot R_a$$

$$\Rightarrow R_2 = K R_3 = K^2 R_a$$

$$\Rightarrow R_1 = K \cdot R_2 = K^3 \cdot R_a$$

$$\Rightarrow \boxed{\frac{R_1}{R_a} = K^3}$$

In general if a stator has n studs there will be $(n-1)$ section. Therefore $\boxed{\frac{R_1}{R_a} = K^{n-1}}$

BRAKING


Braking is done to intensely to stop the motor or some time to control the speed.

There are two types of braking.

Mechanical Braking :- All the kinetic energy ^{is} the rotating part is dissipated as heat which produces noise ^{high} wear & Tear maintenance repair & doesn't offer smooth braking.


2) Electrical braking :- Basic braking is isolating the motor from the supply but it doesn't stop the motor at the required instant quickly. This requires additional braking method.

□ TYPES OF ELECTRIC BRAKING.



* Principle of Electric braking is to produce opposite torque (i.e. torque) ~~in~~ running motor by reversing armature current.

1. DYNAMIC / RHEOSTATIC BRAKING :-




* Disconnecting the armature from the supply leaving its field connected at the instant of braking there will be induced emf E_b which ~~drives~~ ^{drives} braking current into the rheostat externally connected.


This is exactly opposite to the armature current in its original condⁿ. Consequently torque reverses & motor stops quickly.

2. PLUGGING.

Reversing the armature polarity or terminals across the supply through an external resistance in order to control the braking current which becomes more than the normal value.



$$I_a = \frac{V - E_b}{R_a}$$



$$I_a = \frac{V + E_b}{R_a} \quad \text{During plugging}$$

Plugging :-

Voltage across ^{armature} terminals during plugging = $V + E_b$

$$I_a = \frac{V + E_b}{R_a + R_{ext}}$$

Due to reversal of armature current directly the torque reverses & the motor wants to run in its opposite direction due to which it come near zero speed where mechanical braking is applied. Otherwise the motor continues to run in opposite direction.

exbook

3. $V = 240\text{V}, I_L = 15\text{A}, R_a = 0.5\Omega, R_{sh} = 80$

$$I_{sh} = \frac{V}{R_{sh}} = \frac{240}{80} = 3\text{A}$$

$$I_a = I_L - I_{sh} = 15 - 3 = 12\text{A}$$

$$E_b = V - I_a R_a = 240 - 12(0.5) = 234 \text{ V}$$

$$\text{During plugging } \rightarrow V + E_b = 240 + 234 = 474$$

$$1.25 \times 12 =$$

$$1.25 I_a = \frac{V + E_b}{R_a + R_{ext}} \Rightarrow 1.25 \times 12 = \frac{474}{0.5 + R_{ext}}$$

$$\Rightarrow R_{ext} = 31.1 \Omega$$

3. REGENERATIVE BRAKING.

* This is not an intentional braking like above method & it doesn't stop the motor but controls the rise in speed naturally. It is inherent property of the motor when it is subjected to overhauling load condⁿ such as train moving down gradient or a crane lowering its load etc.


* If the increase in speed of the motor increase the back emf to dominate the supply voltage then I_a reverses which produce this braking.

$$E_b \propto \phi N \quad \text{if } N \uparrow \text{ then if } E_b > V$$

$$I_a = \frac{V - E_b}{R_a} \quad \text{then } I_a = (-ve)$$

Braking as well as generating action occurs simultaneously which control speed of motor & motor regains its original mode to run normally. This is very advantageous in mountain railways.


* Series motor are difficult for regenerative braking as the armature current reverses its flux also reverse & its torque is (+)ve. In order to achieve this braking series field wdg is separately excited.



* As the generator

u: A shunt generator connected to bus bar supplying load normally with the prime mover. If the mechanical i/p fails it will act as


- (a) Shunt motor running in opposite direction.
- (b) Shunt motor running in same direction.



$I_a = (-)ve$

Ques: Series generator connected to a bus bar if the mechanical i/p fails.


Sol:



$\Phi_{se} = \text{(-ve)} \ \& \ I_a = \text{(+ve)}$
 \therefore series Motor rotate in opposite dirⁿ.

Note: In such condⁿ as there is no starter & motor start from zero speed due to reverse rotation it draws excessively high current from bus-bar.

Workbook
Q5.



$\Phi_{sh} + \Phi_{se}$
 $\Phi_{sh} - \Phi_{se} = \text{differential}$
 \downarrow
 It dominates $\Phi_{se} \therefore$ run in same direction.

□ LOSSES

1. Iron loss / core loss.
2. Copper / ohmic loss
3. Mechanical loss.

1. IRON LOSS :- As the ^{armature} core rotates it cut the flux emf is induced & produced eddy current loss.

$$W_e = K_e B_m^2 f^2 \tau^2 V \text{ watts.}$$

\downarrow Volume of core

2. COPPER LOSS :- Armature cu loss = $I_a^2 R_a$

Shunt Field cu loss = $I_{sh}^2 R_{sh}$ or $V I_{sh}$

Series Field cu loss = $I_a^2 R_{se}$ or $I_L^2 R_{se}$
Series/long shunt Short shunt

I.P.W resistance }
C.W resistance } I_a
Brush Resistance }

3. MECHANICAL LOSS :-

Friction \rightarrow Brush / Bearing

&

windage \rightarrow Air Friction

* Mechanical losses happens with rotation only & its value proportional to speed.

* Iron loss & Mechanical loss are combinedly known as rotational losses.

* For shunt & compound m/c this loss is approximated as constant as it doesn't depend or vary with load (along with shunt field cu loss)

Total losses = Constant loss + Variable loss

□ CONDITION FOR MAXIMUM EFFICIENCY.

$$\eta = \frac{o/p}{o/p + \text{loss}} = \frac{V I_L}{\frac{V I_L + \frac{W_c}{V I_L} + \frac{I_a^2 R_a}{V I_L}} \quad \because (I_a \approx I_L)$$


$$\text{For } \eta_{(max)} = \frac{d}{d I_a} \left(1 + \frac{W_c}{V I_a} + \frac{I_a R_a}{V} \right) = 0$$

\uparrow
 $I_a \approx I_L$

$$-\frac{w_c}{V I_a^2} + \frac{R_a}{V} = 0 \quad \therefore \boxed{I_a^2 R_a = w_c}$$

In general; Variable loss = constant loss.

□ POWER STAGE DIAGRAM OF A GENERATOR.




$$\eta_{\text{mech}} = \frac{B}{A} = \frac{E_g I_a}{\text{Mech } \frac{2}{p}}$$

$$\eta_{\text{electrical}} = \frac{C}{B} = \frac{V I_L}{E_g I_a}$$

$$\eta = \eta_{\text{mech}} \times \eta_{\text{elec}} = \frac{B}{A} \times \frac{C}{B} = \frac{C}{A} = \frac{V \cdot I_L}{\text{Mech I/p Supplied}}$$

$\begin{matrix} \text{Elec. o/p delivered} \\ \downarrow \\ V \cdot I_L \\ \uparrow \\ \text{Mech I/p Supplied} \end{matrix}$

□ POWER STAGE DIAGRAM OF A MOTOR.



$$P = \frac{2\pi NT}{60}, \quad T_a = \frac{60}{2\pi N} \cdot P, \quad T_{sh} = \frac{60}{2\pi N} (E_b I_a - \text{Rot loss})$$

P_{shaft} or $P_{\text{o/p}}$

$$\eta_{\text{elec}} = \frac{B}{A} = \frac{E_b I_a}{V \cdot I_L}$$

$$\eta_{\text{mech}} = \frac{C}{B} = \frac{P_{\text{shaft}}}{E_b I_a}$$

$$\eta = \eta_{\text{elec}} \times \eta_{\text{mech}} = \frac{B}{A} \times \frac{C}{B} = \frac{C}{A} = \frac{\text{Mech. o/p delivered } P_{\text{shaft}} \text{ or } P_{\text{o/p}}}{\text{Elect. I/p (V} \cdot \text{I}_L)} = \frac{\text{Elect. I/p Supplied.}}$$

□ TESTING

* Testing is done to determine the efficiency and also performance analysis of a m/c.

* It can be done in two ways.

1. Direct
2. Indirect.

* If the m/c is directly load & the η is calculated by measuring its I/p & O/p It is direct way of testing which gives accurate result as all the losses including temp rise is accounted.

INDIRECT :- If the losses are determined in order to predetermined η without actual-loading it is indirect way of testing. It is not accurate compared to direct but large m/c are tested indirectly because of loading constraints.


(A) SWINBURNE'S TEST:-

only suitable for Shunt & compound

→ Run as (M) (A) no load

(A) N_{rated}


→ Apply V_{rated} .



S.No	V	I_L	I_a

$I/p = O/p + \text{LOSS}$

$I/p = \text{LOSS}$



Let $V I_L = 50 \text{ W}$

$I_{a0}^2 R_a = 5 \text{ W} \therefore \text{Constant loss} = 45$

Swinburne's test is all about calculating constant loss
 $R_a = 1 \Omega$

S.No	V	I_L	I_{sh}	I_a	Cu loss	Constant loss	$V I_L$	Total loss
(Full)	220	11	1	10A	100 watt $10^2 \cdot 1$	45 watt	220×11	145
(Half)	220	6	1	5A	25 watt $5^2 \cdot 1$	45 watt	220×6	70

$\eta = \frac{I/p - \text{LOSS}}{I/p}$, $\eta_{full} = \frac{220 \times 11 - 145}{220 \times 11} =$


$\eta_{half} = \frac{220 \times 6 - 70}{220 \times 6} =$

* This test is only conducted to shunt & compound but

& Iron loss vary with load as well as it can't be operated on no load. There will be slight inaccuracy as the iron loss is considered strictly constant.

2. HOPKINSON'S TEST.

→ For shunt/compound.



$$\eta_g = \frac{\text{o/p}}{\text{i/p}} = \frac{\text{o/p of generator}}{\text{o/p of motor}}$$

$$\eta_m = \frac{\text{o/p}}{\text{i/p}} = \text{o/p of motor} = \eta_m \cdot \text{i/p of motor}$$


$$\eta_g = \frac{\text{o/p of generator}}{\eta_m \cdot \text{i/p of motor}} = \frac{V \cdot I_1}{\eta_m \cdot V(I_1 + I_2)}$$

$$\eta_g = \eta_m = \eta$$

$$\eta_g \cdot \eta_m = \frac{I_1}{I_1 + I_2} \Rightarrow \eta = \sqrt{\frac{I_1}{I_1 + I_2}}$$

* As the m/c are identical their efficiency is assumed to be identical but practically the cu losses in both m/c is different. Therefore η are determined separately.

* If the motor & generator of identical rating are ideal then (i/p = o/p) they don't require additional energy from the supply. Practically as they contain loss they draw additional power which is exactly equal to loss in both m/c.



$$VI_2 - (\text{Total cu loss}) = \text{Rotational Loss } (P_R)$$

Rotational Loss of Each m/c is $P_R/2$


$$\eta_g = \frac{O/P}{O/P + \text{Loss}} = \frac{V \cdot I_1}{V \cdot I_1 + P_R + (I_1 + I_3)^2 R_{ag} + I_3^2 R_{shg}}$$

$$\eta_m = \frac{I/P - \text{Loss}}{I/P} = \frac{V(I_1 + I_2) - [P_R/2 + (I_1 + I_2 - I_4)^2 P_{am} + I_4^2 R_{shm}]}{V(I_1 + I_2)}$$

3. FIELDS TEST

* It requires two identical series m/c one acting as motor & other as generator.

* It is not a back to back test like Hopkinson's because the series generator o/p is dissipated in load resistor. The series field wdg of both generator & motor are connected in series in order to make same current to flow in them.



$$V_1 I_1 - V_2 I_2 = P_T \text{ --- Total cu loss --- Rot. loss of both } (P_R)$$

$$I/P - O/P = \text{Losses of Both m/c}$$

$$\text{Rotation loss of Each m/c : } P_R/2$$

$$\eta_m = \frac{I/P - \text{LOSS}}{I/P} = \frac{V_1 I_1 - \left[\frac{P_R}{2} + I_1^2 (R_{am} + R_{sem}) \right]}{V_1 I_1}$$

$$\eta_g = \frac{O/P}{O/P + \text{LOSS}} = \frac{V_2 I_2}{V_2 I_2 + \left[\frac{P_R}{2} + I_1^2 R_{seg} + I_2^2 R_{ag} \right]}$$

4. RETARDATION TEST

* Rate of change of K.E = Rot. Loss

* It is also called as running down test. The rate of change of change of K.E is considered as Rot. loss as the motor run down while reducing its speed it is overcoming the opposition provided by rot. loss.

* Run the motor slightly above its rated speed. Disconnect its only armature from the supply. It continues to run down against rotational loss which has iron, friction and windage loss.

* If both field as well as armature is disconnected the motor run down only against friction & windage loss as there is no flux.

$$K.E = \frac{1}{2} J \omega^2$$

J = Moment of Inertia, kg-m^2

ω = Angular Velocity $2\pi N/60$


$$\text{Rot. loss} = \frac{d}{dt} (K.E) = \frac{d}{dt} \left(\frac{1}{2} J \omega^2 \right) = J \omega \frac{d\omega}{dt}$$

$$= J \frac{2\pi N}{60} \frac{d}{dt} \left(\frac{2\pi N}{60} \right) = \left(\frac{2\pi}{60} \right)^2 J N \frac{dN}{dt} \text{ Watts.}$$

Ques:- Let A Shunt motor has rated speed 1000 rpm. Retardation test is conducted & the speed is decreased from 1030 to 970 rpm in 15 sec. If the moment of inertia of armature is 70 kg-m². what will be its rotational loss.

Sol:- Rotational loss = $70 \times \left(\frac{2\pi \times 1000}{60} \right)^2 \times 1000 \times \frac{d}{dt} (60)$
 = 3.0705 kWatt.

□ ARMATURE REACTION IN DC MOTOR.



Depending on direction of rotation pole tips are named leading pole tips of generator becomes trailing tip of motor (Vice versa)

The flux density under the leading pole tips of a motor will increase.

MNA is shifting in opp direction of motor rotation.

In order to improve commutation brushes also need

to be shifted in opposite direction to its rotation.

The polarity of an interpole should be equal to polarity of main pole behind motor rotation.

09/07/14

Que:- A 24 slot 2 pole DC generator has double layer wdg with 18 turn coils the flux density per pole is 1 Tesla the effective length of m/c is 20cm & $r = 10\text{cm}$ (Armature). The poles are design to cover 80% of armature peripheral. If the armature angular velocity 183.2 rad/sec. Determine the induced emf in wdg.

$$\begin{array}{l} \text{SLOTS} = 24, \\ \text{Pole} = 2. \\ \text{Turn} = 18 \\ B = 1\text{T.} \\ l = 20\text{cm.} \\ r = 10\text{cm.} \end{array} \left. \begin{array}{l} \\ \\ \\ \\ \\ \end{array} \right\} \text{Double layer.} \begin{array}{l} \frac{P \cdot A}{P \cdot P} = 0.8 \\ \omega = 183.2 \text{ r/s} \end{array}$$


No. of coils in armature = 24.

Total no. of ~~turns~~ turns = $24 \times 18 = 432$

Total no. of conductor = $24 \times 18 \times 2 = 864$

$$N = \frac{60}{2\pi} \times 183.2 = 1750 \text{ rpm.}$$

$$E_g = \frac{\phi Z N P}{60 A}, \quad \phi = B \cdot A =$$



$$\text{Area} = 2\pi r l = 2 \times 3.14 \times 0.1 \times 0.2 = 0.1256$$

$$\frac{\text{Area}}{\text{Pole}} = \frac{\text{Area}}{2} = \frac{0.1256}{2} = 0.628 \dots$$


$$\text{Effective Area per pole} = 0.0628 \times 0.8 = 0.050 \text{ m}^2$$

$$\Phi = B \cdot A = 1 \times 0.050 = 0.050 \text{ Wb.}$$

$$E_g = \frac{0.050 \times 864 \times 1750 \times 2}{60 \times 2} = 1260 \text{ V}$$

$$E_g = 1260 \text{ V}$$

Parallel path



$$\text{No. of coils per 1/2 path} = 12$$

$$\text{So, emf induced per coil} = \frac{1260}{12} = 105 \text{ V}$$

$$\text{Emf per turn} = \frac{105}{18} = 5.83 \text{ V.}$$

$$\text{Emf per conductor} = \frac{5.83}{2} = 2.9 \text{ V}$$

Que:- A 4 pole lap wound dc generator consist of 220 turns each of resistance 0.004 what is its armature resistance.

$$\text{sol}^n \text{:- } P = 4, A = 4, Z = 220 \times 2 = 440, R = 0.004$$


$$R_a = \frac{Z \cdot R}{A^2}$$



$$= \frac{0.002 \times 440}{4 \times 4} = 0.055$$

Ques: A compound generator is supplied a load of 250 lamps rated 100 watt at 250 V. The armature resistance $R_a = 0.06 \Omega$, $R_{se} = 0.04 \Omega$, $R_{sh} = 50 \Omega$.


Determine the induced emf when the m/c is connected as long shunt & short shunt. Brush contact drop $1V/Brush$.



$$E_g = V + I_a (R_a + R_{se}) + BCD$$

$$= 250 + 105 (0.06 + 0.04) + 2 \times 1$$

$$E_g = 262.5 \text{ V}$$



$$E_g = V + I_a R_a + I_L R_{se} + BCD$$

$$= 250 + 105.08 (0.06) + 100(0.04) + 2 \times 1$$

$$E_g = 262.3 \text{ V}$$

Que :- In a long shunt compound generator the terminal voltage is 230 when generator delivers 150 Amp 150 A

Shunt field resistance = 92Ω , $R_{se} = 0.015 \Omega$, $R_a = 0.032 \Omega$

& diverter 0.03Ω is connected. Determine power

generated, power delivered.

Solⁿ :- $E_g I_a = P_g$, $P_d = V \cdot I_L$


$\Rightarrow E_g I_a - V I_L = \text{Total cu losses}$

$E_g \neq R_d // R_{se} = \frac{0.03 \times 0.015}{0.03 + 0.015}$

$= 0.01 \Omega$

$E_g = V + I_a R_a + I_a (R_d // R_{se})$
 $= 230 + 152.5 \times 0.032 + 152.5 \times 0.01$

$E_g = 236.4 \text{ V}$



Total cu loss \Rightarrow

1. $(2.5)^2 \times 92 = 575 = R_{sh}$

2. $(152.5)^2 (0.032) = 744.2 = R_a$

3. $(152.5)^2 (0.01) = 232.56 = R_d // R_{se}$

$P_{delivered} = V \cdot I_L = 230 \times 150 = 34500$

$\Rightarrow \text{Total cu loss} = 1551.7$

$\Rightarrow E_g I_a - V I_L = 1551.7$
 $236.4 \times 152.5 - 230 \times 150 = 1551.7$

generator has 480 armature conductors
 wdg, armature current 200 A, find
 δk^2 demagnetising ampere per turns &
 magnetising ampere per turns if i) brushes are on
 ii) Brushes shifted by 6° electrical from GNA.
 Brushes shifted by 6° Mechanical from GNA.

$$I_a \cdot \frac{Z}{2P} = \frac{2000}{180} \times \left(\frac{I_a \cdot Z}{A \cdot 2P} \right)$$

$$\frac{I_a}{A} \cdot \frac{Z}{2P} = \frac{2000}{2} \times \frac{480}{2.8} = 3000 \text{ AT/P}$$

(i) $\theta = 90^\circ$


(ii)

Que:- A 8 pole lap wound dc m/c has 720 conductors
 & the pole covers 70% of the pole pitch find no.
 of conductors in compensating wdg on each pole &

$$\text{Sol}^n \Rightarrow Z_c = \frac{Z}{A \cdot P} \left(\frac{\text{Pole arc}}{\text{Pole pitch}} \right) = \frac{720}{8 \times 8} (0.7) \approx 8$$

Que:- A dc m/c has total armature ampere turns
 per pole 15000. Ratio of pole arc to pole pitch 0.68
 calculate compensating wdg turns per pole & interpole
 wdg turns per pole if the air gap length is 1 cm &
 additional flux density required by the interpole 0.25 Tesla
 Rated armature current 850 A

Solⁿ:-



$$AT/p = 15000$$

$$\frac{P.A}{P.P} = 0.68$$

$$\frac{10200 \text{ AT}}{850} = 12$$

Compensated wdg $AT/p = 0.68 \times 15000 = 10200$

Inter pole wdg $AT/p = 0.32 \times 15000 = 4800$

$$\text{Flux} = \frac{\text{mmf}}{\text{Reluctance}} = \frac{\text{Ampere Turns}}{\text{Reluctance}} = \frac{A.T}{l / \mu_0 \mu_r a}$$

$$\Rightarrow \frac{\Phi \cdot l}{\mu_0 \cdot a} = A.T \Rightarrow \left(\frac{\Phi}{a} \right) = B$$

$$\Rightarrow \frac{B \cdot l}{\mu_0} = A.T, \quad \mu = 4\pi \times 10^{-7}$$

Additional A.T
required on
interpole

$$A.T = \frac{0.025 \times 0.01}{4\pi \times 10^{-7}} = 1989 \text{ A.T/p.}$$

$$\text{Total } AT_p = \frac{4800 \text{ AT/p} + 1989 \text{ A.T/p}}{850} = 7.98$$

↓
Inter pole wdg
Per turn.